C Deco

Ŗ

1

• • • • •

NZ.

		Server and the server
REPORT NO.: 99900094/88-01	INSPECTION DATE: December 12-16, 1988	INSPECTION ON-SITE HOURS: 87
CORRESPONDENCE ADDRESS:	Masoneilan North American Operat Dresser Valve and Control Divisi Dresser Industries, Incorporated B5 Bodwell Street Avon, Massachusetts 02322	ions on
ORGANIZATIONAL CONTACT: N TELEPHONE NUMBER:	4r. William T. Allen III, Qualit (508) 586-4600	y Manager
NUCLEAR INDUSTRY ACTIVITY: Masoneilan North American (Masoneilan-Dresser), manu parts.	: The Dresser Valve and Control Operations, Dresser Industries, afactures ASME Section III valve	Division of Incorporated s and replacement
ASSIGNED INSPECTOR: J. J. (RI)	Petrosino, Reactive Inspection S-1)	Section No. 1 Jate
OTHER INSPECTOR(S): Mr.	T. L. Tinkel, Sonalysts, Incorpo	rated
Mr. I	C. J. Carroll, Sonalysts, Incorp	orated
APPROVED BY: E. T. Baker Branch	, Section Chief, RIS-1, Vendor I	nspection Jate
INSPECTION BASES AND SCOP	E:	
A. BASES: Appendix B t and Pressure Vessel C	o 10 CFR Part 50, Section 111 of ode and 10 CFR Part 21.	the ASME Boiler
B. <u>SCOPE</u> : This inspect 1988, 10 CFR Part 21 internal replacement valves, but were not	ion was performed as a follow-up report from Consumers Power Comp parts that were found in Masonei manufactured by authorized MD fa	o to an October 21, Dany regarding valve lan-Dresser (MD) acilities.
PLANT SITE APPLICABILITY:	All sites.	
9001310431 90013 PDR 0A999 EMVD	22 SSI PDC	

249

Concert of

1

j,

١

- 🐺

REI	REPORT NO.: 99900094/88-01			INSPECTION RESULTS:		PAGE 2 of 17
Α.	VIOL	ATION	<u>s</u> :			
	1.	Cont exis Part requ devi have tion 10 C	rary to Section tence of a defec 21 procedure (2 ires individual ations or noncon determined that ally, the proced FR Part 21 term	21.21, "Notification of t t," it was identified the 36-M-174, Revision B, dat employees to notify their formances only after the a "substantial safety he ure states an incorrect "substantial safety haza	failure to co at the MD 10 ted May 2, 19 r supervisors individual e azard" exists definition of rd" (88-01-01	emply or CFR 087), of employees . Addi- the .).
		This	s is a Severity L	evel V violation (Supple	ment VII).	
Β.	NONC	ONFOR	RMANCES :			
	1.	Cont VII, Appe tro and the	trary to Criterio , "Control of Pur endix B to 10 CFR 1" of Revision J QS4, "Order Mana MD Commercial QA	n IV, "Procurement Docum chased Material, Equipme Part 50; Section 4, "Nu of the MD Nuclear QA Man gement and Procurement C Manual (88-01-02):	ent Control;" ni and Servic clear Procure ual, and Sect ontrol," of F	' Criterion ces," of ement Con- tions QS2.2 Revision G of
		a.	MD failed to en included or ref listed below ev 10 CFR Part 50 applicable lice	sure that adequate quali erenced on its PO docume en though the requiremen and ANSI N45.2 were impo nsee PO's listed below,	ty requirements to the control of Appendised on MD by and	nts were ontractors ix B to the
		ь.	MD failed to en listed included supplier, have hardware, and p	sure that its measures t adequate provisions to objective evidence of th perform receipt inspectio	to control the use a MD appr le quality of ons of the had	e POs roved the rdware.
			Licensee/PO	Vendor	MD	PO
			Consumers Power Company 1007-9218-Q	- Carpenter	PV-000	16
			Consumers Power Company 2003-0106-Q	Masoneilan- France	56859 56846 56964	

REPORT NO.: 99900094/88-01		INSPECTION RESULTS:		PAGE 3 of 1
	Licensee/PO	Vendor	MD	<u>P0</u>
	Consumers Powe Company 1007-8545-Q	r Boston Centerless	B45-V23	3119
	Public Service Gas and Elec P2-205090	Boston tric Centerless	18279	
	Commonwealth E 427281	dison Boston Centerless	A10-PV2	22955
C. <u>UN</u>	RESOLVED/OPEN ITEMS:			
1.	QA Program Control			
	of Section III of t (ASME) Boiler and P of safety-related i retaining and are t the scope of Sectio pins).	he American Society of ressure Vessel Code (Se nternal valve replaceme herefore categorized as n III (e.g., valve stem	Mechanical Engi ction III). Thent parts are no exempt from or is, seat rings,	ineers ne majority ot pressure outside cages and
	For those component the NRC has accepte Appendix B. Howeve exempt from or outs to be manufactured the intent of Appen be in compliance wi did not complete th issue will be categ	s and parts within the d Section III as meetin r, nuclear safety-relat ide the scope of Section and controlled under a dix B to 10 CFR Part 50 th this requirement. H eir review of this issue orized as unresolved it	scope of Section of the intent of ed parts and co on III are require QA program that MD does not lowever, NRC ins e. Therefore, em (88-01-03).	on III omponents ired t meets appear to spectors this
2.	Valve Actuator Sizi	ng		
	The NRC inspectors sizes its automatic friction between th review was not comp unresolved item (88	briefly reviewed the me valve actuators with e e valve stem and the st leted, this issue will -01-04).	thodology by when phasis on according to the second	nich MD bunting for ince this as an

RENO	PORT	99900094/88-01 INSPECTION RESULTS: PA			
D.	STA	TUS OF PREVIOUS	INSPECTION FINDINGS:		
	Not	reviewed during	this inspection.		
Ε.	INS	PECTION FINDINGS	AND OTHER COMMENTS:		
	1.	Entrance and E	xit Meetings		
		The NRC inspection dur inspection dur 1988 and summa 1988 exit meet a. review of	tion team informed the MD staff ing the entrance meeting conduct rized its findings and concerns ing. The scope of the inspect the circumstances regarding the	f of the scope of the cted on December 12, s at the December 16, ion included: he October 21, 1988	
		Consumers	, Power Company (CPC) 10 CFR Par	rt 21 report;	
		b. review of	the MD valve distributor netwo	ork;	
		c. review of Control V	the relationship with sub-tier alve Specialties (CVS) and Cor-	r manufacturers such as -Val; and	
		d. obtaining between s versus se and contr	information regarding different pare parts from the original ec condary sources, and MD's manuf rols.	nces that may be found quipment manufacturer facturing methodologies	
	2.	Background			
		The CPC 10 CFF suspect MD val turbine bypass facility. The parts that wer being authoriz stances of the Information No	Part 21 report, dated October ve internal replacement parts to valve installed at CPC's Palis CPC report identifies approxim re manufactured by vendors not in red to manufacture MD valve trin is matter are discussed in more otice (IN) 88-97.	21, 1988, identified that were found in a MD sades nuclear plant mately 65 valve trim recognized by MD as m parts. The circum- detail in NRC	
		On December 16 information th which was subm 10 CFR Part 21 information st were nonconfor	i, 1988, the inspectors became a nat CPC identified to the Region nitted by CPC as supplemental in report on December 22, 1988. tated, in part, that 6 of 97 values rming in that they have undersit	aware of additional n III NRC staff nformation to the The supplemental lve pins examined zed expanded diameters.	

REPORT NO.: 99900094/88-01	INSPECTION RESULTS:	PAGE 5 of 17
	and the second states and the second states and	

Five of these items were supplied by Masoneilan's Houston, Texas facility and the remaining item was supplied from H. H. Barnum, a previously authorized Masoneilan distributor. Additionally, 7 of 51 seat rings examined were nonconforming regarding manufacturing tolerances. The manufacturer of five of these items has not yet been identified. The two remaining, purchased in 1978, were manufactured by CVS. CVS was an authorized MD manufacturer and distributor in 1978.

- 3. 10 CFR Part 21 Implementation By MD
 - a. The inspector reviewed MD Procedure Number 236-M-174. Revision B, "Compliance with Federal Regulation 10 CFR Part 21," dated May 5, 1987. Some noted inconsistencies are as follows: (1) Part 21 defines the term, substantial safety hazard, as "a loss of safety function to the extent that there is a major reduction in the degree of protection provided to public health and safety for any facility or activity licensed...pursuant to.... " The procedure incorrectly defined "substantial safety hazard" as "Possible exposure of personnel to 25 rems or more of radiation, and/or the release of radioactive material in concentrations which over 24 hours would exceed allowable limits." While these two examples are listed in NUREG-0302 under the definition of substantial safety hazard, other more pertinent examples are also listed under the definition, i.e., exceeding a safety limit as defined in the facility technical specifications; (2) The procedure requires individual employees to notify their supervisors of defects or noncompliance only after the individual employee has determined that a substantial safety hazard exists. This does not address the situation where an employee cannot make that determination and the deviation must be referred to the customer for evaluation; and (3) The procedure does not address Section 21.31, "Procurement Documents," of 10 CFR Part 21 (i.e., assuring that POs issued by MD, specify 10 CFR Part 21 if applicable).

The inspector concludes that the MD 10 CFR Part 21 implementing procedure is inadequate to assure that potentially reportable deviations are identified to management or that a potentially reportable problem is identified to the customer or licensee so that they may cause an evaluation to be performed. Violation 88-01-01 was identified in this area.

REPORT NO.: 99900094/88-01	INSPECTION RESULTS:	PAGE 6 of 17
-------------------------------	------------------------	--------------

4. Purchased Material

The inspection team review of procurement packages for safety-related valve internal replacement parts and discussions with MD personnel identified some inconsistencies in the method in which MD implements Discussions with MD quality assurance/quality control its program. (QA/QC) personnel revealed that QC does not perform receipt inspection activities on bar stock material that may be used for the fabrication of safety-related parts and components with the exception of bar stock designated for Section III use. It was also noted that QA/QC personnel are not involved in the transfer of heat code numbers (i.e., material traceability) during the bar stock cutting process or verification of the transfer, with the exception of material identified as Section III valve body or bonnent material. The review of this area was not completed during the inspection and will be reviewed in more detail during a future inspection. As a result unresolved item 88-01-03 was identified.

Another inconsistency was that MD fails to pass on QA requirements of Appendix B to 10 CFR Part 50, ANSI N45.2, or Section III requirements imposed on them when purchasing either material to fabricate valve internal parts or to purchase safety-related valve internal replacement parts. It was noted that MD neither passes on nor requests any specific quality assurance program requirements from its sub-tier vendors or requires that the sub-tier vendor be on the MD approved supplier list. As discussed above, MD does not require its QA/QC personnel to perform receipt inspections or test materials that are received with the exception of material ordered for use in Section 111 valve body and bonnet fabrication.

Several PO packages (listed below) were identified for safety-related parts that were not processed in accordance with Appendix B to 10 CFR Part 50 although Appendix B was imposed by the customer. As a result Nonconformance 88-01-02 was identified during this part of the inspection.

REPORT NO.: 99900094/88-01	INSPECTION RESULTS:		PAGE 7 of 17
Licensee/PO	Vendor	MD PO	Footnote
Consumers Power Co. 1007-9218-Q (July 31, 1987)	Carpenter	PV-0016	
Consumers Power Co. 2003-0106-Q (December 8, 1987)	Masoneilan France	56859 56846 56964	1 1 1
Consumers Power Co. 1007-8545-Q (June 24, 1987)	Boston Centerless	B45-V23119	2
Public Service Gas and Electric P2-205090 (April 8, 1987)	Boston Centerless	18279	
Commonwealth Edison 427281 (March 30, 1987)	Boston Centerless	A10-PV22955	

5. QA Program Review

MD has established and uses two types of QA manuals (QAMs) to control the operations at its Avon facilities. For Section III work activities, MD uses its nuclear QAM (NQAM), while non-Section III activities are covered by the MD commercial QAM (CQAM). Additionally, MD has a "near-nuclear" (NN) program which uses portions of both QAM's.

The nuclear program is currently governed by Revision J of the NQAM, dated June 1, 1987. The NQAM appears to comply with ASME Section III

¹ There was no objective evidence that MD (France) was an approved supplier. Also, the PO document used to obtain the material was not available for review. The MD engineer stated that this document would not be retained.

² The plug, stem, and pin were not ordered by the Consumers Power Co., PO. However, MD supplied the additional parts and certified them to the PO requirements. MD's PO to Boston Centerless was not available because it was a commercial order and therefore not retained.

REPORT NO.: 9	9900094/88-01	INSPECTION RESULTS:	PAGE 8 of 17
	for Code items (i.e. Code). When Appendi requirements of Sect N45.2 and ASME contr related non-Code par The NQAM states that related items is con Addendum 1 to the NQ states that the NN Q items required to me of applying the "N" of the NQAM (less re to control the manuf	, pressure retaining as def x B of 10 CFR Part 50 is in ion III, the NQAM states th ols are implemented for mar ts as agreed upon by MD and non-Section III material f trolled by the CQAM. AM defines the MD NN QA pro A program is used to manufa et Section III requirements stamp. Under the NN QA pro quirements for "N" stamp co acture of pressure retaining	fined by the ASME mposed without the hat Appendix E, ANSI nufacturing safety- d the purchaser. for use in safety- ogram. Addendum 1 acture safety-related s with the exception ogram, the provisions ertification) are used ng parts. Addendum 1
	also states that the accordance with the formance 88-01-02 in a portion of its CQA deficiencies in the	non-pressure retaining par CQAM. However, it should b dicates failures by MD to e M. Unresolved item 88-01-0 overall MD program control.	rts are supplied in be noted that Noncon- effectively implement 03 also discusses
	The commercial quali Revision G of the CQ of the CQAM, Revisio states that the comm Appendix B to 10 CFR MIL-I-45208A for saf and the purchaser. it meets any QA stan	ty assurance program is cur AM, dated July 1, 1988. Th n F, is dated December 2, 1 ercial QA program meets the Part 50, ANSI N45.2, MIL-0 ety-related components as a Revision G of the CQAM does dards or specifications.	rrently governed by he previous revision 1985. Revision F e requirements of Q-9858A, and agreed upon by MD s not state that
	In conclusion, it ap or has not adequatel, over the MD activiti and manufacturing pr nuclear safety-relat as Section III press addresses this issue	pears that MD has either re y imposed Appendix B type C es regarding procurement, n ocesses for components that ed applications other than ure boundary items. Unresc in part.	elaxed, removed, QA program controls receipt inspection, t can be used in items designated olved item 88-01-03
6.	Secondary Source Man	ufacturers	
	The October 21, 1988 several secondary so that was identified was licensed by and 1975 until September	, 10 CFR Part 21 report fro urce manufacturers. One su to the NRC was CVS of Houma contracted to MD from appro 14, 1980 as an authorized	om CPC identified uch manufacturer a, Louisiana. CVS oximately September 1, manufacturer and

REPORT NO.: 99900094/88-01	INSPECTION RESULTS:	PAGE 9 of 17
supplier of MD pr relations with CV its component dra return all of the by the inspectors from CVS after th procuring carbide orders were place be all nonsafety.	roducts. MD stated that it t VS in the 1980 time period an awings be returned. MD also e MD drawings as requested. s that MD has been routinely he 1980 contract termination e tipped valve plugs from CVS ed with CVS by MD in 1988. T -related.	erminated all business d requested that all of stated that CVS did not However, it was noted procuring components date, and is currently . Approximately eight hese orders appear to
The following is MD to the inspect	a summary of some of the inf tion team regarding CVS:	ormation provided by
a. In the mid-1 required de many large of supply. CVS butor and so 1975 until t and was allo basis for Mo	1970's, MD experienced some d livery schedules for customer orders in-house and because m S was apparently contracted a ervice representative for MD termination of the agreement owed to manufacture spare par asoneilan valves.	ifficulty meeting spare parts due to aterial was in short s a licensed distri- from September 1, on September 14, 1980 ts on an emergency
b. The MD Midwe function for petro-chemic CVS was not the nuclear were not au the nuclear copy of its has not rev here).	est Regional Sales Manager st r CVS was to provide replacem cal industry located in the T authorized to manufacture an power industry. Further, MD thorized to buy replacement v power industry. (Note: MD agreement with CVS. Therefo iewed any of the contractual	ated the primary ent valve parts for the exas-Louisiana area. d sell valve parts to sales representatives alve parts from CVS for was not able to find a re, the NRC inspector requirements discussed
c. The MD Sales tacit approvide valve parts not provide sales repre- other source	s Manager also stated that on val to MD sales representativ from secondary sources. Thi parts within the time requir sentatives were then allowed es.	some occasions MD gave es to buy replacement s occurred when MD could red by the customer. MD to obtain parts from
d. As a result plan to aud where parts	of the CPC 10 CFR Part 21 re it MD sales representatives t were procured from secondary	port, MD has initiated a o identify instances source manufacturers

NO.: 9	990009	4/88-01	RESULTS:	PAGE 10 of
		and supplied t that he will n identified in	o nuclear power plants. I otify the NRC of any probi the Part 21 report.	The QA Manager stated lems similar to those
7.	MD V	alve Trim Compo	ment Identification/Contro	<u>91</u>
	а.	Identification discussions wi its valve inte	- The following information the MD personnel regard rnal replacement parts (va	ion was obtained during ding identification of alve trim):
		(1) Each MD v number. which tra original order num commercia are 40, t QA progra order was the requi valve cod	alve assembly is identific This serial number corresp cks the specifications and valve. If the first two r ber are 44, the order was 1 QA program. If the first he order was processed und m. Order numbers starting processed under the nucle rements of Section III or E.	ed by a unique serial bonds to a PO number, d requirements for the processed under the st two numeric digits der the near-nuclear g with an N indicate the ear QA program and met the draft pump and
		(2) MD does n to provid part numb nal valve	ot need a customer name to e a replacement part. The er can be identified by MD serial number and the par	o identify a part number correct replacement o if they know the origi- rt name or description.
	b.	Part Number Co regarding part	ntrol - The following MD p number control were discu	policy and procedures ussed:
		 Policy an engineeri DMR-3-3, 	d Procedure - The MD proce ng documents, entitled "Re Revision E, dated July 27,	edure for revising evisions-Basic Practice,' , 1982 was reviewed.
		The proce documents The term cial rele puterized The basic assembly forces th parts req	dure is applicable to revi such as drawings and asso revision is applied to any ase of an original drawing method to generate the pa policy is that any change that affects form, fit, fu e part to be non-interchar uires assignment of a new	ising engineering ociated parts lists. y change after offi- g, parts list, or com- articular documents. e to any part or unction, or process that ngeable with previous part number. Parts are

REPORT NO.: 99900094/88-	01	INSPECTION RESULTS:	PAGE 11 of 1
	considered functiona in perfor one for th	d to be interchangeable if 1 and physical characterist mance and durability and cap he other without alteration	they possess such ics as to be equivalent pable of being exchanged of the items themselves
(2)	Part Number historica used by MI the system a MD Nucle over 30 ye	ering Systems - An attempt of perspective about the part of since the late 1960's. No m but, the following informa- ear Product Engineer who have ears:	vas made to obtain some t numbering systems o procedure describes ation was obtained from s been with MD for
	(a) MD pa digit mater required numer a MD	art numbers consist of 12 d ts represent the material co rial codes for commercial pa irements) are represented by ric digits. The material co Material Code Index.	igits. The last three ode for the part. The arts (i.e., no special combinations of three odes are explained in
	<pre>(b) In th numbe subje code addin "refe ment: eithe code addin accon</pre>	he late 1960's, MD began us ers 779 and 780 to distingu- ect to special requirements identifies a commercial par- tional special requirements. For to the parts list." Depo- s, the parts might be handle er the nuclear or commercial identifies a commercial par- tional special requirements redance with the near-nuclear	ing material code ish parts that were and controls. A 779 of that is subject to This code means, anding on the require- ed in accordance with I QA programs. A 780 of that is subject to and is handled in r quality program.
	(c) With mater duced Sect	the introduction of ASME Sorial code 781. This code is in accordance with the number ion III for both N stamp and	ection III, MD adopted s used for items pro- clear QA program and d non-N stamp items.
	Note: ident	These "special requirement tified outside of MD.	its" are usually not
(3)	Alpha-Nume material c ments not system rep	eric Codes - In 1983 MD adop code for special material an covered by the MD Material placed the previously used o	oted an alpha-numeric id material require- Code Index. This codes 779, 780, and 781.

REPORT NO.: 99900094/88-01		INSPECTION RESULTS:	PAGE 12 of 1
	The system	n for using three numeric di	gits for commercial
	part mater	rial codes was not changed.	The alpha-numeric
	material c	code system is explained in	E.S. 420, dated
	December 1	16, 1983. This document sta	tes:
	(a) Alpha speci non-d proce appro chemi the m	a-numeric material codes are ial material, special materi destructive examinations, sp edures, mercury free process oval of weld repair, acid sp ical and physical documentat material code index.	assigned to al requirements, ecial welding ing, customer ot testing, and ion not covered by
	(b) Comme 10th mater	position of the part number rial code).	alpha code in the (1st digit of the
	(c) Nucle	ear requirements have a nume	ral in the 10th
	posit	tion followed by an alpha ch	aracter in either
	the 1	lith or 12th position of the	part number (2nd
	and 3	Brd digit of the material co	de).
(4)	Parts List	- The parts list, Revision	D, for a 20,000
	Series, 4-	inch, 900-psi, valve was ex	amined to review an
	example of	the implementation of the	current MD part
	number sys	stem. The parts list identi	fied various part
	numbers, d	drawings numbers (for Sectio	n III parts), part
	descriptic	ons, quantities, and materia	l specifications for
	each of th	he items in the valve assemble	ly. The following
	parts were	identified with an asteris	k indicating material
	shall be m	nanufactured and certified i	n accordance with the
	requiremen	ints of Article NC-2000 (Clas	s 2) for Section 111.
	 Body Body St Plug Bonnet 	tuds and Nuts and nipple	
	The extern	hal valve parts were identif	ied with a nuclear
	alpha-nume	eric material code. The rem	aining parts were
	identified	d with a three digit numeric	material code
	indicating	g the parts are to be commer	cial grade.

REPORT NU.: 9	9900094/88-01	INSPECTION RESULTS:	PAGE 13 of 17
8.	Differences betwe Secondary Source One issue reviewe or quality differ factured by the O grade parts manuf concern is curren that may find the Differences can e procured and how However, sufficie uate the impact o safety. The foll a. For a second ducing a com application, ary source n detailed dra mercial grad CVS and beca ing commerci copies of th needs to kno the original are applicab on the origi	en Original Equipment Manufac Parts d during the inspection was wences exist between commercial EM for nuclear power applicat actured by secondary sources. tly limited to secondary sources tly limited to secondary sources in way into nuclear power pla xist depending on how the or the current replacement parts nt information is not current f these differences on valve owing comments apply: ary source to have the capabi mercial grade part for a MD three basic items are requine eeds to have sufficient techn wing, and design tolerances) e part. Because of MD's priouse al parts some secondary source e original MD drawings. Next w what supplemental requirem nuclear valve order and whet le to the particular part to nal valve order is controlled ailable to the power plant of	<pre>cturer (OEM) and whether technical and/ al grade parts manu- tions and commercial . This particular rce commercial parts ants. iginal valve was s are being ordered. tly available to eval- operability or plant ility of correctly pro- valve in a nuclear red. First, the second- nical information (e.g., to produce the com- or relationship with -tier vendors for machin- ce manufacturers may have t, the secondary source ents were applicable to ther these requirements be made. Information d by ND and may not be r the secondary source.</pre>
	Third, the s program that b. During the i examples of differences in a nuclear used in a co identified d commercial a nuclear appl and sometime applications	econdary source would have to is equal to or better than i supplementary requirements th between a commercial grade pa application and the same cor mmercial application. A few uring the inspection include: pplications were typically us ications the seat rings were s hard facing. Plugs for sti were used as is, for nuclear	o implement a quality the one used by the OEM. s looked for specific hat could result in art that could be used mmercial grade part specific examples : Seat rings for sed as is but for subjected to NDE rictly commercial r applications the

REPORT NO.: 99900094/88-01		94/88-01	INSPECTION RESULTS:	PAGE 14 of 1	
	c.	Some QA/QC diff invoked in the be the inherent The requirement be available to	erences also arise from r original equipment specif result of the quality pr s leading to quality diff secondary source manufac	equirements ications or may ogram being used. erances may not turing, such as:	
		Requirement of compliant	ts to provide written cer nce with specification re	tification quirements.	
		 Requirement (or approvided field mater 	ts to use material from q ed) suppliers with docume ial test reports from sub	ualified nted certi- -tier vendors.	
		 Requirement control and stocking. 	ts for receipt inspection d identification during m	and material anufacture and	
		 Procedures involve re tions for order. 	for order entry and proc view of original equipmen requirements applicable to	essing that t specifica- o the current	
	d.	One last consid facturers may b drawings prepar or other second drawings can le tolerances. De by a single ins	eration is that some second e using reverse-engineered ed by measuring parts man ary source spare parts). ad to differences, especi- sign tolerances cannot us pection of a finished par	ndary source manu- d drawings (i.e., ufactured by the OEM Reverse engineered ally for dimensional ually be identified t.	
9.	Rev	Review of MD Contracts			
	The induces sale in e acqu avai the	inspectors condu ustrial sales rep cutive correspond es for use in nuc effect was instit uired Masoneilan ilable of contrac refore, a review	cted a review of MD's con resentatives, their marke ence concerning sales of lear power plants. The c uted in 1986 shortly afte from McGraw-Edison. There ts which were in effect p could not be performed.	tract with their ting releases, and nuclear products or ontract currently r Dresser Industries e were no copies rior to 1986;	

NO 9990	0094/88-01	INSPECTION RESULTS:	PAGE 15 0
T m Q t f	he current contr ethod to be used A manager stated o pass all order acility to deter e provided two M epresentatives:	act does not procedurally sp when processing a nuclear p that the sales representations from nuclear power plants mine if the part was nuclear D memorandums that were tran	ecify an explicit lant order. The MD ves were instructed on to MD's Avon or commercial grade. smitted to MD's sales
۵	. Nemo ASM-24- part: "All for Nuclear directed to	86-DF, dated May 8, 1986. This inquiries and orders, REGARD related parts and/or complete Avon Contract Administration	his memo states, in LESS of product type, e equipment are to be
b	. Memo ADM-25- part: "All or that requ complete equ Administrati	880, dated August 15, 1988. inquiries and orders, <u>REGARD</u> ires delivery, for nuclear re ipment are to be directed to on and clearly marked "NUCLE	This memo states, in LESS of product type elated parts and/or AVON Contract AR."
T od T poso r ao	he MD memorandum rders should be efinition of nuc he Midwest sales ossible for an e f determining if afety-related sy rder from his st eplacement parts uthentic MD part n the MD sales r	is specifically state that nu passed to the Avon facility. lear related parts is open to manager when questioned, st xperienced MD sales represent a part order from a nuclear stem himself. He might then ock which could contain non- . Therefore, whether a nucl- or a secondary source part epresentative's handling of	clear related part However, the exact o interpretation. ated that it was tative to feel capable plant was for a decide to fill the authorized substitute ear plant receives an is dependent in part that order.
A r 1 p 1 0	nother contractu epresentatives w f they could car arts. A review tself preclude t r secondary sour	al aspect reviewed was wheth ere required to carry exclus ry competitors products or s of the contract identifies t he MD representative from de ce suppliers.	er MD sales ively MD products or econdary source hat it does not in aling with competitors
1 9 1	n conclusion, it enuine MD parts he responsibilit nd their conform	is possible for an NRC lice from an authorized MD sales y of assuring the adequacy o mance to the procurement docu	nsee to receive non- representative. f purchased material ments therefore, rests

NO.: 99	90009	4/88-01	INSPECTION RESULTS:	PAGE 16 of 1
10.	Additional MD Information			
	The following item were noted during discussion between MD and NRC personnel.			
	a. The MD Avon, MA facility is one of several located around the country and around the world. Other facilities within the United States include the MD Instrument Division in Canton, MA, a MD warehouse/valve refurbishment facility and distribution center in Houston, TX, and another MD manufacturing facility in Montebello, CA. The Montebello facility is engaged in Air Force and NASA work.			
	b.	MD has been p industry for variety of sa Masoneilan's sliding stem	roviding equipment to the c about 25 years. MD valves fety-related and nonsafety 21,000 Series, 40,000 Serie valves are used in nuclear	commercial nuclear power are used in a wide nuclear applications. es, and 41,000 Series power plants.
	с.	MD maintains expiring Augu fication of v customer. MD without ASME	N and NPT stamps (Nos. 1836 st 1989. These stamps are alves or replacement parts also supplies valves that N stamp certification.	5 and 1837), currently used when ASME certi- is requested by a MD meet ASME Section III
	d.	Prior to the valves (usual plants. Thes nonsafety-rel	introduction of Section 111 ly with some type of upgrad e valves were used in both ated applications.	I, MD supplied commercial de) to nuclear power safety-related and

REPORT NO.: 99900094/88-01	INSPECTION RESULTS:	PAGE 17 of 17
F. <u>PERSONNEL CONTACTED</u> : <u>NAME</u>	TITLE	
*P. H. Sanford *W. T. Allen, 111 R. Brundy C. A. Canestrari A. Dectellis D. Ellis K. Juncewicz *J. A. Kerr E. Kramer E. Meagher J. Powell J. Ravezi R. Rohm	Manager, Massachusetts Operations Quality Manager Service Representative Senior Buyer Final Tester Service Representative Regional Manager QA Engineer Nuclear Product Engineer Receipt Inspector QC Supervisor Material Receiver/Handler Valve Assembly Supervisor	

*present during exit meeting

.