

Portland General Electric Company Trojan Nuclear Plant 71760 Columbia River Hwy Rainier, Oregon 97048 (503) 556-3713

(503) 556-3713 U.S. Nuclear Regulatory Commission Document Control Desk Washington DC 20555 January 30, 1990 CPY-035-90

Gentlemen:

## Special Report

Trojan Technical Specification (TTS) 3.7.9, "Penetration Fire Barriers" Limiting Condition for Operation (LCO) requires submittal of a Special Report if a 3-hour fire barrier is nonfunctional for greater than 7 days.

On December 31, 1989, Fire Door No. 73, located in the Control Building 93 foot elevation (entry to the Control Room Vestibule), became inoperable due to a failure in the door latch mechanism. The latch mechanism is in the door's emergency opening hardware assembly (commonly called a "Panic" or "Crash" bar) and parts were not readily available for this installation. Parts are on order and will be installed when received.

The compensatory measures of TTS 3.7.9 (checking local smoke detectors and establishing a hourly fire patrol) were established as required.

Sincerely,

U. P. Yundt General Manager Trojan Fuglear Plant

c: Mr. John B. Martin Regional Administrator, Region V U.S. Nuclear Regulatory Commission

> Mr. David Stewart-Smith State of Oregon Department of Energy

Mr. R. C. Barr USNRC Resident Inspector Trojan Nuclear Plant

1527

9002120134 900130 PDR ADOCK 05000344