

ORIGINAL - ACRST-1781

OFFICIAL TRANSCRIPT OF PROCEEDINGS

11

Agency: Nuclear Regulatory Commission
Advisory Committee on Reactor Safeguards

Title: Subcommittee on the Systematic
Assessment of Experience, Proposed
Power Level Increase for Indian
Point Nuclear Generating Station Unit 2

Docket No.

LOCATION: Bethesda, Maryland

DATE: Tuesday, February 6, 1990 **PAGES:** 1 - 147

ACRS Office Copy - Retain
for the Life of the Committee

ANN RILEY & ASSOCIATES, LTD.

1612 K St. N.W., Suite 300
Washington, D.C. 20006
(202) 293-3950

9002130014 900206
PDR ACRS
T-1781 PDC

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25

PUBLIC NOTICE BY THE
UNITED STATES NUCLEAR REGULATORY COMMISSION'S
ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

DATE: February 6, 1990

The contents of this transcript of the
proceedings of the United States Nuclear Regulatory
Commission's Advisory Committee on Reactor Safeguards,
(date) February 6, 1990,

as reported herein, are a record of the discussions recorded at
the meeting held on the above date.

This transcript has not been reviewed, corrected
or edited, and it may contain inaccuracies.

1 UNITED STATES OF AMERICA

2 NUCLEAR REGULATORY COMMISSION

3 ***

4 ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

5 ***

6 SUBCOMMITTEE ON THE SYSTEMATIC

7 ASSESSMENT OF EXPERIENCE

8 ***

9 PROPOSED POWER LEVEL INCREASE FOR INDIAN POINT

10 NUCLEAR GENERATING STATION UNIT 2

11
12 Nuclear Regulatory Commission

13 7920 Norfolk Avenue

14 Phillips Building, Room P-110

15 Bethesda, Maryland

16
17 TUESDAY, FEBRUARY 6, 1990

18
19 The Committee met, pursuant to notice, at 8:30 a.m.,

20 HAL W. LEWIS, presiding.

21

22

23

24

25

1 ACRS MEMBERS PRESENT:

2 HAL W. LEWIS, ACRS SUBCOMMITTEE CHAIRMAN

3 CARLYLE MICHELSON, ACRS MEMBER

4 CHARLES J. WYLIE, ACRS MEMBER

5 DAVID A. WARD, ACRS MEMBER

6 IVAN CATTON, ACRS MEMBER

7 JAMES C. CARROLL, ACRS MEMBER

8 HERMAN ALDERMAN, COGNIZANT ACRS STAFF MEMBER

9 PARTICIPANTS:

10 DONALD S. BRINKMAN, NRC/NRR

11 CURTIS COWGILL, NRC/RI

12 PETER KELLEY, NRC/RI

13 ROBERT CAPRA, NRC/NRR

14 TIMOTHY COLLINS, NRC/NRR

15 ROBERT A. HERMANN, NRC/NRR

16 MARTIN R. HUM, NRC/NRR

17 BARRY J. ELLIOT, NRC/NRR

18 JAY L. LEE, NRC/NRR

19 JIN-SIEN GUO, NRC/NRR

20 ARNOLD J.H. LEE, NRC/NRR

21 DON R. LASHER, NRC/NRR

22 STEVE BRAM, CON EDISON

23 CHARLES JACKSON, CON EDISON

24 LOU LIBERATORI, CON EDISON

25 ROY KIM, INDIAN POINT

1 BARB SAMARDZICH, INDIAN POINT
2 GARY AMENT, INDIAN POINT
3 DON DURKOSH, INDIAN POINT
4 BOB MCFETRIDGE, INDIAN POINT
5 PETE SKULTE, INDIAN POINT
6 LARRY SMITH, INDIAN POINT
7 SEENA SRINIVAS, INDIAN POINT
8 PAUL MALIK, PMX INC.
9 BRENT BRANDENBERG, CON EDISON
10 TOM THOMAS, INDIAN POINT
11 JAY AKERS, INDIAN POINT
12 BILL BENNET, CON EDISON
13 ALBERT VAIA, INDIAN POINT
14 WALTER MOOMAN, INDIAN POINT
15 JUDE G. DELPERCIO, INDIAN POINT
16 GETACHEW TESFAYE, INDIAN POINT
17 ROBERT R. LAUBHAM, INDIAN POINT
18
19
20
21
22
23
24
25

P R O C E E D I N G S

[8:30 a.m.]

1
2
3 MR. LEWIS: Let's begin our meeting.

4 This is a meeting of the ACRS Subcommittee on the
5 Systematic Assessment of Experience, and it's about a proposed
6 power-level increase for Indian Point Nuclear Generating Unit
7 Number 2. It's approximately a 10-percent increase that is
8 being requested.

9 The meeting will come to order.

10 I am Hal Lewis, Chairman of the Subcommittee.

11 The other ACRS members around are Carl Michelson,
12 Charlie Wylie, Dave Ward, Jay Carroll, and Ivan Catton, and the
13 cognizant ACRS staff member for today's meeting is Herman
14 Alderman, to my right.

15 The rules for the meeting have been announced as part
16 of the notice in the Federal Register, January 23, 1990.

17 The meeting is being conducted in accordance with the
18 provisions of the Federal Advisory Committee Act and the
19 Government in the Sunshine Act, and we have received no written
20 or additional oral statements from members of the public.

21 It would be helpful of everyone who spoke would (a)
22 speak into a microphone, speak clearly and intelligibly so that
23 the recorder can make a good record.

24 The general pattern we will follow be that during the
25 first part of the morning, we will hear from the NRC staff

1 about their views on the request for a power increase, then
2 from the licensee, and then, heaven willing, we will take a
3 short break, and then decide what we want to do.

4 Do any other members of the Subcommittee want to say
5 something before we get cracking?

6 [No response.]

7 MR. LEWIS: Okay. In that case, my understanding is
8 that our first speaker is Curt Cowgill from NRC Region 1, and I
9 would request the people try to keep roughly on schedule,
10 because I will get tough if we get very far off. Okay?

11 MR. CAPRA: Yes, Sir.

12 I'm Bob Capra. In my position in NRR, I am the
13 project director responsible for Indian Point.

14 Prior to Mr. Cowgill's presentation, Don Brinkman,
15 the Indian Point 1 project manager, will make a short
16 presentation.

17 MR. LEWIS: That's fine. Sure. Go for it.

18 [Slide]

19 MR. BRINKMAN: Good morning.

20 My name is Donald Brinkman. I am the NRC project
21 manager for Indian Point 2.

22 We are here today to provide you with a briefing on
23 the licensee's proposal to increase the thermal power at Indian
24 Point 2.

25 My project director, Bob Capra, is here with me.

1 Staff member, Curtis Cowgill, from Region 1, Tim Collins, and
2 Bob Hermann will also be making part of the staff presentation.

3 We are accompanied by additional staff members who
4 participated in the preparation of the staff safety evaluation.
5 They will answer questions that you may have on the safety
6 evaluation.

7 The licensee has representatives here, too.

8 [Slide]

9 MR. BRINKMAN: Our plans for today's presentation are
10 that Mr. Cowgill will provide a discussion of operational
11 experience at Indian Point 2. That will be followed by the
12 licensee's presentation. Then I will come back and give an
13 overview of the staff's evaluation. Assisting me will be Tim
14 Collins, providing a discussion on the ECCS portion of the
15 evaluation. Robert Hermann will give his discussion on the
16 steam generators. And I will come back and give a final
17 conclusion.

18 So, now, I'd like to introduce Mr. Cowgill, who will
19 provide you with the Region 1 perspective.

20 [Slide]

21 MR. COWGILL: Good morning.

22 My name is Curt Cowgill. I'm currently a project
23 section chief in Region 1, with responsibilities for both the
24 Indian Point Unit 2 reactor facility and the Calvert Cliffs
25 facility in Maryland.

1 I have just recently been assigned this project
2 within the last month. I have the resident inspector from
3 Indian Point Unit 2, Peter Kelley, here with me this morning to
4 help me answer your questions.

5 My background -- I was an officer in the Navy nuclear
6 power program until 1979. At that time, I came with the NRC.
7 I have been senior resident inspector at two facilities. I was
8 part of the NRC's staff that oversaw the cleanup of TMI-2 for
9 some period of time. My most recent responsibilities, prior to
10 Indian Point and Calvert Cliffs, I was the section chief
11 responsible for the GPU nuclear plants and Duquesne Light.

12 [Slide]

13 MR. COWGILL: I would like to discuss with you a
14 number of items this morning, associated with recent operating
15 experience at Indian Point 2. I would like to talk about the
16 1988 steam generator dryout event, discussion of trips,
17 operator professionalism, support, operating procedures, and
18 the operator qualification and requalification program.

19 My understanding is that after the steam generator
20 dryout event in 1988, the ACRS staff and Committee was briefed.
21 So, I will keep my remarks concise in that area.

22 The most significant event that we have evaluated in
23 the previous 2 years at Indian Point was the dryout event of
24 the steam generator in January 1988, following a refueling
25 outage, during the reactor startup.

1 During the plant heatup, a high rate of steam leakage
2 through the steam generator and its associated MSIV, with the
3 lack of normal makeup capability in the steam generator,
4 resulted in a total loss of inventory, or dryout, in the steam
5 generator.

6 The process was of a protracted nature. It took
7 about 36 hours and existed for an additional 24 hours before
8 being recognized by the utility management.

9 When plant management became aware of the event,
10 appropriate analyses were conducted to assure that recovery
11 actions were taken to refill the steam generator such that it
12 would not result in equipment damage.

13 An NRC augmented inspected team was sent to the site
14 to evaluate the event and the circumstances leading to the
15 event.

16 The team noted that a tagged out auxiliary feedwater
17 pump, coupled with a leaking MSIV, inappropriate use of
18 emergency procedure analysis, inadequate communication and
19 control of operations by management, as well as a number of
20 procedural adherence problems, led to the event.

21 MR. MICHELSON: Question.

22 MR. COWGILL: Yes, Sir?

23 MR. MICHELSON: There must be a number of instruments
24 that tell you how much water there is in the steam generator.
25 What happened to those?

1 MR. COWGILL: Pete, why don't you come up to a
2 microphone?

3 MR. KELLEY: I am Peter Kelley. I am the resident
4 inspector at Indian Point Unit 2.

5 They were operating at the time, and the operators
6 did recognize the fact that the inventory in the steam
7 generator had gone away, but due to other actions going on and
8 trying to start up the plant, this got kind of buried under
9 some other jobs that the operators were doing at the time.

10 MR. MICHELSON: Well, there must be some kind of a
11 redline on the meter or something that says don't operate below
12 this level, and when you get down there, you'd better do
13 something. Isn't there any -- there must be alarms, even, that
14 says you're running on low water.

15 MR. KELLEY: They do have alarms, and they do have
16 indications.

17 MR. MICHELSON: They ignore all these?

18 MR. KELLEY: They don't have a specific line on the
19 chart recorders themselves that says don't go below --

20 MR. MICHELSON: "Redline" is sometimes, you know,
21 just a commonly-used term.

22 MR. KELLEY: They do have alarms to indicate the
23 level --

24 MR. MICHELSON: And they ignored the alarms,
25 apparently. If the instruments were working, they would have

1 gotten alarms.

2 MR. KELLEY: Alarms were in. At the time of the
3 startup, when they are heating up, they have a lot of alarms in
4 at that time, and it's believed that this was one more alarm
5 that did come in, and due to other actions going on, somehow it
6 was --

7 MR. MICHELSON: That's not a very comforting
8 explanation, to be without water for so long. You know, water
9 is one thing that's pretty important in a boiler, as you well
10 know.

11 MR. LEWIS: The direct answer is the alarm went off,
12 and they ignored it.

13 MR. MICHELSON: They ignored it, apparently.

14 MR. KELLEY: Well, the alarm was in. As Curtis had
15 said, it took about 36 hours for this evolution -- for the
16 complete dryout to occur.

17 MR. LEWIS: Well, is what I said wrong? The alarm
18 went off, but they ignored it. It may not be a fair way to
19 state it.

20 MR. KELLEY: I think that's a correct statement. I
21 think that's correct.

22 MR. LEWIS: Could I ask another question, since
23 you're interrupted?

24 I missed the words "inappropriate use of emergency
25 procedure analysis". I am not quite clear what that means.

1 MR. COWGILL: Peter, can you help me a little bit
2 there?

3 MR. KELLEY: I'm sorry. I didn't hear the question.

4 MR. COWGILL: The inappropriate EOP analysis that
5 they performed during this event.

6 MR. KELLEY: In the basis for the EOPs, they have --
7 highly-developed EOPs is in this EOP guidance, and in the basis
8 or in this guidance, it says just how many -- I believe it was
9 how many cycles, thermal cycles, can a steam generator go
10 through, and I believe it had in there how to recover from this
11 event.

12 MR. LEWIS: What he said was something like
13 inappropriate application or use or emergency procedure
14 analysis. That means that the emergency procedure was wrong or
15 that they used it wrong?

16 MR. KELLEY: They used the basis, the EOP basis, not
17 the EOP itself. None of the action statements in the EOP was
18 used. It was the actual basis that was used to develop the EOP
19 was used.

20 So, the operators felt that using the -- if they can
21 use the EOP basis, they would be okay.

22 MR. LEWIS: I don't understand that, because the
23 point of an emergency operator procedure is that you are
24 supposed to follow the procedure that somebody else has worked
25 out in advance. Did they elect not to follow it because they

1 didn't trust it?

2 MR. KELLEY: Well, there is really no EOP for this
3 steam generator dryout. People were searching for a way to get
4 out of this problem, and they found an EOP which had some -- a
5 basis which had some guidance as to how to get out of it, and
6 that's what they used.

7 MR. LEWIS: So, there was no EOP, and they
8 improvised, and you are saying they improvised on an incorrect
9 basis.

10 MR. KELLEY: That's correct.

11 MR. LEWIS: That's slightly different from what you
12 said. Okay.

13 MR. CARROLL: Now, what were they trying to get out
14 of? They were trying to figure out how to get water back into
15 it?

16 MR. COWGILL: They were trying to recover from the
17 dryout event. Initially, the shift began to perform a task to
18 recover, independently. When management was made aware of the
19 event, management told them to stop, and the utility developed
20 a method for recovering level.

21 MR. CARROLL: How are you using the word
22 "management"?

23 MR. COWGILL: I'm using the word -- management above
24 the shift senior plant management at the facility. That is the
25 "management" I am referring to.

1 MR. CARROLL: So the shift supervisor or whatever,
2 he's called as management the way you're describing it.

3 MR. COWGILL: Not in the context that I used the
4 term, sir.

5 MR. CAPRA: If I can clarify one point to put it in
6 perspective. When this particular event happened, the plant
7 was coming out of an outage. There was a lot of maintenance
8 going on, a lot of systems being returned to service, a lot of
9 systems being tested.

10 This wasn't a situation where the plant was shut
11 down, all systems were returned to normal, and it was a normal
12 plant startup. One of the problems was inadequate control of
13 systems to bring the plant to startup and lack of contingency
14 plans in the event things failed.

15 There were a lot of lessons learned out of this
16 particular event.

17 MR. MICHELSON: Are the procedures for the plant
18 symptom-based procedures now or event-based?

19 MR. KELLEY: For the EOPs?

20 MR. MICHELSON: Yes. The guidelines were written for
21 symptom-based procedures. I just wondered if they have
22 implemented those guidelines into procedures. The question is
23 do you think they're symptom-based procedures?

24 MR. KELLEY: The EOPs are symptom-based.

25 MR. MICHELSON: Isn't one of the symptoms low water

1 in the steam generator? Don't you go to the appropriate action
2 statements for that situation?

3 MR. KELLEY: There is no EOP specifically for, say,
4 just a dryout or a low level in the steam generator.

5 MR. MICHELSON: You mean there's nothing --

6 MR. KELLEY: They do have alarm or abnormal
7 procedures for low levels in the steam generator.

8 MR. MICHELSON: Clearly, low water in the steam
9 generator is an abnormal condition and that's a symptom of
10 something. Don't you go to the procedures where it starts
11 getting into low water in the generator and what to do?

12 MR. KELLEY: Not in the EOP.

13 MR. CARROLL: Strange.

14 MR. MICHELSON: Very strange. I thought that's what
15 they were supposed to do.

16 MR. CARROLL: Is the distinction the fact that EOPs --
17 -- I don't agree with this -- but EOPs in general deal with
18 events occurring during power operation as opposed to during
19 shutdown or startup.

20 MR. KELLEY: That's true. During a startup
21 evolution. During a startup; say, if they would have had a
22 reactor trip and then, of course, that is an EOP itself and
23 they were going through that EOP.

24 MR. CARROLL: Low level would have produced a reactor
25 trip if they had been at a higher power.

1 MR. KELLEY: If they were actually critical.

2 MR. COWGILL: This event occurred, if I'm not
3 mistaken, about 325 degrees Fahrenheit. Is that correct?

4 MR. MICHELSON: That's right.

5 MR. KELLEY: About that, yes.

6 MR. COWGILL: They were heating up on pump heat.

7 MR. MICHELSON: It's the old question of what do you
8 do when you have an accident during shutdown; what procedures
9 do you follow.

10 MR. CARROLL: Where was the steam going out of this
11 generator?

12 MR. KELLEY: They had a main steam isolation valve --

13 MR. CARROLL: Valve open.

14 MR. KELLEY: -- seam leakage and it was leaking out
15 there. Plus, also at the time, the auxiliary water feedwater
16 pump that fed that steam generator was tagged out for
17 additional maintenance. So due to the steam leak and not being
18 able to add water to the generator, that's how it dried out
19 within that 36 hour time span.

20 MR. CARROLL: So steam was going through the MSIV and
21 through drains?

22 MR. KELLEY: I would imagine going through steam
23 traps.

24 MR. CARROLL: I'm not totally clear on the 36 hours
25 that's been referred to. That's how long it took to get to the

1 dryout?

2 MR. KELLEY: That's correct.

3 MR. CARROLL: Then how long was the steam generator
4 dry?

5 MR. COWGILL: Another 24 hours, sir.

6 MR. KELLEY: About another day after that.

7 MR. CARROLL: So now I get down to a dry generator.
8 What happened during the 24 hours?

9 MR. KELLEY: During the 24 hours, Con Ed was trying
10 to determine just how to refill the steam generator again,
11 because they were --

12 MR. CARROLL: Worried about --

13 MR. KELLEY: They were heated up at the time and
14 there were concerns about using -- this was in January. There
15 were concerns about using the colder water in the condensate
16 storage tank and just how fast it should be added.

17 What eventually happened was a sluicing operation
18 from one of the other generators which had warm water in it,
19 from one of those generators to the dried out steam generator.
20 That's how they recovered from the event.

21 So it took that long to determine just what course of
22 action to take.

23 MR. MICHELSON: What was the primary temperature,
24 primary side?

25 MR. KELLEY: I would really have to look it up. It

1 was probably about 350 or so.

2 MR. COWGILL: Yes. 325 to 350 is what we had, sir.

3 MR. CARROLL: Now, at what point did people realize
4 they had a problem in this 36-plus-24 hour period?

5 MR. KELLEY: The operators at the time, they knew
6 they had a problem just a little bit before the end of that 36
7 hour time span, before it completely got dried out.

8 MR. CARROLL: How about "management?"

9 MR. KELLEY: As was stated, it was about a day after,
10 24 hours after the dryout.

11 MR. LEWIS: They knew they had a problem, but they
12 simply went to bed and didn't tell anybody?

13 MR. KELLEY: That's where the communications aspects
14 come in. There were some problems with whether the operators
15 had informed the senior watch supervisor or not that the dryout
16 had occurred. Again, as was said, there were a lot of other
17 activities going on at the time.

18 MR. LEWIS: There are always a lot of other
19 activities going on at the time.

20 MR. KELLEY: This time, probably, they were going a
21 little bit too fast.

22 MR. LEWIS: Please go on.

23 MR. CARROLL: I just have one more question.

24 Whatever you call the most senior person on shift knew about
25 this on a continuing basis. Now, who was he supposed to tell

1 and when did he tell him, or is my first statement right?

2 MR. KELLEY: I would really like to look that up just
3 to get who knew what when and who told who when.

4 MR. COWGILL: Peter, I've got a copy of the executive
5 summary and the conclusions from the inspection report in my
6 notes. So we could look that up for you. Would it be okay to
7 answer that question a little later?

8 MR. CARROLL: Sure. That would be fine.

9 MR. COWGILL: Would you like me to continue now, sir?

10 MR. LEWIS: Yes.

11 MR. COWGILL: From the NRC inspection staff's
12 perspective, we believe that in the recent operating history,
13 the dryout event was really about the low point of the
14 operation at the facility.

15 There was a confirmatory action letter issued. There
16 was a management meeting in Region I to discuss the corrective
17 actions taken by the utility prior to the Regional
18 Administrator agreeing to restart of the facility.

19 Indian Point, in its early operating days in the
20 middle 1980s, had a fairly high reactor trip rate. Over the
21 last two SALP cycles, basically the 1986 to 1990 timeframe,
22 we've seen a dramatic reduction in the operating trip rate.

23 There has been one reactor trip during this cycle.
24 We see the utility continuing this trend and we believe this is
25 a positive attribute.

1 As a result of the dryout event, there were a number
2 of things done by the utility to improve their operation.
3 Certainly, one of them was improving operator professionalism.
4 After the dryout event, the operators themselves wrote an
5 Operator Code of Conduct. It was developed by the operators.
6 It was formally presented to Region I staff.

7 Indian Point operators on a 12-hour rotation.
8 Recently, in the spring of 1989, after exams, they went to a
9 six-shift rotation which improved a number of things, which
10 included overtime usage.

11 We believe the operator control is good. We believe
12 their interaction with other departments is generally good. We
13 believe that shift turnovers, which were a problem associated
14 with this event, have improved since that time. We believe
15 they are formal and effective at this point.

16 We see a continuing trend of improved performance
17 with respect to procedural compliance. There has also been --

18 MR. WARD: You said they went from -- they had been
19 on 12-hour shifts?

20 MR. COWGILL: They are still on 12-hour shifts. They
21 went from a five-shift rotation to a six-shift rotation, sir.

22 The operating shift itself consists of one shift
23 supervisor, which is titled Senior Watch Supervisor, at the
24 facility; one watch engineer, which is their shift technical
25 advisor; a senior reactor operator who is assigned to the

1 control room; two reactor operators; and, seven nuclear plant
2 operators or auxiliary operators, non-licensed staff. That is
3 their shift complement currently.

4 MR. CARROLL: During the steam generator dryout
5 event, was that shift organization augmented because they were
6 in a startup situation?

7 MR. COWGILL: I'm going to have ask Peter again,
8 because I wasn't there.

9 MR. KELLEY: I believe at the time, in 1988, they
10 were still on 12-hour shifts. I don't know how many rotations
11 they had.

12 MR. WARD: They are on 12-hour shifts today.

13 MR. COWGILL: Peter, they say was the shift
14 augmented, additional operators for the startup?

15 MR. KELLEY: Maybe the licensee would know about that
16 at this time, but I don't.

17 MR. MICHELSON: Is the 12-hour shift a common thing
18 in the industry or just an occasional? Most of the utilities,
19 I thought, had less than 12-hour shifts.

20 MR. COWGILL: I can only speak for my most recent
21 experience. I've now had experience with, I guess, about half-
22 dozen utilities directly. This is the first utility I have had
23 experience with that has a permanent 12-hour shift rotation.

24 MR. MICHELSON: I thought that was kind of unusual.

25 MR. COWGILL: I have not had any real time to

1 evaluate how it works. It apparently works for them, but most
2 other utilities don't use it as a general practice.

3 MR. MICHELSON: Does the staff know to what extent
4 12-hour shifts are used in this country?

5 MR. CAPRA: I don't have an exact count. I did see a
6 listing of shift rotations and the longevity of shifts recently
7 in a printout for all operating plants. I believe there were
8 somewhere in the neighborhood of a dozen to 15 or so that had
9 12-hour shifts.

10 MR. MICHELSON: Maybe ten to 12 percent or so.

11 MR. CAPRA: Sure.

12 MR. WARD: Curt, we've heard perhaps more than we
13 should have about this event of two years ago, but a number of
14 actions have taken place since then and I guess the important
15 thing today is what indications do you have that these actions
16 have corrected whatever problems that existed two years ago?

17 MR. COWGILL: I tried to articulate those, but maybe
18 I can do it again. One, we believe the shift turnover process,
19 which was a contributor to the event, has improved. We believe
20 that the formality of the operators is better.

21 The operators themselves have written a Code of
22 Conduct. They adhere to it. We believe that the interactions
23 with other departments is good. We have seen an improved
24 communication within the shift and with plant management.

25 As a result of this event and in the SALP period for

1 that period of time, and SALP was extended to include the steam
2 generator dryout event, the utility was given a two-declining
3 with some fairly strong words from the regional management and
4 a recommendation for an improvement program.

5 The most recent SALP, which ended last year, Category
6 II with no trend assigned, was assigned. Although
7 inconsistencies were still noted, a number of improvements had
8 been noted. In our most recent mid-cycle SALP, we identified
9 to the utility that we saw continued improvement in the
10 operations area. We are comfortable, at least at this point,
11 that the indications we saw on the 1988 dryout event have not
12 recurred and the utility has learned from that experience and
13 has improved its operation in this area.

14 MR. WARD: So these are changes not only in the right
15 direction, but you are convinced these changes have taken hold.

16 MR. COWGILL: Yes, we are. We are convinced that
17 these changes have taken hold and are improving the overall
18 operations.

19 MR. KELLEY: Plus, also, coming out of the last
20 outage, we did do a restart inspection which concurred our
21 findings that Con Ed is kind of on an increasing or improving
22 trend with regard to operations.

23 MR. WARD: A restart inspection; what is that
24 exactly?

25 MR. KELLEY: Basically, watching the startup.

1 MR. COWGILL: Observing activities associated with
2 preparing the plant for restart and observing some aspects of
3 the restart activity. Periodically, we do that.

4 MR. WARD: Was this after a similar shutdown? I
5 mean, is your point that the situation during this inspection
6 was similar to what existed in January of 1988 at the plant?

7 MR. KELLEY: Yes.

8 MR. COWGILL: The plant was coming out of its next
9 refueling outage in the summer of 1989 and we conducted
10 inspection at that time, sir.

11 MR. WARD: Thank you.

12 MR. CARROLL: What were the residents doing during
13 the January 1988 36-plus-24 hour situation?

14 MR. KELLEY: We're not there all the time. We're not
15 there 24 hours a day. We do make it a habit to go in to watch
16 evolutions, such as startups and shutdowns and after-reactor
17 trips, but myself and the senior resident inspector at the time
18 were not in there at the time watching the startup. The
19 startup from cold shutdown to actual criticality can take
20 several days to do.

21 MR. CARROLL: You weren't there at any time during
22 this 24-plus-36 hour period?

23 MR. KELLEY: We were there during the part when they
24 were trying to figure out what to do.

25 MR. CARROLL: That was after they realized they had a

1 dry generator.

2 MR. KELLEY: That's correct.

3 MR. MICHELSON: When a resident enters a control room
4 routinely, does he sometimes look at the alarm board just to
5 see what kind of alarms they're running with?

6 MR. KELLEY: On a routine basis, yes.

7 MR. MICHELSON: And he didn't, apparently, in this
8 case, notice they were running with low water in the steam
9 generator?

10 MR. KELLEY: As I said, at this time --

11 MR. MICHELSON: That's right. You said he wasn't
12 there any time during the 36 hours when he would have noticed
13 that; is that right?

14 MR. KELLEY: One would hope so, that he would see
15 that.

16 MR. MICHELSON: But, normally, they do, at least
17 occasionally, look to see what kind of alarms the plant is
18 running with.

19 MR. KELLEY: That's right. As a matter of fact,
20 that's part of our inspection program. Every day or every time
21 you go into the control room, we observe to see what alarms are
22 up and also to look at the chart recorders and see how they are
23 tracking and trending.

24 MR. CARROLL: So you have a checklist of sorts.

25 MR. KELLEY: It's part of our inspection program.

1 MR. COWGILL: We're going to have to move on, but I
2 would like to correct a checklist. We generally don't use,
3 most of the residents anyhow, I know, don't use a specific
4 checklist. We have an inspection plan and part of that plan is
5 to observe control room activities. That includes observation
6 of alarms.

7 Now, when I was up at the facility a week ago, we did
8 enter the control room and there were maybe a half-dozen alarms
9 lit in the entire control room. Probably 500 alarms, maybe
10 more, in the control room itself.

11 During a startup -- just to put things in perspective
12 -- you might have half of those alarms lit because systems are
13 not operating in the condition that they would normally be in
14 during power operation.

15 So conditions are somewhat different, sir.

16 MR. CARROLL: I have been in a control room.

17 MR. LEWIS: Could I just clarify one point? During
18 the 36 hours, were the residents in the control room, though,
19 during the 36-hour period? I'm fuzzy on what the answer was to
20 that.

21 MR. KELLEY: The answer is no.

22 MR. LEWIS: The answer was yes?

23 MR. KELLEY: No.

24 MR. LEWIS: No.

25 MR. KELLEY: No. The residents were not there.

1 MR. LEWIS: So when you say you are not there 24
2 hours a day, I understand that. That's a long distance from
3 not being there at all during 36 hours.

4 MR. COWGILL: There are possibly times over a 36-hour
5 period we wouldn't be there, sir, particularly over certain
6 weekends.

7 MR. LEWIS: I'm just interested in that 36 hours, and
8 nobody was in there during that period.

9 MR. KELLEY: That's correct.

10 MR. CAPRA: Just to clarify something, sir. We may
11 need to go back here and look at the inspection report anyway,
12 but that 36 hours was the total time for dryout. That wasn't
13 the time period that the steam generator was dry before anybody
14 knew it. It took a significant amount of time even to get to
15 the low water level mark, and then the steam generator to dry
16 out.

17 The 24 hours prior to refill, both licensee
18 management and NRC management were aware some short period of
19 time into that 24 hours of the problem. The rest of it was
20 working out the details of the recovery operation.

21 MR. LEWIS: But we've been told that they knew they
22 were in trouble before the 36 hours began. Even so, we were
23 just told that.

24 MR. COWGILL: I didn't try to imply that, sir. I
25 said that -- at least what I was trying to say was that the

1 dryout event occurred over a protracted period of time.

2 MR. LEWIS: I understand.

3 MR. COWGILL: About 36 hours.

4 MR. LEWIS: But I thought you said that they knew
5 they were in trouble before the 36 hours began. Did I
6 misunderstand that?

7 MR. KELLEY: I would have to check. I'd have to
8 really look at the inspection report to answer that.

9 MR. LEWIS: Fine. Let's move on.

10 MR. CARROLL: During the 36 hours, the level was
11 monotonically decreasing in the generator.

12 MR. KELLEY: Right.

13 MR. CARROLL: You could see it for most of the
14 period, until you went below the wide range and then it dried
15 out. That should have told somebody something bad was
16 happening.

17 MR. KELLEY: Correct.

18 MR. MICHELSON: Along with the alarm that you should
19 have gotten.

20 MR. CATTON: Don't they monitor feed?

21 MR. CARROLL: You don't have very good indication of
22 this.

23 MR. MICHELSON: This is very small feed.

24 MR. CAPRA: Sir, the steam generator was bottled up
25 at the time. They were not feeding the steam generator

1 initially. They knew they didn't have the capability to feed
2 the steam generator. I don't recall, again, without looking at
3 the specifics of the inspection report, but I believe at some
4 point in time, they believed that they would have the auxiliary
5 feedwater pump back in service -- it was tagged out for
6 maintenance -- to feed the steam generator.

7 MR. LEWIS: I'm going to rule out of order any more
8 discussion of that event.

9 MR. COWGILL: I have got five more minutes. I think
10 I need to move on.

11 MR. CARROLL: Is it going to be fair to ask the
12 licensee questions about it, though?

13 MR. LEWIS: You bet you.

14 MR. COWGILL: I would note that we have observed
15 increased, improved operations support. As a result of this
16 event, again, an Operations Planning Group was formed. We
17 believe that the Operations Planning Group and the improved
18 support has aided in the decreased trip rate.

19 There is a Trip Response Group and we've noted during
20 our last SALP cycle that the shift operations folks are relying
21 more on this operations support group.

22 We believe that, based on our emergency operations
23 procedures inspection conducted recently, that the procedures
24 are technically accurate, that the procedures are structured so
25 that with the equipment at the plant that actions can be

1 implemented, and that the procedures can be effectively
2 implemented as written.

3 MR. MICHELSON: Now, in their new way of doing
4 business, how do they respond to alarms when they come in and
5 they're logged and so forth so that you don't ignore an alarm
6 that might be very important?

7 MR. KELLEY: What they have and which they had then,
8 also, are what I'll call alarm response procedures, ARPs. Each
9 alarm has specific procedures when it comes in as to what to do
10 because of the alarm. Now, when alarms come in, we have
11 witnessed that the ARP book does get pulled out and the
12 procedure is followed as to what to do.

13 MR. MICHELSON: Apparently, that didn't happen
14 before.

15 MR. KELLEY: That's correct.

16 MR. COWGILL: We also believe that the operator
17 qualification and requalification programs are effective. As I
18 said before, as a result of the examinations in April of 1989,
19 the utility went to a six-shift rotation.

20 Our inspections have concluded that the operations
21 requalification operator program was satisfactory.

22 MR. MICHELSON: When they go to six-shift operation
23 and still have 12-hour shifts, what kind of a schedule is that?

24 MR. COWGILL: I'm not familiar enough with their
25 schedule --

1 MR. MICHELSON: Why six? Why not shorten the shift
2 time to give the people a little more energy on the shift?

3 MR. CARROLL: A lot of operators like the 12-hour
4 shift.

5 MR. MICHELSON: I know that, but they don't mind
6 sleeping even. Why go to six shifts?

7 MR. CARROLL: Six shifts gives you a shift that is
8 always in training and shifts to cover days off and that short
9 of thing.

10 MR. MICHELSON: And they give you more than that with
11 six of them in 12-hour shifts.

12 MR. CARROLL: Slightly more than that, yes.

13 MR. MICHELSON: I would think it would be better to
14 keep the people a little less on the job and a little more
15 refreshed when they're working.

16 MR. COWGILL: I think that's a question you'd have to
17 direct to the utility and their experience in operating their
18 facility.

19 MR. BRAM: If I might just comment on that, maybe I
20 could answer your question. The studies that we've done with
21 independent consultants have suggested that it's more restful
22 to the operators --

23 MR. LEWIS: Please identify yourself for the
24 Reporter.

25 MR. BRAM: I'm sorry. My name is Steve Bram, Vice

1 President of Nuclear Power, Con Edison. We've had outside
2 consultants come in and do a study of our shift schedule. The
3 conclusion was not only do the operators prefer the 12-hour
4 schedule, but it's actually more restful for them because they
5 have fewer turnovers, which is really what becomes tiring, not
6 the actual length of the shift.

7 MR. MICHELSON: If that were the case, I'm surprised
8 more utilities don't use 12-hour shifts, it's really more
9 restful.

10 MR. CARROLL: I think it's the trend, Carl. I think
11 an awful lot of them are doing that.

12 MR. MICHELSON: Well, 12 percent, roughly.

13 MR. CARROLL: The other factor and I do not know how
14 important it is at Indian Point but I know in my experience,
15 commute time enters into it. If you have long commutes, it's a
16 lot better to work less days.

17 [Slide.]

18 MR. COWGILL: If I could continue for a moment. We
19 conducted a maintenance team inspection in May of 1989 and
20 there were a number of weaknesses identified by that
21 maintenance team inspection. Poorly defined program -- the
22 team identified that there was not a conduct of maintenance
23 procedure to formally define the program. There was also not a
24 formal preventive maintenance program.

25 We indicated poor management support. That was

1 principally based on the fact that the utility themselves had
2 done a self-assessment, identified most of their problems,
3 however, had not provided funds in their budget to correct a
4 number of the items that they found in their self-assessment.

5 There were some material conditions problems,
6 excessive number of work orders on certain pieces of equipment,
7 some equipment had a history of being repeatedly out of service
8 and there were some attention to detail kinds of problems with
9 housekeeping such as leaving material at maintenance sites
10 after completion of maintenance. However, the team did
11 identify that there was excellent implementation of the actual
12 maintenance tasks by the maintenance staff themselves
13 principally because of their knowledge, skills, and dedication
14 to their work.

15 The utility has taken this aboard, has produced a
16 corrective action plan. They did present that plan to NRC
17 Region I in December, 1989. The region was pleased by the
18 program. We will wait to see about the long-term effectiveness
19 but it included program and procedure upgrades. There's a
20 procedure upgrade program including a number of dedicated
21 procedure writers. The residents tell me that some procedures
22 coming out of this program that they have reviewed appear to be
23 good procedures. They've added staffing including some
24 planners, system engineers, failure analysis engineers, added
25 mechanics and I&C technicians.

1 They have some improved facilities to date with plans
2 for more facilities in the near future.

3 MR. MICHELSON: Would any of these procedures they
4 are now preparing make any difference for the situation that
5 occurred in 1988?

6 MR. COWGILL: I'm not sure.

7 MR. MICHELSON: No, we're going to talk about it yet
8 for a while. I just wondered, now you're giving us their
9 corrective program.

10 MR. COWGILL: That's correct.

11 MR. MICHELSON: I'm asking, with this new corrective
12 program, would it have been any different from the viewpoint of
13 procedures available?

14 MR. CARROLL: You're talking maintenance procedures;
15 aren't you?

16 MR. MICHELSON: Only maintenance? Oh, I thought I
17 was talking operating.

18 MR. COWGILL: I'm talking only maintenance
19 procedures.

20 MR. MICHELSON: Oh, okay. It won't make any
21 difference. Thank you.

22 MR. LEWIS: There was an earlier comment that you're
23 comfortable with the way that things are shaping up, the
24 operating code and that sort of thing. That goes beyond
25 maintenance procedures and if that had been in place at the

1 time, would that have been an improvement?

2 MR. COWGILL: I'm sorry. I don't understand your
3 question.

4 MR. LEWIS: Well, when you were asked what are all
5 the changes that make you more comfortable, you cited the
6 operator code, the fact that they appear to be taking it
7 seriously. They're operating more professionally. It's hard
8 to predict the past because it's over but would it have made a
9 difference at the time?

10 MR. COWGILL: What? If they had had the code and
11 some of the more formal things?

12 MR. LEWIS: Yes.

13 MR. COWGILL: It's really hard to tell. My gut
14 reaction would be yes that it would but you know, on any
15 rational basis, I really can't make that statement.

16 MR. MICHELSON: But there are no procedural -- no new
17 procedures for taking care of these kinds of situations over
18 and above what existed at the time; is that correct?

19 MR. COWGILL: I'm not sure, sir.

20 Back to maintenance --

21 MR. WARD: Are we going to get an answer to that? It
22 seems like a pretty key point.

23 MR. KELLEY: Following the dry out of course and
24 following the AIT that was sent up to the plant, several months
25 afterwards, Con Ed has upgraded their operational procedures

1 that they had in place at the time. These procedures were
2 changed. A big review was gone into to improve these, to make
3 them more user friendly, to get the bugs out of these
4 procedures.

5 MR. MICHELSON: But did those procedures cover the
6 situation they saw? I thought I got an earlier indication that
7 maybe the procedures really don't cover this situation anyway.
8 Now did they do anything different now that they do have
9 procedures that would cover this situation or is it still the
10 same? I'm not talking about normal accident procedures and
11 what improvements they might have made there. I'm talking
12 about this particular situation. Have they changed anything?

13 MR. LEWIS: For example, is there a rule that says
14 once an hour, somebody should look at the alarms?

15 MR. KELLEY: They do their normal log taking
16 activities which I think is every four hours.

17 MR. MICHELSON: You mean that even at the time of the
18 event they were taking a log every four hours and they just
19 logged in, no water in the generator?

20 MR. KELLEY: I'd have to take a look to see what they
21 logged in.

22 MR. LEWIS: We're going to ask the licensee some of
23 these questions.

24 MR. CAPRA: At some point in time that is correct.
25 They did indicate the low level and circled it in red and did

1 not take definitive action to correct that at the time. Again,
2 without going back and looking at all the corrective actions, I
3 know that the licensee did modify administrative controls and
4 administrative procedures related to situations as occurred in
5 1988 coming out of refueling outages. As I recall, they made
6 contingency plans as part of their normal process of coming out
7 when they have a particular system out for maintenance. They
8 did not have contingency plans in place before in the event
9 they needed that system.

10 To what level of detail they went into, I'm not sure
11 but there were significant changes in that area. There were
12 also changes as I recall to the monitoring of the control
13 boards in the control room with respect to operators walking
14 down the boards and looking at all the indications, not only
15 the log readings and that was done -- I forget the time. The
16 licensee may be able to address that but that was like on an
17 hourly basis and it was also done with the shift engineer or
18 shift technical advisor as well at the time of shift turnover.

19 MR. LEWIS: The reason we're asking these questions
20 -- I just want to be clear. We're here to review the request
21 for a 10 percent power increase. We're not here to review the
22 existence of a license but one of the important inputs to us is
23 that the NRC staff seems comfortable with the situation --
24 reasonably comfortable as nearly as I can tell. We need to
25 know why and we're trying to find out why and I must say, I'm

1 having trouble but we'll learn more as the day goes on.
2 Please, I'm making a -- you got it? It's your conclusion.

3 MR. CARROLL: I wanted to ask something about
4 maintenance, if I may.

5 MR. LEWIS: I tried.

6 MR. CARROLL: As you probably know, ACRS has some
7 views about the proposed maintenance rule. If a rule were in
8 effect, would that have helped you in any way to assess or to
9 help turnaround the bad things Con Ed was doing here?

10 MR. COWGILL: I'm really not in a position to say
11 that. I really -- I really can't assess that for you, sir. I
12 think that would be a hard statement.

13 MR. CARROLL: What did turn it around? Was it the
14 NRC or was it INPO?

15 MR. COWGILL: We conducted a maintenance team
16 inspection, identified a number of problems that had been
17 previously identified by the utility which were not considered
18 -- and they had not at the time of our inspection taken
19 effective action to correct those problems. They had
20 implemented a corrective action program to date. We are
21 satisfied that that corrective action program if appropriately
22 implemented should improve their maintenance. It's important
23 to note in all this though that we identified that the
24 maintenance staff itself was doing a good job. They had
25 skilled, knowledgeable people and were conducting the

1 maintenance properly although there were some weaknesses in
2 their system.

3 MR. CARROLL: Had INPO identified many of these same
4 things?

5 MR. COWGILL: I can't answer that question. I don't
6 know.

7 MR. CARROLL: We'll ask the licensee. Okay.

8 [Slide.]

9 MR. COWGILL: In conclusion, we at Region I believe
10 that Indian Point II operating experience and performance from
11 1988 to 1990 is adequate to support safe power operation at the
12 higher power level requested by the licensee management.

13 That concludes my presentation unless there are other
14 questions.

15 MR. CARROLL: I have one more question.

16 MR. COWGILL: Please ask.

17 MR. CARROLL: I guess lately I've become concerned at
18 the number of things that suggest that the utilities, their
19 architect engineers and the NRC staff has done a lousy job in
20 letting glitches get through in the design of these plants. A
21 lot of things are being turned up through SSFIs and where the
22 utility does the same kind of thing where systems are just
23 poorly designed. Somebody forgot something. Somebody put a
24 hydrogen storage facility on the roof of a control building so
25 that a leak in it would put hydrogen in the control room.

1 Somebody didn't provide a big enough suction pipe
2 into the auxillary feedwater pumps, all kinds of electrical
3 problems I'm seeing.

4 To what extent has SSFIs and utility programs doing
5 the same kind of thing taken place at Indian Point? Do you
6 feel good about Indian Point in terms of no design glitches
7 anyplace?

8 MR. COWGILL: I don't think that anybody could ever
9 say that there are no design glitches existing at any power
10 plant. I can't speak specifically for Indian Point today
11 because I haven't been with that facility very long but my
12 experience with other utilities that I've dealt with is the
13 fact that the utilities are embarking on a program to
14 critically look at their systems and improve their design bases
15 is a comfort to me that whatever design errors were made 15 or
16 20 years ago, the utilities are taking aggressive action to fix
17 those problems.

18 I'd be more concerned if the utilities weren't taking
19 the actions and finding the problems.

20 MR. CAPRA: I think the utilities are also looking
21 harder these days in part of their design basis reconstitution
22 efforts. Things that hadn't taken place in the past, just
23 based on my limited scope of responsibilities with respect to -
24 - I don't want to compare plants, but I've got 7 facilities in
25 my project directorate. I would certainly say there are no

1 more significant design deficiencies being found at Indian
2 Point 2 than I see being found at other facilities within my
3 directorate which includes some recently licensed facilities as
4 well.

5 MR. CARROLL: My question is; has Indian Point, in
6 your judgment, aggressively looked for these kind of things?
7 Have they got a real program? Have you, the staff,
8 aggressively looked for these things?

9 MR. CAPRA: The utility does have a program. As a
10 matter of fact, it did do its own independent safety systems
11 functional inspection on the auxillary feedwater system at one
12 period of time a couple of years ago.

13 MR. KELLEY: The plant did have an NRC staff SSFI in
14 1988, and as Bob Capra has said, the plant has done their own
15 safety system functional assessments on auxillary feedwater,
16 and I believe it was also on service water. They take actions
17 on those findings.

18 MR. MICHELSON: What did the staff look at in their
19 SSFI? What system did they look at?

20 MR. KELLEY: In the SSFI, it was service water and
21 component cooling water.

22 MR. MICHELSON: This was 1988?

23 MR. KELLEY: Yes.

24 MR. COWGILL: Unless there are any other questions,
25 that concludes my remarks this morning, gentlemen; thank you

1 very much.

2 MR. LEWIS: Thank you. Okay, who is next. Con Ed.
3 Welcome. I imagine that you've gotten some idea of what some
4 of the questions are going to be.

5 [Slide.]

6 MR. BRAM: Thank you. My name is Steve Bram. I am
7 Vice President of Nuclear Power with Consolidated Edison
8 Company of New York. I want to thank the Systematic Assessment
9 of Experience Subcommittee for inviting us here today to make a
10 presentation relating to Con Edison's stretch power
11 application.

12 After a few brief introductory remarks, I will ask
13 Mr. Charles Jackson, Manager, Nuclear Safety and Licensing to
14 provide an overview of the stretch power program. Mr. Lou
15 Liberatori, Manager of Safety Assessment, will then describe
16 the results of our evaluations. I will also make myself
17 available to answer some of your questions on the steam
18 generator dryout event and the maintenance inspection, if you
19 would like.

20 [Slide.]

21 MR. BRAM: I also have with me today a number of
22 specialists from Con Edison's engineering organization, from
23 Westinghouse and other consulting organizations which have
24 contributed to our stretch analysis.

25 [Slide.]

1 MR. BRAM: My remarks today will provide you with an
2 historical perspective on the siting and licensing of the
3 Indian Point units and of the value of Unit No. 2 to Con
4 Edison's customers and the area it serves.

5 Indian Point Unit No. 2, operating at a power level
6 of 2758 megawatt-thermal, is located in West Chester County,
7 New York, approximately 24 miles of the N.Y. City limits. The
8 site also includes Indian Point Unit No. 1 which has been
9 retired, and Indian Point Unit No. 3 which is operating at a
10 licensed power level of 3025 megawatts-thermal.

11 Con Edison has had a long history of nuclear power
12 generation at the Indian Point site. In fact, the first
13 construction permit, CPPR-1 was issued for Unit No. 1 on May 4,
14 1956. Indian Point operated at a licensed power level of 615
15 megawatts-thermal until late 1974 and was retired because of
16 economics and regulatory uncertainties as a result of the
17 initial rulemaking on ECCS.

18 Many of the people currently working at Indian Point
19 therefore have a long history of involvement with nuclear
20 power. Con Edison received construction permit CPPR-21 for
21 Indian Point Unit No. 2 on October 14, 1966. We applied for an
22 operating license on October 15, 1968, and obtained a facility
23 operating license No. DPR-26 to load fuel in the core and
24 conduct subcritical testing on October 19, 1971.

25 On September 28th, 1973, we received Amendment No. 4

1 to the facility operating license to operate Unit No. 2 at a
2 hundred percent steady state power. Indian Point Unit No. 2
3 was originally designed for an NSSS maximum calculated power
4 level of 3216 megawatts-thermal and was guaranteed by the
5 vendor for a core power level of 3071.4 megawatts-thermal.

6 That corresponds to the 3083.4 megawatts-thermal NSSS
7 power, which is the subject of today's presentation. Indian
8 Point Unit No. 2 was the first Westinghouse four loop plant of
9 its design to be licensed for operation. The current power
10 level of 2758 megawatts-thermal was based on extrapolations
11 from previously licensed plants and to permit the accumulation
12 of operating experience before operation at the vendor-
13 guaranteed power level of 3071.4.

14 Even though other units that are of similar design as
15 our's have been operating at higher power levels than what we
16 have applied for, unrelated developments, both within our
17 company and the industry at large, such as the backfitting
18 programs imposed on all licenses as a result of the TMI-2
19 incident, and the Indian Point 2 special proceeding, forced us
20 to put our ongoing stretch power program on hold on a number of
21 occasions until this time.

22 The current phase of our stretch power program began
23 in 1985 and culminated in our September 30, 1988 submittal.

24 [Slide.]

25 MR. BRAM: The average cost of generating a kilowatt

1 hour of electricity with nuclear plants such as ours is
2 significantly less than fossil plants. It is estimated that
3 the additional energy that will be generated as a result of the
4 increased stretch power rating will save our customers more
5 than \$15 million per year.

6 Of course, the actual value will depend on the
7 specific mix of oil and gas and the cost of those fuels that
8 would otherwise be burned to produce the equivalent energy.

9 I might note, very importantly, that all of the
10 savings are automatically passed back directly through to our
11 customers.

12 The additional capacity which results from the
13 stretch power rating will also enable the company to defer
14 installation or purchase of new capacity. On an annual basis,
15 the avoided costs of the equivalent capacity is estimated to be
16 at least \$6 million.

17 Although Unit 2 generation and purchases of energy
18 from other nuclear, as well as hydroelectric and coal plants,
19 contributes to reducing the amount of fuel oil and gas that the
20 company burns for energy generation, Con Edison, nevertheless,
21 remains very dependent on foreign oil sources.

22 In 1989, the company burned 29 million barrels of oil
23 and gas equivalent to another 15 million barrels of oil. The
24 additional energy resulting from stretch power output of Unit 2
25 would save the equivalent of more than one million barrels of

1 oil annually.

2 Finally, the additional energy from Indian Point 2,
3 if it displaced oil fire generation, would result in a
4 reduction of about one thousand tons each of sulfa dioxides and
5 nitrous oxides each year.

6 That concludes my prepared remarks. I can turn the
7 podium over to Mr. Jackson now to go into more detail on the
8 stretch analysis that we undertook of, if you'd like me to
9 entertain some questions relating to the dryout and maintenance
10 and inspection, I'd be happy to do that.

11 MR. LEWIS: My inclination would be to go through the
12 cycle of the licensee's presentations, asking only vital
13 questions as we go along, and then we'll come back for a free-
14 for-all. Is that agreeable?

15 MR. WARD: I think that would be appropriate.

16 MR. LEWIS: All right. Let's roll.

17 [Slide.]

18 MR. JACKSON: Good morning. My name is Charles
19 Jackson. I'm the Manager, Nuclear Safety and Licensing up at
20 Indian Point Station. I'd like to present to you this morning,
21 briefly, an overview of the Indian Point stretch power program.

22 [Slide.]

23 MR. JACKSON: I will briefly describe some features
24 of Indian Point principally, to set the stage for Mr.
25 Liberatori's presentation on detailed evaluation results.

1 I will address the original concern on operating
2 experience with a comparison of Indian Point with more recently
3 licensed plants, a little bit of the additional background on
4 licensing history, and some of the details of our schedule and
5 implementation plan.

6 [Slide.]

7 MR. JACKSON: Indian Point, as Steve mentioned, was
8 the first four-loop Westinghouse pressurized water reactor,
9 Model 44 steam generators. Our core is a 15-by-15 fuel. We
10 are in the first cycle of conversion over to what we term OFA,
11 or the Optimized Fuel Assembly.

12 We are currently cycle 10. We are consistent with
13 other reactors with what we refer to as an extended burnup fuel
14 design. With the stretch application, we'll achieve a 6.33
15 kilowatt-per-foot, which is within the range of other
16 previously licensed plants.

17 Two main features of the plant are; the Westinghouse
18 main turbine, the low pressure rotors have been changed out and
19 a modernization program, we have eliminated the disks and the
20 problems associated with them.

21 We have also replaced the original generator with a
22 General Electric generator, which is --

23 MR. CARROLL: Running backwards, of course.

24 MR. JACKSON: Excuse me?

25 MR. CARROLL: Running backwards.

1 MR. JACKSON: Yes. We had to change the fan
2 orientation. GE and Westinghouse units are a little different,
3 but we were able to make it fit. As you see, it has plenty of
4 margin for the stretch condition.

5 [Slide.]

6 MR. JACKSON: I'm not going to read all these
7 numbers, but the purpose of this slide is to compare typical
8 numbers for the current cycle operation with the range and
9 expected number to the stretch application.

10 I'd like to highlight both the Reactor T average,
11 pressure, steam generator tube plugging, and RCS flow. We have
12 performed the analyses, as Mr. Liberatori will explain a little
13 further, for a range of parameters.

14 This will permit us operational flexibility, margin.
15 We were going after a 90 percent flow. This would enable us to
16 take increased steam generator tube plugging or conversely
17 without the plugging to take additional degradation in service.

18 We felt it was prudent to do the evaluation for the
19 range of parameters as a contingency in margin. This will keep
20 us from having to come back in later for additional
21 application.

22 [Slide.]

23 MR. JACKSON: The two slides that follow this one we
24 will skip over because we are running a little bit behind.
25 Basically, as Steve mentioned, Indian Point 2 application, the

1 current application, the 3071, is still much lower than most
2 newer licensed plants, most of the similar Westinghouse four-
3 loop PWRs at the 3411 megawatt thermal level.

4 We have had a search done on the operating history of
5 the U.S. plants and, as can be seen on the next two slides that
6 are in the handout, we believe there are over 100 reactor years
7 of experience. One of the original concerns for operation of
8 the large reactors and why Indian Point 2 was originally
9 licensed at the 2758 level was to permit the accumulation of
10 the experience.

11 Obviously, such experience has been gained.

12 [Slide.]

13 MR. LEWIS: I'm always interested when people quote
14 something like 100 years of experience as if it proved that you
15 wouldn't have an accident for the next thousand years. It's
16 just that you found that nothing obvious showed up in the first
17 100 years of four-loop experience at that power level.

18 MR. JACKSON: Certainly, I think we could
19 characterize the experience as not seeing surprises. When you
20 don't have experience, you're the first of the kind with an
21 extrapolation, you do not know what certain unknowns might be.
22 There was a concern that extrapolations not be made too great
23 until the experience was gained.

24 We're not proposing that the experience demonstrates
25 no accident potential, but what it's telling us is lessons

1 learned from the other facilities. There aren't the surprises
2 that may have been anticipated.

3 MR. LEWIS: Sure. It tells you that the plants can
4 operate at that level, but the concern about higher power has
5 always been that in the event of a malfunction, you just have a
6 lot more energy to get rid of. This doesn't tell you really
7 much about that. I'm not quibbling. Well, I am quibbling. Go
8 on.

9 MR. JACKSON: There were certain unknowns associated
10 with a large core, things such as xenon stability questions.

11 MR. LEWIS: Sure.

12 MR. JACKSON: They were calculated, projected,
13 expected, but you didn't have the experience and --

14 MR. LEWIS: No. I understand that.

15 MR. JACKSON: -- we now have those and we have a much
16 greater level of confidence than we did when we were here 17-18
17 years ago.

18 MR. LEWIS: That is certainly right. I'm just
19 reacting against another agency. I'm reacting against NASA
20 saying that 24 flights means that we have a safe system.

21 MR. MICHELSON: As I suspect the site had something
22 to do with the level of conservatism, too, didn't it?

23 MR. JACKSON: Not originally. If you go back to the
24 time period, we're talking the late 1960s or early 1970s, that
25 wasn't particularly the issue that it was in the early 1980s,

1 later time period with emergency planning.

2 It was generally a question of experience and there
3 were other reactors at other sites that were also limited
4 initially at that power level. It was not a siting issue, per
5 se.

6 MR. MICHELSON: But it has become one.

7 MR. JACKSON: Certainly, there has been obvious
8 increased attention and concern with siting. Indian Point 2,
9 however, has several design features that a number of other
10 plants do not have, which would serve to mitigate or counter
11 those concerns.

12 I believe we've gone over most of this slide. I just
13 wanted to highlight that although our original application was
14 for 2758 megawatt thermal, all of the original evaluations for
15 the engineered safety features were done at the 3216 level,
16 which is higher than the so-called stretch application power
17 that we're asking for now.

18 As part of that experience, Indian Point 3 that
19 followed us a few years behind in the licensing cycle, although
20 originally licensed at 3025, was restricted in operation to --
21 also at the recommendation of the ACRS -- to approximately the
22 Indian Point 2 level of 2750, along with, I believe, Zion and
23 Cook Plants had a similar early license restriction.

24 As we can see for the Indian Point 3 plant, which was
25 originally an exact duplicate of Indian Point 2, that

1 restriction was lifted in 1978. As Steve mentioned in his
2 presentation, during this period, we had then initiated our
3 stretch program, but we had to be put on hold as other events
4 in the industry happened.

5 One of the features that we have been able to do,
6 both with this application and over the last several years, as
7 we are reanalyzing for reloads, we have been modernizing, if
8 you will, the safety analyses and using more up-to-date
9 techniques. We're not relying on a 22 year old safety analysis
10 package.

11 As you can see from some of the material that will be
12 presented, we have essentially updated most of the safety
13 analysis chapter, if you will, in our FSAR.

14 [Slide]

15 MR. JACKSON: I would like to give a brief overview
16 of our current plans and where we are, first, our schedule.
17 With the assumption of a license amendment authorizing stretch
18 in the near term, we have currently planned a mid-cycle
19 inspection of our steam generator mid-cycle outage, and we
20 would be on schedule to implement a power escalation to the
21 higher power level on the return to service from that outage in
22 March.

23 We believe that's an opportune time to do the stretch
24 escalation. Why we are down, we can make the appropriate set-
25 point changes. Although other plants have done them online, we

1 would prefer, in our schedule, to do them while the plant is in
2 cold shutdown.

3 In addition, we are on schedule for procedure
4 changes, training, set-point changes that have to be made at
5 that time.

6 On procedures --

7 MR. MICHELSON: Did you give a date for when you
8 thought this change would occur, the time?

9 MR. JACKSON: We anticipate end of February, early
10 March, the license amendment. Maybe Mr. Brinkman will be able
11 to describe the staff's schedule. We are shutting down towards
12 the end of February for our mid-cycle. We will be down to
13 towards the end of March, and we would anticipate, if we have
14 the license amendment, making the changes while we are shut
15 down and starting up with the new license and power level.

16 MR. MICHELSON: In April then?

17 MR. JACKSON: At the end of March, our escalation
18 would begin, and return to service is currently scheduled the
19 end of March.

20 MR. CARROLL: Has all of this been programmed into
21 your simulator, and have the operators --

22 MR. JACKSON: Yes. I will describe some of the
23 procedure changes and the training scope that we're going
24 through.

25 On procedures, virtually all of the plant procedures

1 have been reviewed and changed identified for our operating
2 procedures, a checkoff list, test and calibration procedures,
3 any changes in our emergency operating procedures, some routine
4 thing such as heat-balance procedure, and also, we have
5 developed an onsite power escalation procedure to govern this
6 whole process.

7 We get to the training --

8 MR. CARROLL: How about the emergency plan? Does
9 this affect anything with respect to the way you'd analyze
10 accidents in the emergency plan?

11 MR. JACKSON: No. Our emergency plan, protective
12 action response, would not be affected by this change. The
13 responses are based upon observed plant parameters exceeding
14 certain limits and then recommendations based on those
15 parameters.

16 We have revised our emergency plan and procedures to,
17 as closely as possible, follow the symptom-based emergency
18 operating procedures so that the things that the operator would
19 have available to him to guide his actions in an emergency
20 would also immediately trigger appropriate events in the
21 emergency plan. We still have retained some of our event-based
22 requirements, but we have moved to making those emergency plan
23 procedures more user friendly for the operators.

24 In training, first of all, there is operator
25 training, formal classroom. This will begin at the next cycle

1 within the next, approximate, week, week and a half, so that
2 the operators will be trained on the changes in the various
3 set-points, procedures that are required, and we will catch all
4 operators before return to service. The operators will be
5 trained before they would have to go into the control room with
6 any of the changes.

7 We also are programming the changes into our
8 simulator, and those things that are affecting the simulator
9 response, the operators will go through that training prior to
10 being in the control room.

11 There aren't too many changes in terms of the actual
12 plant simulator response, but we will be reviewing accidents,
13 transients, everything from new reading on a megawatt meter to
14 how various secondary-plant pieces of equipment respond.

15 Our training scope will cover all areas of the NSSS,
16 as I mentioned -- accident transience, balance of plant
17 systems, technical specification changes, and all of the plant
18 set-point changes, which we treat very formally, as if they
19 were modifications to the facility.

20 We have begun part of the training of some of the
21 support staff in what we refer to as our "systems courses".

22 So, we are on schedule with the procedure changes,
23 the review process, and the training program.

24 [Slide]

25 MR. JACKSON: The next slide briefly describes the

1 areas where major set-point changes are required. Overpower
2 over temperature Delta T will be described and the reasons for
3 changes in the more detailed description by Mr. Liberatori, but
4 they're all the key areas. They match closely where we have
5 tech spec changes required and include such things as the
6 normal operating range on secondary-plant support equipment.

7 Before I conclude, the NRC project manager, Mr.
8 Brinkman, had indicated that there were some questions
9 regarding biofouling, and although I don't have a specific
10 slide, if it's appropriate, I'd just make a few remarks on some
11 of our experience now.

12 Two areas of biofouling history at Indian Point: one
13 called river grass and its potential for intake clogging, and
14 also, microorganisms.

15 The grass is a brief seasonal experience, when we
16 have temperature change in the river, and we get grass carried
17 into the intake structure. We have fine screens, travelling
18 screens, and our service water, in addition, has a Zurn
19 strainer system. When we get into the periods of time, the few
20 days each year, that we have grass, this requires additional
21 attention on the part of our operators for more frequent
22 cleaning of the intake structures.

23 Normally, we aren't getting grass carryover through
24 the screening system, but on the couple of occasions when that
25 has occurred, this requires that we go and inspect heat

1 exchanger equipment to be sure we don't have any clogging.

2 MR. MICHELSON: Are you using full-flow backwash-type
3 screens?

4 MR. JACKSON: Yes.

5 MR. MICHELSON: What's the mesh size, the finest mesh
6 size the water passes through on the way to the service water?

7 MR. JACKSON: On the service water, I believe we're
8 down to eighth-inch, now, screen size. We can double-check
9 that dimension. I'm going on memory. We had been larger, and
10 after our experience in 1980, one of the modifications we made
11 was to go to a finer screen size. I do not know the screen
12 size on our fine screens in front of the circulating water for
13 the condensers.

14 MR. MICHELSON: What about the emergency core cooling
15 systems? In other words, your emergency water systems -- what
16 screening do you use on that?

17 MR. JACKSON: Our service water feed is the heat sink
18 for the -- both directly for, for example, containment heat
19 removal with our fan cooler systems, and indirectly, for our
20 component cooling, which then serves the decay heat removal,
21 RHR heat exchangers. Service water directly cools our diesel
22 generators. Those are your key pieces.

23 MR. MICHELSON: And the screen size for that system?

24 MR. JACKSON: That's the --

25 MR. MICHELSON: Eighth-inch?

1 MR. JACKSON: That's what I have previously
2 described. The water is taken in through fine screens and then
3 through strainers, the Zurn strainer system that we have. We
4 have one strainer for each of the six service water pumps.

5 MR. MICHELSON: But the fine screen is one-eighth
6 inch.

7 MR. JACKSON: The Zurn strainer is about one-eighth.
8 I don't remember the exact size on the fine screen opening.
9 It's probably something a little larger than that. The purpose
10 of the fine screen is right at the river front, to catch large
11 debris before it would get to a pump. It's principally pump
12 protection. Then we have the fine mesh in the Zurn strainer
13 system, which then has a backwash capability, as well.

14 So, I mentioned, the grass is a seasonal thing.
15 We're prepared for it. It's just increased attention to
16 cleaning.

17 Microorganism experience: Where we are located in
18 the Hudson River, we're brackish water. We're not freshwater,
19 if we were further up the Hudson, nor are we the salt content
20 that we would see if we were down in the ocean. From certain
21 perspectives, perhaps that's an ideal location. But we have
22 had some minor barnacle problem that you see with brackish
23 water, at the intakes, but it has not been a major problem with
24 blockage. It's long term and removal of equipment such as
25 screens for cleaning. It's not a problem we have as much. Our

1 routine maintenance for corrosion inspection also takes care of
2 anything that's necessary for barnacles.

3 In 1980, when we had an increased leakage experience
4 with our fan cooler units inside containment, we believe that
5 there was some microorganism attach that was a minor
6 contributor to some of the leakage. We had particles that were
7 getting through and being lodged in tubes, and in the crevice
8 area, where those particles were lodged, we were seeing minor
9 pitting, which we believe was associated with some
10 microorganisms.

11 MR. MICHELSON: Which ones did you identify?

12 MR. JACKSON: I don't remember the specific names,
13 but they were attacking -- either they or their byproduct were
14 attacking the 90/10 copper tubes that we had installed at the
15 time.

16 As a result of that, several actions were taken. We
17 initiated chlorination, the service water system, and we are
18 essentially on a continuous, during daylight, weekday hours.
19 The fan coolers have been replaced.

20 Correction: The Zurn strainer is down to sixteenth-
21 inch mesh.

22 MR. MICHELSON: Sixteenth mesh. Okay. Thank you.

23 MR. CARROLL: I knew there must be somebody in that
24 cast of thousands back there that knew the answer.

25 MR. MICHELSON: Yes. Sixteenth is getting a little

1 closer.

2 MR. JACKSON: Yes. We had originally been the
3 eighth. We're down to sixteenth.

4 MR. MICHELSON: Yes.

5 MR. JACKSON: Part of our corrective action, of
6 course, as I mentioned, was chlorination. We do that during
7 daylight hours during the week.

8 MR. MICHELSON: You do it continuously in daylight
9 hours.

10 MR. JACKSON: Continuously in daylight hours. That's
11 correct.

12 MR. MICHELSON: Why do you choose the daylight hours?

13 MR. JACKSON: Well, it's a semiautomatic system.

14 Also, sunlight as an effect on the consumption of the residual
15 that then gets put into the discharge canal back to the river.

16 MR. MICHELSON: I see.

17 MR. JACKSON: Also, we want to closely monitor the
18 concentration, and we have additional personnel during the
19 daylight.

20 MR. MICHELSON: Go ahead.

21 MR. JACKSON: Additional things beyond the
22 chlorination -- specifically, the fan coolers. They were
23 originally redesigned. We replaced, of course, the leaking
24 coolers, and we redesigned the water boxes to preclude the
25 particles from being a potential plugging --

1 MR. MICHELSON: When you talk about "particles", are
2 you talking about bi-valves --

3 MR. JACKSON: No. These were principally pieces of
4 concrete.

5 MR. MICHELSON: Well, that's nothing to do with
6 biofouling, necessarily, although it's also an important
7 consideration.

8 MR. JACKSON: We really haven't seen -- there were a
9 few barnacles we saw in inlet water boxes, but not anything
10 significant that would have any measurable effect on flow.

11 MR. MICHELSON: No Asiatic clam contaminations in
12 that area?

13 MR. JACKSON: No, we haven't seen any of that kind of
14 --

15 MR. MICHELSON: No other types of clams?

16 MR. JACKSON: No, we have not seen any kind of a clam
17 infestation.

18 MR. MICHELSON: Do you have a silting problem at all
19 in that area?

20 MR. JACKSON: No, we don't have a significant silting
21 problem. The river drops off very steeply at the side of the
22 river, the Hudson River, where we are.

23 MR. MICHELSON: The easiest way to alleviate any of
24 my questions is simply for you tell me that you have done
25 certain tests of the flow capabilities of these systems in a

1 fairly decent time and that you're seeing there is still full
2 flow capability, and therefore, there is no reason to believe
3 your cooling water systems are other than fully effective.

4 MR. JACKSON: We have just responded -- I'm about to
5 send the response in to Generic Letter -- I believe it's 89-13,
6 where we are proposing an extensive program on performance
7 monitoring, but we have had for some time -- I'll give you two
8 key examples of the service water-fed heat exchangers, diesel
9 generators.

10 Flow is checked daily through the diesel generators,
11 to know that we're still seeing adequate flow. Monthly, when
12 we run diesel generators for a monthly test, we measure both
13 the inlet/outlet temperature Delta T, and we trend that.

14 For the fan cooler units, every 4 hours, we're
15 logging service water flow, and we have an action statement on
16 minimum flow.

17 So, two of the key safety-related service water heat
18 exchanger systems, which are at different elevations, are
19 continuously monitored.

20 MR. MICHELSON: Okay. Now, in the case of your
21 containment coolers, as an example, what degree, if any, of
22 flow degradation have you observed over the last, say, 3 years?

23 MR. JACKSON: Essentially none.

24 MR. MICHELSON: It's still a design basis flow.

25 MR. JACKSON: We're still above the evaluated

1 minimum. Approximately 1,200, I believe, is the number; 1,600
2 is the minimum for each of the fan coolers.

3 MR. MICHELSON: That's the number used in your safety
4 evaluation?

5 MR. JACKSON: Yes.

6 MR. MICHELSON: Your safety analysis.

7 MR. JACKSON: Of course, there are a number of
8 indirect measures such as the containment temperature during
9 normal operation which is monitored and we're able to correlate
10 that.

11 MR. MICHELSON: Direct measurement of the flow is a
12 very good way of knowing if you've got any degree of plugging
13 occurring in the system.

14 MR. JACKSON: We have a number of, as I mentioned,
15 direct measurements on flow as well as indirect measurements of
16 other parameters that are affected by the performance of the
17 heat exchangers.

18 MR. MICHELSON: How about your component cooling
19 water system? Do you monitor the service water side every four
20 hours?

21 MR. JACKSON: Service water side is monitored and I
22 don't have the frequency but we periodically monitor the closed
23 cycle side of it as well.

24 MR. MICHELSON: I'm interested mostly in the open
25 cycle side.

1 MR. JACKSON: On the service water side, I believe
2 we're bounding that by the different elevations of what we're
3 seeing on both the fan coolers and the diesel generators.

4 MR. MICHELSON: You mean you're not measuring your
5 component cooling water flows occasionally?

6 MR. JACKSON: We are measuring them occasionally but
7 I don't have off the top of my head the frequency. Maybe I can
8 get some help.

9 MR. MICHELSON: Because that's of course in some
10 respects even more important than the containment although
11 they're both very important.

12 MR. JACKSON: Yes, it is important. I just don't --
13 I pulled two examples from our procedures and I didn't pull all
14 of the heat exchangers out but we can get that answer for you.

15 MR. MICHELSON: Yes, if you could, and then indicate
16 when was the last time you measured it and how close to design
17 flow you might have been.

18 MR. JACKSON: I believe we did measurements during
19 the last refueling.

20 MR. MICHELSON: By design flow, I mean the one you're
21 using in your safety analysis because you're making an argument
22 and the staff's making an argument that these systems are way
23 oversized and they're still oversized and I just wanted to make
24 sure we know they're oversized and that's why you measure the
25 flow once in a while.

1 MR. JACKSON: Yes, as we mentioned, they were
2 previously designed and evaluated for a much higher power level
3 than the oversized but we'll get the specific number for you by
4 the end of the morning.

5 MR. MICHELSON: Thank you.

6 MR. JACKSON: At this point, if there are no further
7 questions, I'd like to introduce Lou Liberatori who will now go
8 into the next layer of detail on the evaluations that were
9 performed and some of the results.

10 MR. CARROLL: Out of curiosity, is the increased
11 condenser delta T causing any problems? Who did you have to
12 get approval to?

13 MR. JACKSON: When we originally licensed the plant,
14 the environmental effects were evaluated at the full power
15 level. In addition, the environmental effects were evaluated
16 including Indian Point Unit I which is now retired. So we have
17 plenty of margin in what was evaluated. We didn't have to go
18 back and do re-reviews and get any additional approvals in that
19 area.

20 MR. MICHELSON: Just while you're still here, just
21 one brief question. You said you were working on your response
22 to the service water system generic letter. Are you going to
23 take any exceptions to the generic letter?

24 MR. JACKSON: I don't believe so. We're proposing a
25 program that incorporates much of what we're already doing.

1 While we've been here in Washington, the final part of that
2 letter has been prepared and I don't have a copy with me but as
3 I recall --

4 MR. MICHELSON: You're not aware that you will take
5 exception to any of the requirements.

6 MR. JACKSON: As I recall the graphs, we're proposing
7 a program that I believe we think is consistent with what's
8 being requested.

9 MR. MICHELSON: Thank you.

10 [Slide.]

11 MR. LIBERATORI: Thank you, Charlie.

12 Good morning. I'm Lou Liberator, manager of safety
13 assessment at Con Edison's Indian Point Station. The purpose
14 of my presentation this morning is to give you a brief overview
15 of the results of our stretch program concentrating in both the
16 analytical areas as well as the plant's equipment performance
17 areas.

18 As Steve stated, there are many specialists in the
19 audience today to support me in any questions or details that I
20 might not be able to provide to you. First of all, as you can
21 see from my first slide, I divided my program into four basic
22 areas. I'd like to cover transients and accidents first
23 describing both loss of coolant and non-loss of coolant
24 accidents as well as off-site dose evaluations, touch on the
25 technical specification changes that we requested of the staff,

1 describe our plant equipment evaluations and then draw a
2 conclusion.

3 Before I move to my next slide, I'd like to briefly
4 describe the amendment process as we approached it. We had two
5 processes going on in parallel. One was an effort to change
6 over in fuel design from the standard Westinghouse fuel to the
7 optimized fuel assembly and that was going on essentially in
8 parallel with our restarted stretch program and to support the
9 fuel design change, all the loss of coolant accidents and
10 certain of the FSAR non-loss of coolant accidents required
11 reanalysis.

12 What we chose to do was not only perform those
13 analyses to support the fuel change but also to conduct them at
14 the assumed higher power levels since we knew we had that
15 effort going on in parallel and in effect, it prevented us from
16 having to do analysis twice and also represented an efficiency
17 on the part of the staff resources in terms of review.

18 What our stretch application did contain were the
19 remaining FSAR transients which were not specifically
20 reanalyzed as part of the fuel design package.

21 So at this point, we have as Mr. Jackson referred to
22 earlier, effectively reanalyzed the required FSAR transients
23 for entire Chapter 14 of our FSAR and those analyses packages
24 bound current operation as well as the proposed stretch power
25 operation and I'll give into more of that as I go on in my

1 slide presentation. Next slide, please.

2 [Slide.]

3 MR. LIBERATORI: With respect to the loss of coolant
4 accidents, as part of our upgrading to more recent approved
5 models by the staff, we have performed the large break LOCA
6 analysis using the BASH code technology and have performed the
7 small break accidents using the NOTRUMP model and I've depicted
8 the PCTs for both the large break and the small break on this
9 slide and as you can see, both numbers are appreciably within
10 the 2,200 degree acceptance limit of 5046.

11 MR. CATTON: What were those numbers before the power
12 increase?

13 MR. LIBERATORI: The previous number for -- let's
14 take the large break, for example. For the limiting break
15 size, the number was approximately 1950 and I guess what I
16 should point out is, if you recall Mr. Jackson's slide on the
17 ranges of parameters that we've evaluated the stretch for,
18 these numbers represent the peak clad temperature for the
19 limiting values for each of those parameters.

20 So if you looked at where the plant will actually
21 operate, we're probably talking a peak clad temperature that's
22 approximately the same as what we have now at 2758, again,
23 owing to the more sophisticated modeling and computer codes
24 that are used today.

25 Again, just a point that the remainder of the 5046

1 criterion were demonstrated to be satisfied in our submittal to
2 the staff and we also relooked at containment performance with
3 respect to its response to a loss of coolant accident. Since
4 original licensing of the unit, the containment response has
5 always been evaluated assuming a core power level of 3216 and
6 we were consistent with that in our reassessment with respect
7 to the proposed power level and obviously it bounds it.

8 We did need to redo the analysis since at the upper
9 range of the operating temperatures of what we've analyzed we
10 would have a slightly higher hot lake temperature than was
11 previously utilized. So we reanalyzed the containment again at
12 3216 but with the wider temperature range and the effects were
13 about a half a pound higher than what we had calculated before
14 so we're talking approximately 41.1 pounds versus the original
15 FCR value of 40.6 pounds both of which are clearly within the
16 containment design pressure of 47 pounds.

17 More importantly, in the staff's original SER, they
18 defined a margin of safety with respect to containment as the
19 design pressure should exceed the peak pressure by at least 10
20 percent and both the 40.6 and the 41.1 satisfy that original
21 criteria so we're really not changing that margin of safety as
22 originally licensed.

23 Otherwise, there was really no major effect in terms
24 of containment performance. Next slide, please.

25 [Slide.]

1 MR. MICHELSON: Excuse me. In the case of
2 containment performance, you're depending upon the heat
3 exchangers there in part for keeping -- is that correct in this
4 plant?

5 MR. LIBERATORI: That's correct. The analyses for
6 the containment were done assuming heat input associated with a
7 3216 operating core and the fan coolant performance is based on
8 being able to remove that heat and the --

9 MR. MICHELSON: A certain number of fan coolers were
10 assumed to be functioning properly.

11 MR. LIBERATORI: That's correct and the flows that we
12 used in terms of establishing operability for the fan coolers
13 are based on their ability to remove a 3216 heating core.

14 MR. MICHELSON: Now in designing those fan coolers,
15 there are certain fouling factors and so forth assumed in the
16 design. Have you any test evidence of late to verify that
17 these are still reasonable numbers?

18 MR. LIBERATORI: I believe we -- subject to
19 correction by some people -- I believe we stuck with the same
20 fouling factors. That appeared to be reasonable. I think as
21 Mr. Jackson stated that the fan cooler performance certainly
22 from our periodic inspections has been fairly good.

23 MR. MICHELSON: Does the fan cooler performance
24 include a test estimate of the fouling factors?

25 MR. LIBERATORI: I don't believe I have the

1 information to answer that.

2 MR. MICHELSON: Or do you just measure the fullness
3 of the heat exchanger and leave it go at that, delta T?

4 MR. LIBERATORI: We'll see if we can get an answer to
5 that question before the morning is over.

6 MR. MICHELSON: Okay.

7 MR. JACKSON: I can give a brief answer. It's flows
8 delta T and of course indirectly, an expected performance on
9 normal containment temperature. Of course, we do have new heat
10 exchangers. We're not talking about 20-year-old heat
11 exchangers.

12 MR. MICHELSON: These are new.

13 MR. JACKSON: After the 1980 event, we replaced and
14 more recently, we replaced the heat exchangers from the 90/10
15 copper material to a AL6X material.

16 MR. MICHELSON: Were the new heat exchangers any more
17 conservatively designed than the previous ones or the same?

18 MR. JACKSON: I think they were identical.

19 MR. MICHELSON: Thank you.

20 I would like to know why you believe that the heat
21 transfer capabilities are approximately the same as the
22 original design basis.

23 MR. JACKSON: Yes.

24 [Slide.]

25 MR. LIBERATORI: My next slide touches briefly on the

1 non-LOCA transients. All of the SER required non-LOCA
2 transients were reanalyzed. As I stated earlier, some were
3 done as part of the fuel design change, some specifically
4 associated with stretch.

5 In each case, we've demonstrated that the transients
6 satisfy the various applicable criteria for each of the
7 individual accidents. Again, as Mr. Jackson indicated, using
8 currently accepted codes by the staff and each of the specific
9 numbers for the various accidents are contained in our
10 submittal.

11 MR. MICHELSON: Have you ever performed a natural
12 circulation test from full power on this plant; either on
13 purpose or by accident? Have you ever gone into natural
14 circulation from full power?

15 MR. LIBERATORI: Well, we have had plant trips which
16 have resulted from loss of offsite power, which put us into
17 that.

18 MR. MICHELSON: Yes, that will put you into natural
19 circulation.

20 MR. LIBERATORI: That's at least one that I can
21 recall which was probably about ten years ago.

22 MR. MICHELSON: Did you ever analyze the subsequent
23 performance to see if it met your expectations?

24 MR. LIBERATORI: I guess, to the best of my
25 recollection, the plant behaved as expected in terms of off-

1 speed, attaining and achieving hot shutdown, diesel generators
2 picking up, you know, required loads. To my recollection, that
3 was the case.

4 MR. JACKSON: If I may interrupt; I don't think the
5 actual event would really lead itself to the analysis. We
6 didn't go into a cooldown; we just maintained the plant
7 briefly.

8 MR. MICHELSON: Have you ever, on purpose, performed
9 some kind of natural circulation test, you know, as a test?

10 MR. JACKSON: I believe, if we go back 20 years, I
11 believe that during hot functional, there may have been some
12 verification.

13 MR. MICHELSON: This is in more recent times.

14 MR. JACKSON: This wouldn't have been in the more
15 recent times.

16 MR. MICHELSON: The emphasis was put back on it in
17 the early 80's, but I believe they allowed you to use a sister
18 plant's results so you didn't -- I just wondered if you did
19 your own, or if you used a sister plant result?

20 MR. JACKSON: I think we're relying on experiences
21 with --

22 MR. MICHELSON: This tells you something about how
23 much your predictions of margin really -- how much that margin
24 is really there. You're going to lose a little bit of it now
25 when you go up in power, another 10-12 percent, so that margin

1 is going to disappear.

2 If you did a natural circulation test today, it will
3 be different, the result, once you have elevated your power --
4 potentially different.

5 MR. JACKSON: It would be potentially different.

6 MR. MICHELSON: I just wondered if you had any old
7 test results or not on this. I assume person --
8 I'd like to ask the staff; if you raise 12
9 percent, are you required now to go back and do a natural
10 circulation test, or just show that somebody else had done one
11 that looks close enough?

12 MR. COLLINS: My name is Tim Collins. I'm with the
13 Reactor Systems Branch. A plant increasing its power by 10
14 percent would not be required to do a natural circulation test.
15 They can depend upon the results of other plants if they'd
16 like.

17 MR. CARROLL: What test is it, in point, relying on?

18 MR. COLLINS: I don't know the answer to that.

19 MR. MICHELSON: Well, has the staff asked them to
20 demonstrate that they will have -- you have not asked them?

21 MR. COLLINS: No, we have not asked them.

22 MR. JACKSON: I believe the information we're relying
23 on is Diablo Canyon which was performed at a much higher power
24 level than we're asking for.

25 MR. MICHELSON: How about the loop configuration and

1 so forth; identical?

2 MR. JACKSON: We're talking a similar design.

3 MR. MICHELSON: Similar pumps and so forth?

4 MR. JACKSON: I'm looking at Westinghouse to verify
5 it. I believe it's a similar design and similar configuration.

6 MR. MICHELSON: So somebody has gone through the
7 arithmetic and says that this is sufficiently identical that
8 that test satisfies your need? I would hope that staff asked
9 for that because I thought it was a requirement in order to
10 elevate power, but maybe not.

11 MR. COLLINS: No, we do not require that.

12 MR. MICHELSON: It's been required in the past. You
13 know, you required everybody to either go do it or demonstrate
14 that somebody else has done it that's close enough and alike.
15 That was in the early 80's -- '83 or '84 or somewhere in that
16 timeframe, I thought. That was when we started getting very
17 much interested in plants not seeming to do so well when they
18 went on natural circulation.

19 Let's go back and look at it. Maybe I'm wrong. How
20 about it, Jay, do you remember the history on that natural
21 circulation as to when it was?

22 MR. CARROLL: Your timeframe is about right, I guess.

23 MR. MICHELSON: I thought it was a requirement that
24 everybody had to meet and I would think that it's still a
25 requirement to meet if you want to raise your power.

1 MR. CARROLL: I think that what they're arguing is
2 that an identical -- essentially identical plant has
3 demonstrated this --

4 MR. MICHELSON: No problem, but I think that it has
5 to be documented. I think it's that much of a requirement that
6 you either do it, or you document it.

7 MR. CARROLL: I'm surprised the staff hasn't put that
8 in their safety analysis.

9 MR. CAPRA: Excuse me, sir. I'm not familiar with
10 that particular requirement with respect to a power uprate.
11 Now, around the timeframe in 1980 -- again, I don't have the
12 details of it -- there was a generic letter that was issued in
13 response to an event, I believe, at St. Lucie with the ability
14 of a plant to cool down a natural circulation without drawing a
15 bubble in the head, where generic requirements laid on all
16 utilities to either perform an analysis or do a test, as I
17 recall.

18 Indian Point was reviewed and evaluated for
19 compliance with that particular generic letter, but that was
20 not associated with this power uprate.

21 MR. MICHELSON: When you raise the power 10-12
22 percent, I think you need to go back and make sure that
23 analysis done back at that time is still valid. I think that
24 ought to be a standard check item for whenever you do any
25 consideration of power upgrading of this magnitude.

1 I think there's no problem. I'm sure they've
2 sister that looks close enough alike and has the test results,
3 but the fact that the staff didn't even ask or look at it
4 bothers me a little bit.

5 MR. CAPRA: If you will recall, the original staff
6 evaluation for this plant, with the exception of ECCS
7 performance was done.

8 MR. CARROLL: That was before we understood these
9 problems.

10 MR. LEWIS: There's a whole batch of generic things
11 that are being asked here, centered around this particular one
12 which is that part of the argument for the upgrade is that the
13 plant was originally, in 1973 and in that period just before
14 then, evaluated at the higher level, but there have been a
15 number of things since then and presumably to justify an
16 upgrade or an increase in power, one has to demonstrate that
17 the plant would now, at the new power, comply with the current
18 regulations for plants at that power, and that includes some of
19 these -- not backfitting, but reanalysis items from the past.

20 I assume the staff is certifying that that's the case
21 to us.

22 MR. JACKSON: I think, Dr. Lewis, if I might attempt
23 an answer, -- this is Charles Jackson from Con Ed. I believe
24 that are -- in consulting with Westinghouse -- that our
25 evaluation and the acceptance by the staff of the SER was based

1 upon experience with, particularly, Diablo Canyon, but others
2 at higher power level than we are asking for now.

3 MR. LEWIS: That's for the specific issue?

4 MR. JACKSON: Yes, and also for the issue of our
5 sister plant, Indian Point 3, which was also reviewed and
6 evaluated at a very close level, the 3025, so that we think
7 that we're well bounded by what has gone before and what has
8 been evaluated, so that it did not become the subject of a need
9 for a specific reevaluation in this application.

10 MR. CARROLL: Does the staff's SER deal with the
11 issue of natural circulation?

12 MR. CAPRA: No, sir, it does not. We used the
13 original licensing basis of the facility with exception of the
14 revised ECCS analysis. I know that doesn't answer your
15 question. I'm telling you what the staff did, in fact, review.

16

17 We did not take the delta between the original
18 licensing basis of the facility and upgrade it to all current
19 regulatory requirements on this particular power uprate and
20 that's consistent with what we've done for other stretch power
21 applications.

22 MR. LEWIS: Will the plant at the new power level, if
23 it's approved, comply with all existing requirements for a
24 plant at that power level? The staff is certifying that to us?

25 MR. CAPRA: Yes, sir, I believe it will do that with

1 respect to --

2 MR. LEWIS: But with the exception of natural
3 circulation?

4 MR. COLLINS: I am not sure exactly what you're
5 asking. This plant -- we're not saying that this plant will
6 meet all criteria for a plant that would be licensed today;
7 we're not saying that.

8 We're saying that at the higher power level, it would
9 meet the requirements that it was licensed to originally.

10 MR. LEWIS: Okay.

11 MR. MICHELSON: That's not good enough.

12 MR. LEWIS: No, not at all.

13 MR. COLLINS: That's what we're saying, though.

14 MR. LEWIS: That's what I was trying to pin down and
15 that's what my friends have been trying to pin down on this
16 particular point.

17 MR. COLLINS: That is what we're saying.

18 MR. MICHELSON: There have been a number of changed
19 requirements from time to time since it was originally
20 licensed. There have been generic letters and so forth. I
21 assume that you review all of those kinds of newer requirements
22 for comparable plants and make sure this plant meets the same
23 requirements?

24 MR. COLLINS: Anything that was backfit since the
25 plant was originally licensed; it still has to meet those

1 requirements also, if something was backfit on the plant. But
2 something which was not backfit into this plant; it would not
3 now have to meet those criteria because they're upgrading the
4 power.

5 MR. MICHELSON: Natural circulation wasn't a backfit.
6 That was a requirement and that has always been a design
7 requirement. They just went back and reminded people that
8 you've got to make sure it works. I assume in this case that
9 somebody has assured that, yes, it will work, also at this
10 higher power level on this plant. I'm sure it's not a problem,
11 but I'm a little concerned that somebody doesn't, you know,
12 kind of check it anyway.

13 MR. CARROLL: Let me try: has it been specifically
14 looked at?

15 MR. COLLINS: The natural circulation question; this
16 one?

17 MR. CARROLL: Yes.

18 MR. COLLINS: I can't say for sure; I don't know for
19 sure. Okay, we certainly didn't address it in the SER, but
20 that doesn't mean that somebody didn't look at it in the
21 process and decide it was a no-never-mind. I would have to
22 check that. I just don't know.

23 MR. CARROLL: Do you believe that it should be looked
24 at in a stretch application?

25 MR. COLLINS: Yes, yes.

1 MR. CARROLL: And documented in the SER?

2 MR. MICHELSON: It really should be in the SER.

3 MR. LEWIS: Let me ask the question in a slightly
4 different way. Since --

5 MR. CARROLL: I didn't get an answer to my question.

6 MR. LEWIS: I heard the answer to your question, but
7 let me broaden it a little bit. I just want to be very clear
8 about this.

9 Since 1973, there have been a batch of things. There
10 were the hundred-odd post-TMI action plan items and the plant
11 presumably has complied with as many of those as everyone else
12 has and has been reviewed in the normal course of events for
13 compliance of those.

14 There have been a batch of generic letters and so
15 forth. A few of those -- were those compliances based on the
16 2758 or on the original plant power analysis which was done at
17 a higher level, on which we are now inquiring? That is to say;
18 has all subsequent analysis been done at the 2758 license core
19 level or at the original design basis level?

20 MR. CAPRA: All of the reanalyses that were done with
21 respect to the transient accident analysis for this power
22 uprate were done at the higher power level.

23 MR. LEWIS: That is not the question I asked.

24 MR. CAPRA: If your question is each individual
25 requirement --

1 MR. LEWIS: I'm saying there have been many
2 requirements levied since 1973 of which there were the hundreds
3 of TMI and there are lots of generic letters and things like
4 that. Those reviews were all done at 2758?

5 MR. CAPRA: I believe that's probably the case, if
6 they were power dependent at all. I mean, many requirements --

7 MR. LEWIS: I'm aware that many of them are not power
8 dependent but where there is power involved as there is, for
9 example, for natural circulation, they were done at the 2758.
10 That means that we do not have an assurance that those letters
11 would have been complied with if the plant had originally gone
12 to the original design level; is that correct?

13 MR. CAPRA: I can't give you a direct answer to that.

14 MR. LEWIS: I see.

15 MR. CAPRA: We have no evaluated that.

16 MR. LEWIS: Fine.

17 MR. CAPRA: Perhaps each individual requirement --

18 MR. JACKSON: Dr. Lewis, perhaps I can attempt to
19 address that.

20 MR. LEWIS: You see why I'm asking.

21 MR. JACKSON: Yes, and we have already gone through
22 that. The question really is much broader than the specific
23 issues that might have been evaluated in part of an SER issued
24 by the staff. We have attempted throughout the history of this
25 unit to maintain modifications and evaluations on safety-

1 related areas at the 3216 level and there are only a limited
2 number of them that were specific where they were power level
3 dependent specific to the 2758 and we believe we've identified
4 those and we've incorporated the various modifications in the
5 assumptions for the reanalysis work that has been performed for
6 this application.

7 However, we have gone beyond that and there are
8 provisions which you're probably aware of that a licensee is
9 permitted to make modifications under 10 CFR 5059. We have
10 conducted a review of the several hundred such modifications
11 that we have performed to assure ourselves that there are none
12 of the evaluations that we have performed that are power level
13 dependent that, a set point or an assumption on some parameter
14 such as flow or pressure is power level dependent in those
15 safety evaluations.

16 We have not found any additional that have not been
17 part of the reevaluation and we've completed that review
18 ourselves to give us that assurance. We had a similar concern
19 that we may have done something over the years that is specific
20 to a given power level. I think as staff mentioned, most of the
21 modifications evaluations are not power level dependent. There
22 are only a few of them that are.

23 MR. LEWIS: Okay, I thank you, I must say for a
24 direct answer. Let me make sure I understand it. You say that
25 throughout the history of the plant, you've formed in the back

1 of your mind that you might go again for the original design
2 power level and therefore you've made all your mod's
3 consistently with the originally designed power level and now
4 you've gone back to make sure that you did that okay; is that
5 essentially what you've said?

6 MR. JACKSON: That's correct.

7 MR. LEWIS: Thank you.

8 MR. CARROLL: I thought I heard you say there were a
9 few that were done at the 2758?

10 MR. JACKSON: Yes. The principal area is the
11 emergency core cooling system in which the staff evaluations
12 were -- although we as licensee had formed a calculations and
13 submitted them on the docket at higher power, the evaluations
14 done by the staff and specific set points that resulted from
15 that and technical specifications were at the 2758 so that was
16 one of the major areas of our reevaluation was the emergency
17 core cooling system performance and compliance with 5059.

18 MR. MICHELSON: This is an area that I'm surprised
19 the staff didn't include in their SER. They should have said
20 that there are a few things that might have happened that would
21 be power dependent and here's the ones that did happen and
22 here's how we evaluate them. I didn't find it anywhere in the
23 SER but maybe I missed it, such things as the natural
24 circulation test. It is an important consideration when you
25 elevate the power this much, to make sure that these things are

1 still monitored.

2 MR. CAPRA: Yes, sir. I understand your concern and
3 you didn't miss it in the SER.- It's not addressed.

4 MR. LEWIS: Please go on. We've not given you much
5 of a chance to talk.

6 MR. LIBERATORI: If I might on a follow up slide, I
7 think I have a good example of the situation that occurred
8 after 1973. So I think I can give you a good example.

9 MR. LEWIS: How are you doing on schedule because my
10 friends will shoot me if we're very late with our mid-morning
11 break.

12 MR. LIBERATORI: I probably have about half left but
13 I'll do the best I can.

14 MR. LEWIS: How many?

15 MR. LIBERATORI: About half of my presentation left.

16 MR. LEWIS: Which means?

17 MR. LIBERATORI: Maybe another 10 minutes.

18 MR. LEWIS: I'll hold you to that. Go.

19 MR. LIBERATORI: Okay.

20 Non-loss of coolant accidents, as I stated, have all
21 been reanalyzed at this point. They meet the various non-LOCA
22 acceptance criterion. With respect to containment performance,
23 the transient of interest is the steam line break as opposed to
24 the loss of coolant. Licensing up to this point has had the
25 loss of coolant response bound, the steam break response.

1 We've reconfirmed that that continues to be the case at the
2 proposed power level. There's no change with regard to that.
3 Next slide, please.

4 [Slide.]

5 MR. LIBERATORI: Off-site dose evaluations, again the
6 original FSAR performed all the dose consequences assuming a
7 3216 radiological source term. So that still bounds the
8 situation we're talking about now. There were two specific
9 events which we reassessed. The first one was to look at the
10 dose calculations for the tube rupture accident which as I
11 stated were done with a 3216 source term to get a feel for the
12 sensitivity affect of again the parameter range that we've
13 analyzed for here and we found that the effect of the parameter
14 range really were insignificant in terms of the dose
15 consequences of the tube rupture and in fact remained well
16 within the guidelines for the accident.

17 The second accident which I referred to was a fuel
18 handling accident in containment. There was a generic letter
19 in the late 1970s which the staff requested all licensees to
20 evaluate. That accident was not in our original FSAR and at
21 the time we did it, we did it at the 2758 calculated power
22 level. As part of our submittal to staff, we have recalculated
23 that accident with a 3216 radiological source term making that
24 now consistent with all the original FSAR accident analyses and
25 in fact, one of our tech spec changes was a result of that. In

1 order to maintain the same dose consequences for that event, we
2 back-calculated it increasing the delay time prior to moving
3 the first spent fuel assembly such that the consequences of the
4 action would remain the same even though we assumed a much
5 higher radiological source term now.

6 MR. CARROLL: What's the minimum time?

7 MR. LIBERATORI: The minimum time is currently 131
8 hours. It will be increased to 174 hours. So approximately 40
9 hours longer and that results in the same consequence for the
10 accident, just in effect allowing more decay since we assume
11 the higher source term. There is the case of an accident which
12 in our review we did uncover as a post-licensing accident, then
13 reanalyzed it.

14 MR. CARROLL: Isn't that hurting you in terms of real
15 world schedules?

16 MR. LIBERATORI: Well, we've looked at it in terms of
17 real world schedules and based on experience, when we normally
18 start moving fuel, we did not see that as a tremendous economic
19 restriction.

20 MR. CARROLL: Okay.

21 MR. MICHELSON: What was the feedwater maximum
22 temperature and what is it now under the new power?

23 MR. LIBERATORI: The main feedwater temperature?

24 MR. MICHELSON: Yes.

25 MR. LIBERATORI: If my recollection is correct, it's

1 going up about 10 degrees from about 415, 420 range to
2 approximately 427, something in that range.

3 MR. JACKSON: A 15 degree increase, going up to about
4 430.

5 MR. MICHELSON: That's included of course in your
6 analyses and so forth?

7 MR. LIBERATORI: That's correct. That's correct.

8 MR. MICHELSON: Thank you.

9 MR. LIBERATORI: So in summary, the limiting FSAR
10 events are now consistently analyzed at the 3216 power level
11 source term and the results remain below the Part 100 guideline
12 limits.

13 Next slide, please.

14 [Slide.]

15 MR. LIBERATORI: Quickly, to touch on the technical
16 specification changes we've requested of the staff, first
17 change was the power level from 2758 to 3071.4. Changes we
18 needed to bolt these T-average max as well as the T-average
19 input to the overpower and overtemperature delta-T equations
20 again based on the upper bound of the new operating temperature
21 range.

22 The loss of feedwater flow accident assumed a higher
23 minimum aux feed flow to take care of the higher decay heat
24 levels. We revised the tech spec's minimum to match what we
25 used in the current analysis. The basis of that particular

1 tech spec happened to state what the full power steam flow was,
2 so just that number physically has to change to the steam flow
3 at the higher power level.

4 MR. MICHELSON: How much have you elevated the steam
5 temperature for the new power?

6 MR. LIBERATORI: Not appreciably. Probably on the
7 order of the same -- subject to check I guess on the order of
8 the same 5 or 10 degrees.

9 MR. MICHELSON: What's your new steam temperature max
10 of the generator?

11 MR. JACKSON: Remember, we're analyzing for a range.
12 The current power steam temperature at steam generator outlet
13 is 514 approximately and if we go to the upper range of the RCS
14 temperature, we're just over 513. The lower temperature
15 extreme would be 482.

16 MR. MICHELSON: That's the current.

17 MR. JACKSON: We're currently --

18 MR. MICHELSON: You've got a range currently, I
19 assume.

20 MR. JACKSON: No, right now, we have a specific
21 point.

22 MR. MICHELSON: Oh, you don't want to stick with one
23 point.

24 MR. JACKSON: Okay. The revised analyses, if you'll
25 recall one of my earlier slides provided for a various range of

1 RCS temperatures, pressure -- secondary pressures.

2 MR. MICHELSON: It's secondary I'm interested in.
3 You're not going to exceed the 514 yet; is that correct?

4 MR. CARROLL: Pressure is dropping as the power goes
5 up.

6 MR. MICHELSON: Uh-huh, but he's still starting out
7 at the 514 as his peak.

8 MR. JACKSON: Yes. At the upper range of
9 temperature, we're essentially the same, within a degree, the
10 lower RCS temperature range, your temperature is dropped and of
11 course, you're going to be limited based upon pressure in terms
12 of stress analysis considerations. So depending on plugging
13 level --

14 MR. MICHELSON: That takes care of it. Thank you.

15 MR. LIBERATORI: The last technical specification
16 change that I just mentioned previously was the increase in the
17 delay time prior to moving the spent fuel assembly to be
18 consistent with the assumptions made in the fuel handling
19 accident in the site containment.

20 Next slide, please.

21 [Slide.]

22 MR. LIBERATORI: Plant equipment review. We looked
23 both at the nuclear steam supply systems and equipment in
24 conjunction with Westinghouse, the original NSSS vendor.
25 Likewise, we looked at all the balance-of-plant systems and

1 equipment in conjunction with United Engineers, with the
2 original AE.

3 The next slide.

4 [Slide.]

5 MR. LIBERATORI: This is in a sense a listing of key
6 systems within the NSSS scope which we evaluated. In each
7 case, we reviewed the equipment against the stretch conditions
8 and determined that the design envelopes the anticipated
9 operating conditions at stretch.

10 And as Mr. Jackson mentioned, there are normal
11 control setpoints, alarm setpoints, and so forth, which will
12 have to be adjusted to reflect where we will actually operate
13 the plant, but again, within the capability of the existing
14 instrumentation. It is just a matter of adjusting things. So
15 there are no physical, you know, hardware changes necessary to
16 support this evaluation. In effect, the design envelopes the
17 anticipated operating conditions.

18 The next slide.

19 MR. CARROLL: Pressure safety valves. Do you have
20 loop seals?

21 MR. LIBERATORI: No, we don't.

22 MR. CARROLL: Okay. What impact, if any, does the
23 current flap about how to set safety valves and potential 10
24 percent errors in safety valve set-ins, and that sort of thing,
25 have on the safety analysis that you've performed?

1 MR. LIBERATORI: We feel it doesn't have a
2 significant impact on us. We don't have loop seals; we test
3 our safety valves in a facility with saturated pressure.

4 MR. CARROLL: So you are actually testing them on
5 saturated steam?

6 MR. LIBERATORI: That is correct. And we are part of
7 the Westinghouse owners group, so obviously we are aware of the
8 existing issue, and it seems to be concentrating on those
9 plants with loop seals.

10 MR. CARROLL: Yes.

11 MR. LIBERATORI: But we will continue to follow the
12 issue, and whatever comes out of that analysis, we certainly
13 will follow it if it applies to us.

14 MR. CARROLL: Has your experience with pressurizer
15 safety valves been good without them having loop seals?

16 MR. CARROLL: I would say our experience has been
17 good, yes.

18 [Slide.]

19 MR. LIBERATORI: Balance-of-plant. As Mr. Jackson
20 pointed out, originally designed and guaranteed at 3083.4,
21 calculated capability of 3216 megawatts thermal. We did a
22 similar review, evaluated the systems and equipment against
23 stretch, determined that the design of the systems enveloped
24 the anticipated operating conditions. Again, there are normal
25 control setpoint changes necessary, heated drain tank levels,

1 alarms, deviation alarms, et cetera, associated with normal
2 operation.

3 In addition, for both NSSS and BOP, obviously there
4 are changes to the facility necessary to accomplish the
5 requirements of the proposed technical specifications. We've
6 submitted, you know, reactor protection trips and aux. feed
7 flow and so forth.

8 The next slide, please.

9 [Slide.]

10 MR. LIBERATORI: I would like to conclude by saying
11 that we believe the Stretch Program has demonstrated compliance
12 of the FSAR analyses with applicable acceptance criteria, that
13 we have demonstrated compliance of the components and systems
14 with FSAR functional and regulatory requirements. The Stretch
15 Program has reconfirmed the capability of the plant to perform
16 in its original guaranteed power rating, and, as our
17 application states, we determined there is no significant
18 hazards consideration involved as per 10 CFR 50.92C.

19 That concludes my prepared presentation.

20 MR. LEWIS: Thank you very much.

21 MR. JACKSON: Dr. Lewis, there were two questions
22 that, if you would like our brief answers to the questions
23 before the break, we can attempt to answer them now.

24 MR. LEWIS: Oh, why don't we do them after the break,
25 when we are more prepared. Let me give us a 10-minute break,

1 reconvene at quarter of, and then we will have those questions,
2 the licensee conclusion, and the staff conclusion.

3 [Brief recess.]

4 MR. LEWIS: Okay. Let's come to order.

5 I think you had a couple of things to tell us before
6 the summary. Is that right?

7 MR. JACKSON: That's correct.

8 MR. LEWIS: Okay.

9 MR. JACKSON: Charles Jackson.

10 MR. LEWIS: Are you ready?

11 MR. JACKSON: There were two questions, and if I
12 understand them correctly, let me attempt an answer.

13 First was on the component cooling heat exchanger and
14 what monitoring was being done and how frequently.

15 On the component cooling water side, the closed-cycle
16 side, there is a monitoring every 4 hours of the header
17 temperature and flows. On the service water side, we are also,
18 on similar frequency, measuring header pressures, and then at
19 refueling intervals, we put on special instrumentation for
20 flow. We don't, right now, have instrumentation for flow to
21 that specific heat exchanger but monitor the header flow.

22 MR. MICHELSON: Do you mean the header flow or the
23 header pressure?

24 MR. JACKSON: The header pressure. Excuse me.

25 MR. MICHELSON: Header pressure doesn't tell you

1 anything.

2 MR. JACKSON: We're measuring the --

3 MR. MICHELSON: The pressure will go up as you start
4 to plug the headers.

5 MR. JACKSON: Well, we're measuring the temperature
6 on the other side of the heat exchanger, and --

7 MR. MICHELSON: The downstream side of the service
8 water, you're monitoring the temperature. Is that what you're
9 saying?

10 MR. JACKSON: No. On the component cooling water
11 side, we're monitoring regularly the temperature. So, if we
12 had a decreased flow on the service water side of the heat
13 exchanger, we'd see, for the normal operating condition,
14 temperature would increase, and we have established a range of
15 expected temperature that we would expect to see.

16 MR. MICHELSON: Okay. So, you monitor only -- you
17 only monitor the header pressure on the service water side.
18 I'm not quite sure what that's for. If it's dropping, that
19 just tells you your pumping system isn't working as well. If
20 it's going up, you think it's working well, but it's not; it's
21 plugged.

22 MR. JACKSON: But we would expect the performance on
23 the component cooling water heat exchangers to be similar to
24 the heat exchangers that are also in that system on other
25 safety-related equipment, such as the --

1 MR. MICHELSON: Do you monitor the downstream
2 temperature at all on the service water side?

3 MR. JACKSON: I don't believe so, no. We do it
4 indirectly, but it's a mixed flow in the discharge canal with
5 other flows.

6 MR. MICHELSON: Now, did you find out when you last
7 did any kind of test on that heat exchanger to confirm that it
8 was functioning properly, and by that, I mean a real test of
9 flow measurements?

10 MR. JACKSON: We did flow measurement, I believe,
11 during the last refueling outage, which would have been last
12 summer, with special test instrumentation that was put on the
13 service water side, and of course, we are instrumented to
14 monitor on the component cooling water side. Those heat
15 exchangers are not the original 20-year-old heat exchangers.
16 They have been replaced.

17 MR. MICHELSON: They're about 10 years old now.

18 MR. JACKSON: Seven or 8 years old, I believe. It
19 was either the '82 or the '84 outage -- '84, I believe.

20 MR. MICHELSON: And you have no real biofouling
21 problem on the heat exchanger.

22 MR. JACKSON: No. We haven't seen anything since we
23 -- particularly since we have had chlorination on the service
24 water for a number of years.

25 MR. MICHELSON: That's been a number of years that

1 you've chlorinated?

2 MR. JACKSON: Yes. We instituted that -- I believe
3 it was '81 -- '81-'82 time period.

4 MR. MICHELSON: What was the reason for replacing the
5 heat exchangers?

6 MR. JACKSON: On the component cooling heat
7 exchangers, there was degradation that was occurring on the
8 surface of the tube sheet. It was, we believe, an erosion
9 mechanism, and we replaced the -- we had attempted repairs of
10 the surface tube sheet but finally replaced them.

11 One other quick question was on the fouling factor.
12 I have asked Mr. Paul Malik, who was recently with Con Edison
13 as the project manager for the stretch program, and he has also
14 been our heat exchanger project engineer for various upgrades.
15 He is now at PMX Corporation. He is consulting.

16 Paul, would you give a brief answer?

17 MR. MALIK: First, I'd like to thank you. You know,
18 this is a great honor for me to address the distinguished
19 members, who I see in the papers, the names. This is the first
20 time I'm seeing all of them. It's a really personal
21 satisfaction.

22 MR. LEWIS: Shall we assign the same credibility to
23 the rest of what you say?

24 [Laughter.]

25 MR. MALIK: Yes, Sir. No, I say that as I feel it,

1 and sometimes I get in trouble for that, but I would still say
2 it.

3 Okay. Fouling factor, as we know, is a function of
4 the water velocity and the river water conditions and
5 temperature. Originally, when the plant was designed, since
6 then the water hasn't changed. What we have done since 1982, I
7 think, approximately, we have increased the flow to the fan
8 coolers.

9 Originally, when the plant was designed, each fan
10 cooler was supposed to have 570 gallons per minute going to the
11 fan cooler, but presently, the flow through each fan cooler is
12 roughly 1,200 to 1,400 gallons per minute. So, what we have
13 done is we have increased the velocity to retard any buildup,
14 any corrosion products, or any fouling, to improve on the
15 fouling mechanism.

16 Number three is that originally, when the plant was
17 designed, we were required to have 1,600 to 1,800 gallons per
18 minute to meet the containment pressure criteria. In 1987, we
19 did the reanalysis of the containment, and presently -- and
20 that was based on 85 degrees -- we need only 1,600 gallons per
21 minute and 95 degrees. So, we have a margin of 20 percent in
22 the essential service water system for the fan coolers.

23 This gives us a great confidence that even if there
24 was a slight seasonal change in fouling, it can be easily
25 eradicated by the margin we have in the system.

1 MR. LEWIS: Thank you very much.

2 Okay. Now, I guess, we're on to hearing the
3 licensee's conclusions. Is that the state of the art at the
4 moment? After which, we'll hear the staff conclusions, after
5 which we'll come to our conclusions. They may all be the same,
6 but they may not.

7 MR. MICHELSON: Before we get to that, let me ask one
8 more question.

9 What was, again, the reason why you decided to more
10 than double your flow through the containment coolers?

11 MR. MALIK: Well, we found at that time, for many
12 reasons, that we were not -- you see, 570 gallons per minute
13 was part of the design. We are always trying to modernize and
14 improve the plant, and we felt 570 gallons per minute was just
15 not the right flow for the containment.

16 MR. MICHELSON: Apparently, then, the original design
17 basis, which was 570 gpm, I assume, or thereabouts, was found
18 to be inadequate for some reason.

19 MR. MALIK: I don't know if it was inadequate, Sir,
20 but --

21 MR. JACKSON: Perhaps I can attempt to answer that.

22 You have two flow conditions. One is the normal
23 operation flow for heat removal from containment and then a
24 significantly increased flow for accident conditions.

25 What we found in the early '80s, we felt that a

1 contributor to some of the corrosion mechanism was the reduced
2 flow, and we felt that, in addition to the other changes that
3 were made, increasing the normal flow would serve to have a
4 benefit on sweeping the coolers clean of any material that
5 might be depositing.

6 MR. MICHELSON: I don't know if you ever did tell me
7 what the bio-organism was that you thought had caused the
8 pitting attack. Do you know what it might have been?

9 MR. JACKSON: No, I don't, but I --

10 MR. MICHELSON: You apparently were upping the
11 velocity to try to sweep it cleaner, but what was bothering you
12 that you had to sweep?

13 MR. JACKSON: Well, it was a -- I don't remember the
14 specific name of the organism. I believe it was a product from
15 the metabolism of that organism that was causing --

16 MR. MICHELSON: Yes. Well, they attacked the tubes
17 and that attachment point was where it occurred.

18 MR. JACKSON: It was really attacking in a crevice
19 area, and we were seeing, I guess, minor pitting. It was not a
20 significant contributor to the other events, the erosion type
21 of attack we were seeing on the tubes.

22 MR. MICHELSON: It's enough to make you replace the
23 heat exchangers.

24 MR. JACKSON: That, in itself, would not have been
25 enough for us to replace it. The chlorination would have been

1 more than adequate to cover that.

2 MR. MICHELSON: Why did you replace the heat
3 exchangers?

4 MR. JACKSON: The heat exchangers had developed a
5 leaking mechanism. The original design had braised joints, and
6 those braised joints were subject to considerable corrosion and
7 erosion type of things.

8 MR. MICHELSON: That was the heat exchanger header
9 problem you were having. Is that right?

10 MR. JACKSON: Well, it was the heat exchanger itself.
11 The heat exchanger design had a U-bend, and the U-bend section
12 had what was typical, in those days, of an air-conditioning
13 design, a braised joint, and we replaced with a new material
14 that did not have the braised joints and have subsequently
15 improved with a different tube material. We've had two
16 replacements since that problem.

17 MR. MICHELSON: But you don't know what your
18 biofouling problem was.

19 MR. JACKSON: I mentioned it because it was a minor
20 contributor that we had some. I don't have the specific report
21 here with me to give you the name of the species, but I think
22 we could find it.

23 MR. MICHELSON: That's all right. Thank you.

24 [Slide]

25 MR. BRAM: Mr. Chairman, I'll be very brief in my

1 concluding remarks, so that we can stay on schedule or get back
2 to schedule.

3 Indian Point Unit Number 2 is being operated with the
4 utmost concern for nuclear safety. The plant is being well
5 maintained, and modernized of equipment has been ongoing
6 through various betterment programs. This includes the main
7 turbine, main generator, heat exchanger equipment, and pumps.

8 We have also, as previously described, upgraded many
9 of the FSAR analysis packages to current technology.
10 Additional equipment enhancements are planned for future years.

11 Indian Point Unit 2 is an important part of Con
12 Edison's capacity base. We are committed to excellence in the
13 manner in which we operate and maintain the plant.

14 Our corporate long-term strategic plan, in
15 coordination with the industry at large, is to extend the
16 current licensed life of the unit beyond 40 years. Stretch
17 Power is an integral part of this strategic plan.

18 Our analysis and evaluations have reconfirmed the
19 capability of the plant to perform at the original guaranteed
20 power rating of 3071.4 megawatts thermal. We are currently on
21 schedule to implement the Stretch Power escalation following
22 the upcoming outage and request your concurrence to proceed.

23 Thank you.

24 MR. LEWIS: Thank you.

25 MR. CARROLL: Are you going to comment on the dry-out

1 incident. or give us a little bit of perspective on it?

2 MR. BRAM: Well, if you'd like me to, I certainly
3 would be happy to. I might say that the incident occurred, as
4 we've discussed, a little over two years ago. I think, from
5 the point of view of lessons learned and what we have done with
6 those lessons learned, it has been a positive experience for
7 us.

8 I think that we, as a company, have always stressed
9 nuclear safety, and I think that we learned some things from
10 this event, and consequently have, over the last two years,
11 been able to make some very important, useful improvements in
12 the way we do operate the plant and the umbrella of our desire
13 for nuclear safety.

14 The actual event, as we've talked about, took place
15 over a 36-hour period. Our own investigation, which I believe
16 was supported by the NRC inspection, the AIT team, was that the
17 operators did recognize the instrumentation. It gave them the
18 indications that the generator was slowly drying out; it was
19 not that they were caught by surprise.

20 What we believe happened, however, is that they were
21 aware of the fact that the motor-driven aux feed pump was out
22 of service for maintenance. They had been given a schedule
23 that indicated that that piece of equipment was very soon to be
24 returned to service, and they fully expected that that piece of
25 equipment would be back before the steam generator actually

1 dried out. For that reason, they did not take any action
2 sooner.

3 When the piece of equipment did not return, that is
4 really when, if you want to call it at the last moment, when
5 they found themselves with a steam generator that was dried
6 out.

7 The corrective actions that we took as a result of
8 that event I think were far reaching. For one thing, we
9 recognized that we had to have additional senior management
10 involvement in plant operation, starting at my level, a vice
11 president level, and going down to the general manager level,
12 the operations manager level, right down to the actual shift
13 watch supervisor.

14 At my level -- and I might say, by the way, from my
15 point of view, this was a very interesting experience because I
16 had only been in my job for two weeks when this event occurred,
17 so it was an outstanding opportunity for me to learn every
18 detail of operation of the plant, what we do well and what we
19 don't do so well. It was also a golden opportunity to meet our
20 regional administrator under circumstances that I'd prefer not
21 to do so again.

22 But in any event, one thing that became very apparent
23 to me was that the policies that were being set by senior
24 management had to be communicated more effectively down to the
25 operating level, and I don't know of any better way to do that

1 then to get down and talk with the operators myself. So that
2 is something that I have been doing routinely over the last two
3 years. I insist that my general managers do that, and that my
4 operations manager do that regularly.

5 I, periodically, make surveillances myself of control
6 room operations, including the watch turnovers. I read the
7 logs, and, as I said, I talk with the operators to ascertain
8 what problems they have with the equipment and what their
9 concerns are.

10 I think that healthy give and take has given senior
11 management more credibility, and I think it has contributed to
12 effective communications and an understanding by all operations
13 personnel as to what our expectations are in the operation of
14 that unit.

15 We did some other very concrete things, also. For
16 one thing, although at the time of this incident we did have an
17 STA, a shift technical advisor function, that function, below
18 350, was not required to be in the control room at all times.

19 We made a change as a result of this, and the shift technical
20 advisor is now required to be in the control room around the
21 clock to provide additional technical guidance to the watch.

22 The shift watch supervisor, who is the ranking
23 authority in the control room, has also been instructed to make
24 sure that he or she does not get their attention diverted by
25 small details that might give them a loss of oversight of the

1 broader picture of what's going on in the plant.

2 We felt that, in part, during this event, the SWSes
3 on duty were involved in some of the details of the start-up,
4 and did not have an opportunity to pay as much attention to the
5 broad picture of what was going on, and might have been able to
6 handle the situation differently if they were focusing very
7 specifically on that type of -- or had that type of
8 perspective.

9 We identified some problems with log keeping as a
10 result of this event. We modified the logs themselves. We
11 felt that our watch turnover procedures could be enhanced as a
12 result of that 36-hour period, where we felt that perhaps again
13 the communications were not effective in highlighting that this
14 was a concern.

15 We have increased the number of surveillances that
16 are made by our independent QA organization. They are
17 surveilling operations functions, both during the day watch and
18 off watch and on weekends. They make surveillances of the log;
19 they make surveillances of the watch turnovers; and they
20 provide written reports to management in the plant, including
21 myself, of what their observations are of the quality of the
22 operators' work.

23 Very importantly, also what we have done is we
24 provided an additional staff group to perform pre-operational
25 planning. The purpose of this group is to review every

1 evolution of the plant, to review the procedure that is
2 applicable to that evolution, and to make a determination
3 whether or not the plant is in a condition, materially, to
4 initiate that evolution.

5 The purpose of this was to help the watch and be sure
6 that the watch personnel were not the only people making a
7 determination of whether a planned evolution could be carried
8 through effectively and properly. So this group now reviews
9 all the procedures before they're actually implemented to make
10 sure that the initial conditions are as require in the
11 procedures, and that those procedures can be implemented before
12 they actually are implemented by the watch. Then, of course,
13 the watch has the final decision as to whether or not to
14 implement that procedure, but it's been pre-checked before the
15 watch actually gets that procedure.

16 With regard to start-up procedures, one of the things
17 that we saw as a result of this event, which, again, took place
18 back two refueling outages ago, and I think it was mentioned
19 that the NRC made an inspection of our more recent refueling
20 outage startup, one of the things that we feel contributed to
21 the dry-out event was the fact that we did have equipment out
22 of service during the heat-up period, particularly that aux
23 feed pump.

24 We now require that before we reach 200 degrees, all
25 of our 350-degree holds are cleared, so that we have further

1 assurance that our plant is ready to ascend in power. Any
2 exceptions to that have to be approved by the highest levels of
3 management.

4 So we think that we put in additional lines of
5 defense, if you will. NRC, in their presentation, pointed to
6 some other things that have been done. I think the training of
7 our operators is excellent. I think the personnel that we have
8 are highly qualified to operate the plant. I have the utmost
9 of confidence in them, and I think now what we've done is close
10 the loop to make sure that senior management's expectations are
11 clearly understood and that there's adequate feedback to senior
12 management to be sure that we're achieving what we want to
13 achieve.

14 MR. WYLIE: Could I ask questions?

15 MR. LEWIS: Sure. Go ahead.

16 MR. WYLIE: In your subsequent inspections of the
17 steam generators -- I believe in '89 -- did you notice any
18 difference in the deterioration of the one that dried out
19 compared to the others?

20 MR. BRAM: In what way?

21 MR. WYLIE: Well, I don't know. Normally -- you
22 identified cracking and your girth cracks, and what have you,
23 with those steam generators. Did you notice any difference in
24 that particular steam generator and the others?

25 MR. BRAM: That steam generator is one of the two

1 steam generators that did experience somewhat more cracking
2 than the other two. We do have two steam generators that seem
3 to have more -- I'm sorry -- the steam generators that had the
4 most cracking were Steam Generators 22 and 23. I don't know
5 that we saw any change, significant change, though, in that
6 steam generator.

7 Charlie, do you recall offhand whether we saw any
8 significant difference?

9 MR. JACKSON: No.

10 MR. BRAM: I don't believe so.

11 MR. WYLIE: You purchased four replacement steam
12 generators, I believe.

13 MR. BRAM: That's correct.

14 MR. WYLIE: What are your plans for them?

15 MR. BRAM: Well, right now, those four steam
16 generators are in storage. We have no specific plan to install
17 those four steam generators, but they are available in the
18 event that our evaluations would suggest that it's justified to
19 install them. Right now, we do not believe that there is any
20 immediate need to make that installation.

21 MR. WYLIE: Thank you.

22 MR. LEWIS: If there are no further questions, then
23 thank you.

24 MR. CARROLL: Well, I did want to follow up on one
25 other thing: the extent to which you're really looking at the

1 design to make sure that this ancient plant -- that there
2 aren't some glitches in the design, the SSFI kind of look.

3 MR. BRAM: Well, I think it was mentioned that there
4 have been several SSFIs already undertaken. I believe three or
5 four have actually been completed. I don't recall offhand the
6 schedule, but there are more that are planned in future years.

7 MR. CARROLL: By Con Ed?

8 MR. BRAM: Yes, by Con Edison.

9 MR. CARROLL: Have you looked at electrical systems?
10 That seems to be a place people are finding --

11 MR. BRAM: Yes, we did. Last year, in 1989, we
12 undertook an SSFI of our electrical systems.

13 MR. CARROLL: And did that turn up anything
14 startling?

15 MR. BRAM: Nothing startling. There were some
16 enhancements that we made as a result of it, and we are doing a
17 walkdown of our electrical systems, which will be a multi-year
18 program, to make sure that we're satisfied that we understand
19 the design basis of those systems.

20 MR. CARROLL: Okay.

21 Moving on to maintenance, do we need a maintenance
22 rule to help you understand how to maintain your power plant?

23 MR. BRAM: I think not. I think we and others in the
24 industry know how to maintain our power plants. I think that
25 there are many examples of initiatives that have been

1 undertaken in the industry, certainly by Con Edison.

2 I think, in some respects, a maintenance rule might
3 just divert our attention from what we're otherwise doing. I
4 think we have a sense of responsibility, and we want to
5 maintain those plants as well as the NRC does.

6 MR. CARROLL: To the extent that the NRC found some
7 negative things about your maintenance program in their
8 maintenance team inspection, have those previously been
9 identified by you and your self-assessment and by INPO?

10 MR. BRAM: Yes to all of that. The findings of the
11 NRC inspection team really were very similar to the findings
12 that we had made in our own self-assessment towards the very
13 end of 1987. We had identified eight points in our self-
14 assessment. Those points, in fact, were shared with the
15 maintenance inspection team when they came into the plant.
16 They've also been shared with INPO, and certainly the NRC and
17 INPO are in agreement with our own findings. That, in effect,
18 was, in large part, reflected in the NRC inspection report.

19 MR. CARROLL: So the problem is a matter of time to
20 implement things as opposed to basic flaws in the program?

21 MR. BRAM: Yes, it is a question of timing.
22 Actually, we had intended to -- first of all, let me say this.
23 We have already, in many respects, implemented corrective
24 actions that we had identified and that the NRC staff had
25 identified in the self-assessment and in the maintenance

1 inspection.

2 There are more to be done. We have a very detailed
3 program that we have put down in writing. When Bill Russell
4 was up to visit us about two months ago now, we presented a
5 part of that program to him, and we are planning to sit down
6 with the staff in large to go into more detail. Some of that
7 has already been implemented, and you can see very definite
8 improvements in the plant already.

9 MR. LEWIS: Thank you very much, Mr. Bram. I
10 appreciate it and I think we'll now go on. I don't know who's
11 going to speak for the staff. If I could beg and plead for the
12 staff to try to hold itself to 30 minutes including our nasty
13 questions, it would be a tremendous help.

14 MR. CARROLL: I thought we were being kind and gentle
15 today.

16 MR. LEWIS: Indeed we are. We tend to get kinder as
17 lunch approaches.

18 Please go on.

19 MR. BRINKMAN: Thank you, Dr. Lewis. There are three
20 speakers left for the staff presentation, about 10 minutes a
21 piece. We'll try to move along and maintain your schedule.

22 The staff in its safety evaluation and in its review
23 of this application confirmed that the plant was in fact
24 designed as the licensee has stated for the core power level,
25 3071.4. We also looked at the original license application and

1 determined that the original operating license was requested at
2 2758. There was no technical reason for the derate. It was
3 simply as was stated, to gain experience at the higher power
4 levels than the previous plants.

5 In our 1970 safety evaluation report, the staff
6 evaluated all the engineered safety features except the ECCS
7 system and we did the environmental reviews. They were all
8 done at 3216 and it was reported as such in the original safety
9 evaluation. The state of the ECCS system was at 2758.

10 [Slide.]

11 MR. BRINKMAN: In our current safety evaluation, we
12 looked at the core design and determined that yes, the core is
13 adequate to perform at the 3,071.4 megawatt level. The
14 licensee performed all the applicable FSAR Chapter 14 -- they
15 were not in standard format but they did perform all the
16 Chapter 14 events and the staff confirmed that the results are
17 acceptable and they're bounded by the LOCA analysis.

18 We looked at ECCS performance which Tim Collins will
19 give a further presentation on here in a few minutes. We
20 looked at overpressure protection, determined that it is
21 satisfactory. We looked at the anticipated operational
22 occurrences. Their results are acceptable. We looked at non-
23 LOCA events. Found them to be acceptable. We reviewed the
24 auxillary feedwater and residual heat removal performance. We
25 determined that with the increased flow in the auxillary

1 feedwater system, it is acceptable.

2 We looked at the reactor coolant system to assess the
3 stress and fatigue usage factors. We found them to be
4 acceptable at the stretch power conditions. We also reviewed
5 the containment integrity analysis. The original design
6 pressure of the containment was 47 p.s.i. For the stretch
7 power, we found the LOCA analysis to be bounding, 40.31
8 p.s.i.g. for the stretch power with the NSSS rating of 3,083.4.
9 We found it to be 41.12 at the design level of 3216 megawatts.
10 We looked at the analysis for containment integrity for the
11 main steam line break. We found that it was bounded by the
12 LOCA and for main steam line, we reviewed the calculation for
13 39.99 at the stretch power conditions.

14 MR. CARROLL: What's the pressure go to if one wants
15 to postulate a catastrophic failure of the steam generator
16 shell that takes with it the tube bundle which is a combination
17 of those two.

18 MR. BRINKMAN: I don't believe we have any of that.
19 Bob Herman, do you have anything to offer on that?

20 We have not analyzed that.

21 MR. MICHELSON: Have we not analyzed the blowing out
22 of the manhole cover plate which is about how you would get
23 into it, for instance, in a more easy fashion.

24 MR. CARROLL: No, I want to rupture the primary and
25 secondary side.

1 MR. MICHELSON: Yes, okay. You want to get the whole
2 thing. Well, there must be cover plates on the secondary side
3 too; aren't there?

4 MR. CARROLL: Oh, yes.

5 MR. BRINKMAN: There are manways on the secondary
6 side.

7 MR. MICHELSON: I know there's a manway on the
8 primary side, too.

9 MR. CARROLL: I'm having the girthwell failure
10 somehow or other.

11 MR. MICHELSON: That's an incredible failure.

12 MR. CARROLL: Oh, it is.

13 MR. MICHELSON: No, it's not a design basis failure.

14 MR. CARROLL: I understand.

15 MR. BRINKMAN: We have not analyzed that.

16 MR. CARROLL: It might be just twice.

17 MR. MICHELSON: I thought the manways had been
18 analyzed but I guess not. On PWRs, you've never looked at the
19 manway -- the cover plate blowing off?

20 MR. BRINKMAN: I don't believe we have. Does any of
21 the staff have anything on that?

22 I don't believe we have. We also looked at the
23 balance of plant systems including the steam turbine system
24 with its -- the main steam system, the feedwater condenser, the
25 condensate systems, circulating water systems and the rest of

1 their support systems and determined that they are adequate for
2 stretch power conditions.

3 We've talked about the service water system. We
4 looked at the essential service water, the non-essential
5 service water and determined it has adequate capability for the
6 stretch power conditions. We looked at diesel generators.
7 They have adequate capacity to support the stretch power. The
8 auxillary feedwater system ends up with a slightly higher flow
9 here but we've already analyzed it for the full flow of the
10 capability of the pumps. So that was enveloped.

11 We looked at POP piping systems and determined they
12 are satisfactory at the stretch conditions as well as the steam
13 generators. The steam generators -- Bob Herman will give a
14 further presentation on that in a few minutes dealing primarily
15 with the cracking phenomenon that has been observed at Indian
16 Point in the steam generators.

17 We looked at environmental qualification of the
18 equipment and determined that the licensee did evaluate the
19 effects of the stretch power and the equipment qualification
20 and confirmed that the equipment in the EQ program is qualified
21 for the temperature, pressure and radiation levels
22 corresponding to the harsh environments which could be involved
23 with a pipe break condition.

24 We reviewed the plant instrumentation and confirmed
25 that no changes in plant equipment are required. The licensee

1 is using approved methodology for calculating set point
2 changes. We then reviewed the set point changes for true
3 channels in some detail, the overpower Delta-T and the
4 overtemperature Delta-T channels and we confirmed that the
5 potential uncertainties have been properly considered.

6 We also looked at the environmental consequences of
7 the power increase. The original environmental statement
8 assumed a power level 3216 which bounds the proposed stretch
9 power level of 3,071.4 megawatts thermal. We reviewed one of
10 the accident analysis in the application for the steamline tube
11 rupture accident and confirmed that the off-site doses remained
12 well within the acceptance criteria of standard review plan
13 15.63.

14 The licensee's reassessment of the radiological
15 consequences do not alter the conclusions stated in our
16 original safety evaluation. They're well within the Part 100
17 guidelines.

18 MR. CATTON: If everything looked so good at 3216,
19 why aren't they asking for more than 10 percent?

20 MR. BRINKMAN: I'll ask the licensee to respond to
21 that.

22 MR. JACKSON: The original contract guarantee point
23 was at the 3083 and that's the level that we're proposing to go
24 to but we're not foreclosing subsequent analysis after
25 experience at that level to go and ask the staff for increase

1 to higher levels, whether it's 3216 or 3250, which is where I
2 guess the similar generation plants are operating now but we
3 picked the design point of the 3083 for this phase of an
4 upgrade.

5 MR. CATTON: Sounds good to me.

6 MR. BRINKMAN: We've evaluated their request at the
7 current 3,071.4 and these are the conclusions we have come to.
8 They've certainly indicated they may request higher at some
9 time in the future. We looked at the requested technical
10 specification changes changing the value of rated power from
11 2758 to 3,071.4, would be accomplished in a change in the
12 definition of rated power in the tech specs and changed the
13 allowable Tavg in the limiting safety system settings, trip
14 settings, and in the LCL set points and would require an
15 increase in the minimum required auxillary flow rate to 380
16 gallons a minute. We agree with that change.

17 To be consistent with the fuel handling accident in
18 containment, we would increase the fuel handling rate down to
19 174 hours.

20 Now I'd like to ask Tim Collins to come up and speak.

21 MR. MICHELSON: Before you leave though, I have a
22 question. You told me about all the kinds of things you looked
23 at in the process of reviewing this situation so let me ask
24 you, did you look at the operating history of this plant for
25 the last five years or so from the viewpoint of events that

1 might have occurred that would be power-related for which you'd
2 like to assure that appropriate corrective actions have been
3 taken. So maybe you could tell me to what extent you've
4 reviewed the licensee event report history on this plant for
5 let's say the last five years to make sure that there haven't
6 been events for which you might have some concern.

7 MR. BRINKMAN: I did not review them as part of this
8 application per se, Dr. Michelson. However, I'd do that as a
9 routine function in my position as project manager. I receive
10 the licensee event reports. I review them. I have been in
11 this position for about the past year. I do not recall any in
12 the past year.

13 MR. MICHELSON: A year is fairly short.

14 MR. BRINKMAN: Yes, it is.

15 MR. MICHELSON: Well, did you ask, for instance, AEOD
16 to give you a computer printout of certain kinds of things that
17 might have occurred at Indian Point for the last five years?

18 MR. BRINKMAN: I did not.

19 MR. MICHELSON: Isn't that kind of what you would
20 want to do to find out if there's anything in the operating
21 history? We've looked at the paper. The paper looks good.
22 The computations look good. How's the plant really working and
23 have you asked at all or asked somebody else to look at or does
24 AEOD -- wouldn't they normally respond to a request from NRR
25 asking, give us a quick run-down on the operating history of

1 Indian Point II for the last five years. They'd give you some
2 computer printouts and so forth and categorize the LERS
3 according to the kind of events that have been occurring.

4 This is all automatically done on the sequence coding
5 and search system. All you have to do is look at the output
6 and decide if there's anything there that raises an interest.

7 MR. CAPRA: No, sir. We have not gone back to AEOD
8 and asked them to do that in that methodological of a manner.

9 MR. MICHELSON: This isn't very much work for them,
10 you know. It's all on computers. It's got to be used, of
11 course, in order to be useful but it's all there and very
12 easily searchable in a number of different ways. Just for my
13 own curiosity this afternoon I'm going to ask them to give me
14 the biofouling printouts for the last five years. It's
15 something that's very easy for them to do. I know who to call
16 and in about two minutes they'll come back and tell me how many
17 hits there are and if you want the details, they'll print it
18 out or give you categorizations of them or whatever, just as an
19 interesting example.

20 I would have thought that the staff in the process of
21 reviewing any application of this sort would inquire at least a
22 little bit into how the plant's been operating as well as
23 whether the papers are all in order.

24 MR. CAPRA: In NRR we do keep up on a day-to-day
25 basis, with plant operations through the region. You are

1 correct, we had not gone and listed specific LERs.

2 MR. MICHELSON: See, unfortunately, it is, you get
3 hit so much by the day to day things that you kind of lose
4 sight of what happened a year ago or two years ago that might
5 be very important from the viewpoint of if you increase the
6 power level, it might have been more of an aggravation than it
7 was at the time. So it looks like it is a kind of a tidy
8 check. As long as we are doing all these other good checks,
9 why don't we ask how the plant has been operating?

10 MR. CAPRA: Yes, sir. Like I say, we have not done
11 it in the method that you have so described, but we certainly
12 participate, along with the region, in, you said we sometimes
13 get caught up in the day to day events. We do go back, on a
14 periodic basis, and review overall licensee performance on a
15 periodic basis through the SALP process, which both us and the
16 region have participated in. But we certainly go into a lot of
17 detailed reviewing, all LERs and all events.

18 MR. MICHELSON: They are viewed at that time from a
19 somewhat different interest viewpoint. You are more interested
20 in the process now and how well is the process working. And
21 that is important, too. But in this case I am interested in
22 how well the mechanical equipment has been functioning,
23 particularly as it may be related to increases in heat output.

24 MR. CARROLL: Related to that, do you look at NPRDS
25 to see if there is anything in there that suggests that there

1 may be problems with higher thermal output?

2 MR. CAPRA: No, sir. We haven't looked at NPRDS
3 specifically related to this power increase.

4 MR. MICHELSON: There is a couple of obvious ones.
5 One is the containment heat exchanger. I can pull that out of
6 NPRDS and see what kind of maintenance record it's had, what
7 kind of problems it has had, and so forth, without asking the
8 utility, which is important to ask, too, but usually you like
9 to kind of search out a little bit so you know which questions
10 to ask. And it depends on how thorough you want to do the job.
11 If it is a 2 percent power increase, I wouldn't be overly
12 thorough. Ten to 12 percent, which I think this is in that
13 range, begins to get more interesting.

14 MR. CARROLL: The utility did look at these kind of
15 things.

16 MR. JACKSON: Yes, we have looked at these. The
17 performance of equipment, specifically reliability issues
18 associated with NPRDS data base. We have an expanded system
19 engineer program at the plant and one of the functions of a
20 system engineer in this particular system is to specifically
21 review history, both of the maintenance experience, any failure
22 history, as well as be cognizant of problem areas that exist
23 for that system, for example, where members of the EPRI SWAT
24 program on service water, and our system engineer routinely
25 exchange information. We are keeping up to date with our data

1 entry in that system. And we routinely use that for
2 evaluation.

3 MR. CARROLL: Now, Joe's system engineer on the
4 feedwater system specifically asked himself the question, does
5 10 percent more feedwater flow look like it is going to cause
6 some grief with the existing equipment?'

7 MR. JACKSON: Yes. He will specifically look at that
8 in part of his training, which is now, that was one of the
9 first areas of training that had been reinitiated, was the
10 system courses. And the system course training has been
11 modified to include the additional stretch areas. Things, for
12 example, in the secondary plant, in the condensate system, the
13 drains, the feedwater system, we have directed by our system
14 engineer an ongoing program looking at erosion, pipe thinning
15 problems associated with high flow. We predict, we inspect and
16 predict areas where we might approach a minimum wall thickness
17 and schedule future corrective action, whether it be additional
18 inspection or replacement of equipment, based upon that
19 history.

20 It is the intent of the additional people, after they
21 have been through their training, to routinely monitor these
22 activities, be on top of it, anticipate.

23 MR. MICHELSON: You don't need to search your
24 database, of course, you generated it, and you are the
25 originators of the LERs.

1 MR. JACKSON: That is correct.

2 MR. MICHELSON: And you certainly ought to be aware
3 of your own. I assume you look at Indian Point 1 and 3 as
4 well.

5 MR. JACKSON: Well, yes, certainly. And we have
6 cross membership on various safety committees and many of the
7 people at Unit 3 are former ConEdison employees. There is a
8 considerable exchange of experience at the site.

9 MR. MICHELSON: I didn't want to indicate in any way
10 that I didn't think you were looking at it thoroughly. I just
11 thought that the staff ought to be aware of this because they
12 have to look at it from a little different viewpoint. And this
13 is a check and balance process, anyway. And therefore, their
14 view is important as well as yours, of the same information.

15 MR. BRINKMAN: Anything else?

16 [No response.]

17 MR. BRINKMAN: All right. Mr. Collins.

18 [Slide.]

19 MR. COLLINS: My part of the presentation today is
20 the review that the staff did on the ECCS system.

21 Basically, there are two parts to the review that we
22 did. The first one I call the "system overview." It is kind
23 of a broad look at the system to see if there is anything
24 particularly different about it, relative to other plants.

25 We also looked at the original design rating of the

1 pumps in the system to see if the licensee was trying to
2 squeeze more out of them than they were originally designed
3 for.

4 We look at the s see how many high-pressure pumps,
5 low-pressure pumps are in the ECCS, and compare it to other
6 plants of similar size and similar design.

7 The second part of the review is really the LOCA
8 analysis part, it is a performance analysis. And in this part
9 of our review, we look at the methods used by the licensee to
10 make sure we have approved them for the application that they
11 are using them; the scope of their analysis; we verify that the
12 inputs are consistent with the Appendix K requirements and that
13 the technical specifications bound the analysis inputs; and
14 then we just check to see that the results are consistent with
15 the ECCS rule and any other Appendix K requirements.

16 [Slide.]

17 MR. COLLINS: As far as the system overview goes, the
18 original system design was for 3216 megawatt plant, so we
19 concluded there was no squeezing of any of the ECCS components
20 as far as the power upgrading went.

21 The configuration is four accumulators, one on each
22 cold leg. He has injected about 600 psi. And they are
23 designed such that three of the accumulators will supply enough
24 water to basically cover the core halfway with no other
25 injection.

1 Three high-head safety injection pumps. Each one,
2 they injected about 1700 psi, and about 400 gallons a minute is
3 their design flow.

4 There are two RHR pumps which act as part of the
5 safety injection system. They are 3,000 GPM pumps. They
6 injected about 600 psi.

7 And then there are two recirculation pumps which draw
8 on the emergency sump and they have a 3,000 GPM capability, and
9 they deliver about 250 psi.

10 Basically, it is a typical mix of subsystems, high-
11 and-low-pressure systems, and typical capacity for a plant of
12 3,000, 3,200 megawatts.

13 [Slide.]

14 MR. COLLINS: As far as the performance analysis
15 goes, for the large breaks they use the BASH system of codes,
16 which is the standard Westinghouse ECCS methodology for large
17 breaks.

18 They use the NOTRUMP code for small breaks. Same
19 thing, the standard approved methods.

20 The scope, they reviewed the full break spectrum and
21 verified the size of the break, single failure considerations.

22 For inputs, they used 102 percent of the 3071.4
23 megawatts that they are asking for; 102 percent of peak linear
24 power. They assumed a lot more steam generator tube plugging
25 than they have experienced. I think their experience is like 8

1 percent, but they have put in a lot of margin by assuming 25
2 percent plugging. And they used all the required Appendix K
3 inputs.

4 The results, they have already discussed, large break
5 is 2039 and the small break was 1218, and the criterion is
6 2200.

7 MR. MICHELSON: When you redid the analysis, did you
8 change the setpoint on the accumulator injection?

9 MR. COLLINS: I don't -- let's see if they changed it
10 or not --

11 MR. MICHELSON: Did your analysis show you needed to
12 change the pressure injection point for the accumulators?

13 MR. COLLINS: The Setpoint. Lou --

14 MR. JACKSON: Lou Liberatori, I think, can address
15 that specifically.

16 MR. LIBERATORI: Yes. As part of the reanalyses,
17 Westinghouse did some sensitivity runs upfront to in effect
18 fine-tune the accumulator. So there is a different water
19 volume now. And I believe we increased the overpressure about
20 15 pounds. I think it was from 500 to 615, within the
21 capability of the accumulator. So we did finetune the
22 accumulator to get the maximum benefit from it.

23 MR. MICHELSON: All right. Thank you.

24 MR. WARD: But Lou, you finetune that, then, to --
25 these are so-called evaluation model calculations. You had the

1 option of going to best estimate model analysis. You didn't do
2 that. I guess I understand why. But how do you feel about
3 finetuning the instruments, or the systems, to an artificial
4 analysis rather than to best estimate of the plant behavior?

5 MR. LIBERATORI: Westinghouse, correct me if I'm
6 wrong, but I don't believe the best estimate evaluation model
7 has been approved yet for four-loop plants. So we could not
8 use the best estimate model. And in fact, we may very well use
9 that for future considerations.

10 MR. JACKSON: I would like to add to that answer. We
11 are currently working with Westinghouse and EPRI on an R&D
12 project to use Indian Point II as a model for a four-loop best
13 estimate plant. So that is why I hedged a bit on future
14 uprates. There is the potential with the results from a best
15 estimate model after review, and if accepted by the staff, to
16 proceed further. But we are currently evaluating and we will
17 be doing the analysis over the next approximately two-year
18 period.

19 [Slide.]

20 MR. COLLINS: Our conclusions were that the component
21 design rating had not been changed for the original rating.
22 Where the component design rating hadn't been changed for the
23 upgrade, they had used approved analysis methods for all their
24 analyses; that the scope of the analysis was in compliance with
25 the Appendix K requirements. The inputs and results satisfied

1 Appendix K and 5046, and we see that ECCS is acceptable for
2 operation at the 3071 megawatt level.

3 [Slide.]

4 MR. HERMANN: Good morning. My name is Bob Hermann.
5 I'm the Staff Section Leader in Materials Engineering. I've
6 come to talk about the girth weld cracking, both at Indian
7 Point, and we're going to talk a little bit generically about
8 girth weld cracking.

9 With regard to actions to date, the problem started
10 back in the 1982 timeframe with a leak at Indian Point through
11 the shell. The staff has put out information notices 8237,
12 8565 and 9004, Indian Point 3 problems and Indian Point 2 and
13 Zion problems. I think what I'd like to do next is to put up a
14 slide of Model 44 Generator, so you get an idea of where things
15 are in the generator.

16 [Slide.]

17 MR. HERMANN: The girth weld we're talking about is
18 right here. The feed water ring is right here, and you can't
19 see it in this one but I'll show you in a later slide that
20 there's a baffle plate down in this area, too. I just wanted
21 to give you a feel for where things are in the generator.

22 You have an area of discontinuity in the shell and an
23 area of cold water impinging on the shell down in this area.

24 MR. CATTON: Is this thermal fatigue, then?

25 MR. HERMANN: It's a combination, but we'll get

1 there. I just think what I will do then is, before I get into
2 the discussion of overall experience, let me put up the other
3 slide and make things a little easier.

4 [Slide.]

5 MR. HERMANN: Here is the girth weld on the
6 generator. There was a downflow comer resistant plate with
7 some holes in it at this area. The feed ring is up here and
8 cold water was impinging in this area and the mixing area down
9 around the girth weld.

10 MR. MICHELSON: How does the water come out of the
11 feed ring in your plant?

12 MR. HERMANN: I believe, through the J-tubes.

13 MR. MICHELSON: You've got standard J-tubes on the
14 outside?

15 MR. HERMANN: Yes.

16 MR. CARROLL: They're on the outside of the ring?

17 MR. HERMANN: Let me put it back up for you. Yes,
18 they are; aren't they? I believe they're outside of that
19 wrapper. There's a wrapper riser barrel wall.

20 MR. CARROLL: Okay, so they loop over the top of it;
21 is that what you're saying?

22 MR. HERMANN: Yes.

23 MR. CATTON: Is it insufficient mixing?

24 MR. HERMANN: It's an area that -- well, let me get
25 to the mechanism in a minute. I just wanted to give you a

1 little bit of an idea of what things look like first.

2 Everybody always likes hardware.

3 [Slide.]

4 MR. HERMANN: The experiences with cracking have been
5 four domestic plants, one foreign plant, Models 44 and 51
6 generators. The cracks have ranged from severe to isolated and
7 as I said earlier, Indian Point Unit 3 had a through-wall leak.
8 I guess the experience in Indian Point 2 was comprehensive NDE
9 done after the Indian Point 3 cracking.

10 Original repairs of some cracks were done in the Fall
11 of 1987. I believe that was done between refueling outages 8
12 and 9. A year later, -- well, from the Fall of '87 to the
13 Spring of '89, they came back and took another look and there
14 were fairly severe cracks that had returned. I'm going to put
15 up a slide of the cracking that was found at the two outages.

16 [Slide.]

17 MR. HERMANN: Correct me if I'm wrong, but it was the
18 generator that dried out 23?

19 MR. KELLEY: Yes.

20 MR. HERMANN: These are the results for '89 and '87.
21 The most severe cracking was in Generator 22 and not 23. I
22 believe what the second most significant cracking was 23 or 24,
23 Martin?

24 MR. KELLEY: 23.

25 MR. HERMANN: 23 was second. The earlier cracks; I

1 guess the maximum crack in depth in '87 was on the order of a
2 little over an inch and in 1989, one area was up to an inch and
3 a quarter, and this was in one cycle's operation.

4 MR. CARROLL: The wall thickness is?

5 MR. HERMANN: It started around 3 and a half inches,
6 I believe.

7 MR. CATTON: What are those?

8 MR. HERMANN: Those are the cracks that were removed
9 by grinding -- the crack depths.

10 [Slide.]

11 Failure mechanisms; and this is probably --

12 MR. MICHELSON: Typically, how long were the cracks,
13 if they were one and a half inches deep?

14 MR. HERMANN: Some of them -- they were fairly well
15 around the circumference. They were separated by five or six
16 inches or something like that.

17 MR. MICHELSON: They weren't that deep all the way
18 around; were they?

19 MR. HERMANN: No.

20 MR. HUM: On Steam Generator 22, there is essentially
21 a groove the entire circumference.

22 MR. MICHELSON: At a depth of 1.42? That's Zone 7.

23 MR. HUM: The groove was established in '87 and they
24 are not at that depth. That is a low grind out. Bob will talk
25 later about that.

1 MR. MICHELSON: That's about an average of at least a
2 half to three quarters of an inch, though.

3 MR. CARROLL: It would help, I guess, if we knew what
4 the zones meant, or generally what they meant.

5 MR. HERMANN: If the licensee would help me on the
6 zones, I believe they were areas that the just picked for
7 identifying where the cracks were.

8 MR. CARROLL: Around the circumference?

9 MR. HERMANN: Yes, circumferentially around it.

10 MR. JACKSON: We have a representative from
11 Westinghouse and steam generators, Al Vaia.

12 MR. VAIA: Al Vaia, Manager of the Secondary Steam
13 Generator Service Group. Basically for the zones, we divided
14 the circumference of the steam generator into 12 equal zones.
15 This was done from a logistics point of view in order to
16 monitor where cracks were so that from a data point of view, we
17 could continue to monitor where the cracks were.

18 The different zones; basically it's a 50-inch
19 increment. Each zone is approximately 50 inches in length, and
20 there are 12 around the circumference. The cracks that were
21 found were basically a number of cracks associated with pits.
22 Some of the cracks did connect, so the plot that Bob showed
23 there was the maximum depth in any one zone.

24 It was not an indication that the crack was 360
25 degrees continuously; they were at different planes within each

1 of the zones.

2 MR. CARROLL: So, roughly how long was a given crack?
3 How long might it be?

4 MR. VAIA: Well, some of the grind out areas may have
5 been as long as 5, 6, 7, 8 inches, but that could have been
6 made up by a number of short cracks which had connected and
7 during the grinding operation -- they may have connected, or
8 during the grinding operation, that was the total length of the
9 excavation.

10 MR. CARROLL: When I see for Zone 7, 1.42 and for
11 Zone 8, 1.38; that doesn't imply that for 100 inches around the
12 circumference, I've got a crack?

13 MR. VAIA: No, it doesn't. Also, between the '87 and
14 the '89 results, that is not necessarily the same location.

15 MR. MICHELSON: It's the same zone, though?

16 MR. VAIA: Yes, it's the same zone.

17 MR. MICHELSON: The zones were the same in the two
18 cases; isn't that correct?

19 MR. VAIA: Yes, we kept the same zone and the
20 identification from '87 was maintained for '89 and will be
21 maintained for all future inspections.

22 MR. HUM: I would like to point out that in the SCR,
23 there is -- references a topic report that shows the length and
24 depths of all grind outs, and what I was trying to emphasize
25 about the '87 results was that, as a result of the grinding sa

1 portrayed in this slide, there is a groove that is essentially
2 around the entire circumference. That's not suggesting that
3 this was one continuous crack. Obviously, they started and
4 stopped. But I would also point out that I think that some of
5 the cracks were quite long.

6 MR. MICHELSON: They were all well repaired back to
7 the original surface, weren't they?

8 MR. HERMANN: No.

9 MR. MICHELSON: No? How much -- what's the condition
10 presently, then, of this groove?

11 MR. HERMANN: I believe the first time the first time
12 that the repairs were done on the plant in the '87 outage,
13 there wasn't any welding done, so what you had looked at,
14 especially in Steam Generator 22, were the depths of the grind
15 outs and the zones as show up on the plot.

16 There were different profiles on the grind outs with
17 tapers on them, so people didn't necessarily large stress
18 razors in the area. It just wasn't somebody went in there with
19 a pencil grinder and, you know, ground out a crack locally; it
20 was an engineered grinding situation where they had specified
21 tapers and so much allowable at the bottom.

22 MR. MICHELSON: And you filled in a portion of the
23 depth and left the rest of it?

24 MR. HERMANN: No. In 1989, there was --

25 MR. MICHELSON: Well, in '87 you must have done that,

1 because in '89, the depth was less than it was in '87 in some
2 cases. So you must have done some filling.

3 MR. HERMANN: In some cases, but I believe the
4 numbers you're looking at were probably numbers that may have
5 been down in an area where there was a groove, so the actual
6 well thickness could have been less in 1989 than it was in '87.

7 MR. VAIA: Yes. During the '87 evaluation, the
8 various repairs were analyzed relative to the pressure
9 integrity of the steam generator and also from a fatigue point
10 of view. The area where you saw the 1.07 was a local grind-out
11 area where we analyzed for one-inch uniform groove 360 degrees,
12 and as part of the analysis, we superimposed a small local area
13 on that location. So in 1987, there was no repair done of the
14 steam generator, and that was based on the design and fatigue
15 analysis that was performed.

16 In 1989, one steam generator, Steam Generator 22,
17 because of the overall depth of the indications, there was a
18 well repair performed, and all of the grooves were restored to
19 a condition that was three-quarters of an inch, was the maximum
20 depth left in Steam Generator 22 after the '89 repair.

21 MR. CARROLL: But the numbers in the table are
22 before-repair numbers?

23 MR. VAIA: Yes, they are.

24 MR. CARROLL: So what Carl is saying is how can Zone
25 9 go from 1.01 in '87 down to .53 in '89?

1 MR. VAIA: That's a different location, and what is
2 shown there is the maximum depth in '89 at that location. MR.
3 MICHELSON: The 101 was still there --

4 MR. VAIA: One-oh-one was still there.

5 MR. MICHELSON: Okay.

6 MR. VAIA: The new indication in 1989 had a maximum
7 depth of .58.

8 MR. MICHELSON: It's another groove they dug, but new
9 cracks.

10 MR. VAIA: Those were new cracks, yes.

11 MR. MICHELSON: Those were new cracks that were
12 removed.

13 MR. VAIA: Yes.

14 MR. MICHELSON: Okay.

15 MR. CARROLL: Very unclear table.

16 MR. WYLIE: Twenty-two is the steam generator that
17 dried out?

18 MR. HERMANN: No, it's not.

19 MR. WYLIE: Twenty-three.

20 MR. HERMANN: Twenty-three was the generator that
21 dried out.

22 [Slide.]

23 MR. HERMANN: Back to the discussion of the
24 mechanisms. The mechanisms that are being postulated to date
25 are corrosion assistant fatigue. This is not only true at this

1 unit, but at some other units where people have done
2 metallography to identify the mode of failures. In cases,
3 there has been pitting in the generators, small cracks coming
4 out of the bottom of the pits, and then thermal transients
5 which are driving the cracks.

6 The other thing that's dependent, probably, on the
7 crack growth rate is the -- well -- it is -- is the severity of
8 the thermal cycling and the aggressiveness of the environment
9 in terms of things like oxygen and alloys, contaminants like
10 copper.

11 One of the other things that was being discussed with
12 regard to Indian Point, originally, these were field stress
13 relieved units, and there were some questions regarding the
14 lower fabrication heat treatment. I don't really think that
15 went anywhere in terms of the cracking mechanism.

16 The other issue that was thought to aggravate the
17 situation at Indian Point was the downcomer location, and I'll
18 put that slide back on again.

19 MR. LEWIS: Could I just interrupt for one second to
20 say something about time? We really are running out of time
21 because there is another subcommittee meeting here at one
22 o'clock. Some of these people have to get out and have lunch.
23 Otherwise, they'll be grumpy at one o'clock.

24 MR. HERMANN: I'll try to hurry up.

25 MR. LEWIS: So let's roll it off.

1 MR. HERMANN: Okay.

2 [Slide.]

3 MR. HERMANN: Anyway, the area that probably got
4 aggravated by the thermal problems was because of the plate
5 being right here. It tended to have the aux feed water splash
6 up against the hot shell. During the transience, water level
7 goes down, and it'll be filled with cold feed water.

8 [Slide.]

9 MR. HERMANN: Generically-corrective actions to date:
10 Repairs were by grinding to establish profiles, which we talked
11 about before with the tapers; well build-up and post well heat
12 treatment of deep flaws; final excavation MP and mapping of the
13 excavations; the downcomer plates have been removed.

14 MR. CARROLL: They were there originally to minimize
15 carry over right?

16 MR. HERMANN: The downcomer flow resistance plates?
17 I believe they were put in and taken out a couple of times for
18 various and sundry reasons. They were in there for vibration
19 purposes at one time.

20 MR. JACKSON: I'll try to answer that. They were
21 there for control of the recirculation ratios stability
22 control.

23 MR. CARROLL: So it's okay to take them out? No
24 problems?

25 MR. JACKSON: Westinghouse has analyzed the

1 sensibility of removing them and have given us an Okay on that.

2 MR. HERMANN: The other things that have been done is
3 water chemistry has been improved and flow conditions have been
4 changed to try to minimize how much cold water is slugged up
5 against the shell. Heat exchangers and other things have been
6 replaced to get copper out of the system. I believe there is
7 still some copper in the sludge in the generators, but they are
8 trying to minimize that.

9 The last item --

10 MR. CATTON: Is their condenser copper?

11 MR. HERMANN: I believe it was before, but it's been
12 replaced, I think.

13 MR. JACKSON: The condenser tube material --
14 originally Admiralty. We are in a phase change-out, and in the
15 upcoming refueling, we will replace out one-third of the
16 condenser and we will continue our replacement after that.

17 MR. CATTON: Replacing it with what?

18 MR. JACKSON: Titanium.

19 MR. CARROLL: Do you have polishers?

20 MR. JACKSON: No, we don't.

21 MR. CARROLL: And the feedwater heaters were copper
22 alloy?

23 MR. JACKSON: The feedwater heaters were originally
24 copper. They've been changed out. The only remaining
25 feedwater heaters are those in the condenser neck at the very

1 lowest low pressure. The moisture separator reheater tube
2 bundles have also been changed out.

3 MR. HERMANN: The last item on here is "Replaced
4 Steam Generators at Indian Point." There have been other
5 people that have replaced generators that have had this
6 problem. They are available at Indian Point.

7 [Slide.]

8 MR. HERMANN: The last slide is the possible generic
9 future actions. Examination of these areas, we believe, can
10 probably be done reliably now with ultrasonics from the
11 outside. We've just had some early results from Zion where
12 they're finding pretty shallow cracks and they've confirmed
13 those depths in the last outage when they ground them out by
14 MT, so it looks like UT is good a good tool in this case to be
15 able to find this kind of cracking.

16 The code rules have changed. The 1974 edition of the
17 code required a 20 percent look at structural discontinuities
18 which could be spread over three different areas. The '77
19 edition of the code requires a hundred percent where you could
20 do some distribution, but you're allowed to do a weld in one
21 generator to satisfy the code. So, you're getting a much
22 better sample by the routine inspections in this area for
23 looking at problems.

24 The other thing is that people have voluntarily at a
25 lot of plants been looking at these problems.

1 MR. MICHELSON: Apparently, the code does not require
2 that you do a weld repair?

3 MR. HERMANN: You can look at the original designs
4 and evaluate the wall and the discontinuity in the wall to see
5 if it's necessary.

6 MR. MICHELSON: They apparently had a lot of excess
7 metal in this design; is that the reason?

8 MR. HERMANN: Yes.

9 MR. MICHELSON: The code does prescribe the "as-left"
10 condition though in order not to do the weld repair; is that
11 correct?

12 MR. HERMANN: There's been an evaluation of the
13 configuration of the grind out areas. I'm not sure if that
14 came out of the code rules. I'm sure it meets the code rules
15 for local discontinuities. I'm not sure if the establishment
16 of what the tapers were specifically called out by the ASME
17 code, but there are stress allowables you have to meet.

18 MR. MICHELSON: What's the reason that you don't do
19 the weld repairs? You just don't do it if you don't have to?

20 MR. HERMANN: That's probably part of it, and it's a
21 difficult thing to do, and you always have a problem when
22 you're welding on a shell like this that you could get into
23 more problems.

24 MR. MICHELSON: But you don't have a heat treatment
25 problem.

1 MR. HERMANN: You do have a heat treatment problem.
2 You have to post-weld heat treat.

3 MR. MICHELSON: To what extent do you post-weld heat
4 treat in this case?

5 MR. HERMANN: These are -- in Generator 22 they did a
6 post-weld heat treatment that was local to the shell area.

7 MR. MICHELSON: What temperature did they treat it
8 at?

9 MR. HERMANN: I believe it was 1200 probably.

10 MR. MICHELSON: This is all relatively accessible, I
11 guess; isn't it?

12 MR. CARROLL: You have some radiation problems in
13 there.

14 MR. MICHELSON: If it's hot.

15 MR. JACKSON: Yes, it's accessible with scaffolding.
16 You can get at the inside and at the outside, however, you do
17 have a radiation field associated with the tubes that are in
18 that area and obviously, you would lower water level to be able
19 to gain internal access, and that reduces the shielding, so
20 there is an exposure.

21 If we don't have to weld; meaning we meet minimum
22 wall code requirements; we would not do that to save the
23 radiation exposure.

24 MR. MICHELSON: To what extent, where you left a weld
25 and just ground it out to get the proper configuration; to what

1 extent did you find cracks in that type of as-left defect when
2 you did your inspection the next time? I can't read that table
3 and tell whether it's a new crack or an old crack.

4 MR. VAIA: In 1987, there was no weld repair. The
5 1989 outage, there was welding done on Steam Generator 22. At
6 the mid-cycle inspection, we will go back in and reinspect that
7 region and we'll be able to really answer your question after
8 the mid-cycle outage.

9 MR. HERMANN: I think there was a concern that -- on
10 the part of the staff and probably on the part of the licensee
11 about the severity of the cracking that occurred essentially in
12 one cycle after all the cracks were ground out. I think that's
13 one of the reasons that --

14 MR. MICHELSON: Well, maybe I heard the answer, but
15 maybe I heard too many words. To what extent -- what fraction
16 of the welds that were ground out and left were found to have
17 cracked again the next time you looked?

18 MR. VAIA: Okay, during the 1987 compared to the '89
19 results, there were a number of grindout areas that did show
20 re-cracking, but it wasn't that all the cracking in '89 occurred
21 in the previously ground out area. There was some additional
22 cracking in '89 that occurred away from the grindout areas.

23 MR. MICHELSON: Now, in the case where it occurred in
24 the same ground out area, how much additional cracking are we
25 talking about and what depths?

1 MR. VAIA: I believe about 2/10ths to a quarter inch
2 at the most.

3 MR. HERMANN: With regard to the questions earlier,
4 though, on the integrity of the shells, one of the things in
5 the evaluating operation later on, the assumptions that were
6 made take the worst cracking to date and put them in an area
7 where the shell was the thinnest, although the cracks had all
8 been removed.

9 That was done as a conservative way of looking at,
10 you know, what kind of performance could you expect out of the
11 shell, should you get the same kind of degradation. The
12 timeframe was cut for inspection essentially to a half a cycle
13 rather than a cycle.

14 MR. VAIA: A number of the mitigating actions that
15 Bob indicated, you know, were taken between the '89 -- well,
16 during the '89 outage, and the effect of those mitigating
17 actions will be determined during this mid-cycle outage.

18 MR. HERMANN: In conclusion, the staff is looking at
19 whether we need to take any additional action in terms of
20 generic communications on the subject. There are a couple of
21 things that are going on. We just got the first results over
22 the telephone of some samples taken at Zion which has the same
23 mechanism.

24 There are two or three units coming down right now
25 that we're trying to get some more information on the

1 examination, voluntary examination of these girth welds.

2 MR. MICHELSON: What was the original design pressure
3 for the shell?

4 MR. HERMANN: Around 1200, I imagine, 1250, something
5 like that.

6 MR. JACKSON: I believe we're talking about around
7 1100 DU.

8 MR. HERMANN: The design is probably around 13.

9 MR. JACKSON: 1085 is the design.

10 MR. MICHELSON: I guess the staff looked at the
11 degradation of the shell in terms of possible pressurization
12 from the primary side under certain kinds of accident scenarios
13 to make sure that even with these degraded wall thicknesses, we
14 were still okay, and hopefully we are.

15 MR. ELLIOTT: Barry Elliott, Materials Engineering
16 Branch. All design transients were looked at and the limiting
17 transient happened to be a reactor trip.

18 MR. MICHELSON: You mean there weren't any
19 possibilities of steam tube ruptures that might pressurize the
20 shell side to some very high pressures? Of course, you've got
21 relief capacity eventually, but I just wondered, under the
22 particular accident at the time, what the scenario might be
23 concerning the relief capability and so forth. That's the only
24 time that you could get beyond what you might anticipate.

25 MR. LEWIS: I am going to stipulate that there are a

1 lot of unanswered questions we all have. I will allow Mr. Ward
2 one more question which he's burning to ask.

3 MR. WARD: The question is; when are you going to
4 adjourn.

5 MR. LEWIS: Well, that's what I'm going to say.
6 There are clearly many more questions we all have, but we have
7 absolutely run out of time, so I'm going to call this quits.
8 Let me not start a discussion among the Subcommittee members
9 now, because that would do us in.

10 Let me ask the following: we are on the hook to
11 write a letter about this. I still have a lot of questions and
12 I think many of us do. We have a hunk of time scheduled at the
13 full committee meeting on Friday morning.

14 MR. WYLIE: Not much.

15 MR. LEWIS: Pardon?

16 MR. WYLIE: We only have three quarters of an hour.

17 MR. LEWIS: I've already asked our Chairman whether
18 we could perhaps have a bit more if it turns out to be
19 necessary. It's right before noon, and I have no problem with
20 that.

21 I do think that I would invite you all to put
22 together your preliminary views on what we've heard today; get
23 them to me Thursday morning and I will either draft a possible
24 letter for us, or I will draft two or three alternative
25 possible letters for us. We'll discuss it on Friday and decide

1 where we come down.

2 I wish we had the rest of the day today to do this,
3 but we simply don't. I'm going to be --

4 MR. WYLIE: Licensing?

5 MR. LEWIS: Yes, we do. We want as many people as
6 you're willing to send, the same crowd, if you can or something
7 like that; it's up to you, but we will have questions and, in
8 particular, I believe our official metallurgist may have some
9 questions.

10 MR. WYLIE: Do you plan to do the summary or let the
11 licensee do the summary?

12 MR. LEWIS: Let me give it a try.

13 MR. WYLIE: You've got the staff and the licensee.

14 MR. LEWIS: What I don't want to do is repeat today
15 on Friday, because there are six of us here now.

16 MR. WYLIE: But you could summarize.

17 MR. LEWIS: I will summarize as best I can, and you
18 will decide how well I've done it by booing and the appropriate
19 things. For the moment, for today's hearing, bang!

20 [Whereupon, at 12:12 p.m., the Subcommittee was
21 adjourned.]

22

23

24

25

REPORTER'S CERTIFICATE

This is to certify that the attached proceedings before the United States Nuclear Regulatory Commission


in the matter of:

NAME OF PROCEEDING: ACRS Indian Point 2

DOCKET NUMBER:

PLACE OF PROCEEDING: Bethesda, Maryland

were held as herein appears, and that this is the original transcript thereof for the file of the United States Nuclear Regulatory Commission taken by me and thereafter reduced to typewriting by me or under the direction of the court reporting company, and that the transcript is a true and accurate record of the foregoing proceedings.



MARILYNN NATIONS
Official Reporter
Ann Riley & Associates, Ltd.


Sheet

INDIAN POINT UNIT NO. 2 STRETCH RATING

**PRESENTATION TO THE
SYSTEMATIC ASSESSMENT OF EXPERIENCE
SUBCOMMITTEE OF THE ADVISORY COMMITTEE
ON REACTOR SAFEGUARDS**

FEBRUARY 6, 1990

AGENDA



- | | |
|------------------------------|---------------------|
| I. INTRODUCTION | STEPHEN B. BRAM |
| II. STRETCH POWER OVERVIEW | CHARLES W. JACKSON |
| III. STRETCH PROGRAM RESULTS | LOUIS F. LIBERATORI |
| IV. CONCLUDING REMARKS | STEPHEN B. BRAM |

INTRODUCTION

- o HISTORICAL BACKGROUND**
- o ECONOMIC AND OTHER BENEFITS**

HISTORICAL BACKGROUND

- 0 LOCATION AND ORIGINAL DESIGN**
- 0 PROTOTYPE FOUR-LOOP WESTINGHOUSE DESIGN**
- 0 STRETCH POWER HISTORICAL PERSPECTIVE**

ECONOMIC AND OTHER BENEFITS

- 0 REPLACEMENT ENERGY SAVINGS
- 0 DEFERRED CAPACITY ADDITIONS
- 0 FOSSIL FUEL DEPENDENCY
- 0 EMISSIONS

AGENDA

I. INTRODUCTION

STEPHEN B. BRAM

→ II. STRETCH POWER OVERVIEW

CHARLES W. JACKSON

III. STRETCH PROGRAM RESULTS

LOUIS F. LIBERATORI

IV. CONCLUDING REMARKS

STEPHEN B. BRAM

STRETCH POWER OVERVIEW

- 0 DESCRIPTION OF INDIAN POINT UNIT No. 2
- 0 COMPARISON OF INDIAN POINT UNIT No. 2 APPLICATION RATING WITH PREVIOUSLY LICENSED PLANTS
- 0 BACKGROUND - LICENSING HISTORY
- 0 IMPLEMENTATION PLAN

DESCRIPTION OF INDIAN POINT UNIT NO. 2

PLANT CONFIGURATION AND CORE DESIGN

- o 4-LOOP WESTINGHOUSE PRESSURIZED WATER REACTOR
 - MODEL 44 STEAM GENERATORS
 - 193 15x15 9-GRID OPTIMIZED FUEL AND STANDARD FUEL
- o CURRENT CYCLE 10 CORE DESIGN
 - EXTENDED BURNUP FUEL DESIGN
 - 5.7 KWT/FT (6.33 Kw/FT AT STRETCH)
- o WESTINGHOUSE MAIN TURBINE
 - FI LOW PRESSURE ROTORS
- o GE MAIN GENERATOR 1439 MVA

INDIAN POINT UNIT NO. 2

KEY DESIGN OPERATING PARAMETERS

| <u>PARAMETER</u> | <u>CURRENT OPERATION</u> | <u>STRETCH OPERATION</u> |
|--------------------------------------|------------------------------|------------------------------|
| NSSS POWER (MWT) | 2770 | 3083.4 |
| CORE POWER (MWT) | 2758 | 3071.4 |
| REACTOR T _{AVG} (°F) | 549.0 | 549 - 579.7 |
| STEAM PRESSURE (PSIA) | 700 | 650 - 768 |
| STEAM FLOW (x10 ⁶ LBM/HR) | 11.66 | 13.25 - 13.31 |
| S/G TUBE PLUGGING (%) | 8 | 25 * |
| RCS FLOW/LOOP (GPM) | 89700 | 80700 * |

*ASSUMED

**COMPARISON OF INDIAN POINT UNIT NO. 2
WITH PREVIOUSLY LICENSED PLANTS**

- 0 INDIAN POINT UNIT No. 2 APPLICATION 3071.4 MWT
- STILL LOWER THAN MORE RECENTLY LICENSED PLANTS**
- 0 SIGNIFICANT OPERATING EXPERIENCE FOR LARGE FOUR-LOOP
WESTINGHOUSE PWRs BEYOND 3071.4 MWT**

**LICENSE AND CORE POWER DATA
FOR OTHER WESTINGHOUSE 4-LOOP PLANTS**

| <u>PLANT</u> | <u>CORE POWER (MWT)</u> | <u>LICENSE DATE</u> |
|---------------------|-------------------------|---------------------|
| ZION No. 1 | 3250 | 1973 |
| ZION No. 2 | 3250 | 1973 |
| D. C. COOK No. 1 | 3250 | 1974 |
| D. C. COOK No. 2 | 3411 | 1977 |
| TROJAN | 3411 | 1975 |
| SALEM No. 1 | 3338/3411 | 1976/1986 |
| SALEM No. 2 | 3411 | 1981 |
| DIABLO CANYON No. 1 | 3338 | 1984 |
| DIABLO CANYON No. 2 | 3411 | 1985 |
| SEQUOYAH No. 1 | 3411 | 1980 |
| SEQUOYAH No. 2 | 3411 | 1981 |
| W. B. MCGUIRE No. 1 | 3411 | 1981 |
| W. B. MCGUIRE No. 2 | 3411 | 1983 |
| CATAWBA No. 1 | 3411 | 1985 |
| CATAWBA No. 2 | 3411 | 1986 |

LICENSE AND CORE POWER DATA
FOR OTHER WESTINGHOUSE 4-LOOP PLANTS

(CONTINUED)

| <u>PLANT</u> | <u>CORE POWER (MWT)</u> | <u>LICENSE DATE</u> |
|-----------------------|-------------------------|---------------------|
| BYRON No. 1 | 3411 | 1985 |
| BYRON No. 2 | 3411 | 1987 |
| BRAIDWOOD No. 1 | 3411 | 1987 |
| BRAIDWOOD No. 2 | 3411 | 1988 |
| CALLAWAY | 3411/3565 | 1984/1988 |
| WOLF CREEK | 3411 | 1985 |
| ALVIN W. VOGTLE No. 1 | 3411 | 1987 |
| ALVIN W. VOGTLE No. 2 | 3411 | 1989 |
| MILLSTONE No. 3 | 3411 | 1986 |

BACKGROUND - LICENSING HISTORY

- 0 INDIAN POINT DESIGNED FOR 3083.4 MWT (3071.4 MWT CORE POWER)
- 0 ORIGINAL LICENSE APPLICATION 2758 MWT CORE POWER (OCTOBER 1968)
- 0 ENGINEERED SAFETY FEATURES ORIGINALLY EVALUATED AT 3216 MWT CORE POWER
- 0 INDIAN POINT UNIT No. 3 LICENSE AT 3025 MWT RESTRICTED TO 2760 MWT UNTIL MORE EXPERIENCE GAINED - RESTRICTION LIFTED JULY 1978
- 0 UPDATED SAFETY ANALYSES FOR RECENT INDIAN POINT UNIT No. 2 RELOADS AS WELL AS FOR STRETCH

IMPLEMENTATION PLAN

- 0 SCHEDULE**
- 0 PROCEDURES**
- 0 TRAINING**
- 0 PLANT SETPOINT CHANGES**

PLANT SETPOINT CHANGES

- 0 OVER POWER/OVER TEMPERATURE DELTA-T
- 0 MAIN STEAMFLOW
- 0 RCS FLOW CALIBRATION
- 0 ALARMS
- 0 AUXILIARY FEEDWATER
- 0 FIRST-STAGE PRESSURE
- 0 TAVG
- 0 NORMAL OPERATION CONTROL SETPOINT
ADJUSTMENTS SUCH AS HEATER DRAIN TANK
CONTROL SYSTEM

AGENDA

I. INTRODUCTION

STEPHEN B. BRAM

II. STRETCH POWER OVERVIEW

CHARLES W. JACKSON

→ III. STRETCH PROGRAM RESULTS

LOUIS F. LIBERATORI

IV. CONCLUDING REMARKS

STEPHEN B. BRAM

STRETCH PROGRAM RESULTS

0 TRANSIENTS AND ACCIDENTS

- LOCA
- Non-LOCA
- OFF-SITE DOSE EVALUATIONS

0 TECHNICAL SPECIFICATIONS

0 PLANT EQUIPMENT EVALUATIONS

0 CONCLUSION

LOCA TRANSIENTS AND ACCIDENTS

- o NRC LICENSED COMPUTER MODELS
 - BASH
 - NOTRUMP
- o LARGE BREAK PCT RESULTS
 - 2039°F
- o SMALL BREAK PCT RESULTS
 - 1218.5°F
- o RESULTS SATISFY 10CFR50.46 ECCS ACCEPTANCE CRITERIA
- o CONTAINMENT PERFORMANCE

NON-LOCA TRANSIENTS AND ACCIDENTS

- 0 ALL FSAR NON-LOCA TRANSIENTS WERE REANALYZED
- 0 RESULTS MEET NON-LOCA ACCEPTANCE CRITERIA
- 0 CONTAINMENT PERFORMANCE

OFF-SITE DOSE EVALUATION

- 0 TRANSIENTS AND ACCIDENTS
- 0 3216 MWT POWER LEVEL
- 0 RESULTS REMAIN BELOW 10CFR PART 100 LIMITS

TECHNICAL SPECIFICATIONS

- 0 POWER LEVEL
- 0 TAVG/DELTA-T
- 0 MINIMUM AFW FLOW
- 0 STEAM FLOW BASIS
- 0 MINIMUM DECAY TIME FOR REFUELING

PLANT EQUIPMENT REVIEW

- 0 NSSS SYSTEMS AND EQUIPMENT
- 0 BOP SYSTEMS AND EQUIPMENT

INDIAN POINT UNIT NO. 2 STRETCH RATING PROGRAM

NSSS SYSTEMS

- 0 REACTOR COOLANT SYSTEM
- 0 PRESSURIZER AND STEAM GENERATOR SAFETY VALVE SYSTEMS
- 0 CHEMICAL AND VOLUME CONTROL SYSTEM
- 0 RESIDUAL HEAT REMOVAL SYSTEM
- 0 EMERGENCY CORE COOLING SYSTEMS
- 0 CONTAINMENT COOLING SYSTEMS
- 0 SERVICE WATER AND COMPONENT COOLING SYSTEMS

**INDIAN POINT UNIT NO. 2 STRETCH RATING PROGRAM
BOP SYSTEMS**

- 0 BOP SYSTEMS ORIGINALLY DESIGNED AND GUARANTEED AT 3083.4 MWT**
- 0 BOP HAS A CALCULATED CAPABILITY OF 3216 MWT**
- 0 BOP SYSTEMS AND EQUIPMENT WERE REVIEWED**

CONCLUSIONS

THE STRETCH PROGRAM:

- DEMONSTRATED COMPLIANCE OF FSAR ANALYSES WITH APPLICABLE ACCEPTANCE CRITERIA
- DEMONSTRATED COMPLIANCE OF PLANT COMPONENTS AND SYSTEMS WITH FSAR FUNCTIONAL AND REGULATORY REQUIREMENTS
- RECONFIRMED THE CAPABILITY OF THE PLANT TO PERFORM AT THE ORIGINAL GUARANTEED POWER RATING (3071.4 MWT CORE POWER -3083.4 MWT NSSS)
- DETERMINED NO SIGNIFICANT HAZARDS CONSIDERATION IS INVOLVED

AGENDA

I. INTRODUCTION

STEPHEN B. BRAM

II. STRETCH POWER OVERVIEW

CHARLES W. JACKSON

III. STRETCH PROGRAM RESULTS

LOUIS F. LIBERATORI

→ IV. CONCLUDING REMARKS

STEPHEN B. BRAM

Insert

**NRC STAFF EVALUATION OF
CONSOLIDATED EDISON'S PROPOSAL TO
INCREASE LICENSED THERMAL POWER AT
INDIAN POINT UNIT 2**

PRESENTED AT

**ACRS
SYSTEMATIC ASSESSMENT OF EXPERIENCE
SUBCOMMITTEE
MEETING ON FEBRUARY 6, 1990**

- **INTRODUCTION -- D. BRINKMAN**
- **OPERATIONAL EXPERIENCE -- C. COWGILL**
- **LICENSEE PRESENTATION**
- **OVERVIEW OF STAFF EVALUATION -- D. BRINKMAN**
- **ECCS EVALUATION -- T. COLLINS**
- **STEAM GENERATORS -- R. HERMANN**
- **CONCLUSION -- D. BRINKMAN**

INDIAN POINT 2
NRC REGION I STAFF
OPERATING EXPERIENCE BRIEFING FOR ACRS
FEBRUARY 1990

CURTIS COWGILL
SECTION CHIEF

OPERATING EXPERIENCE

- **JANUARY 1988 STEAM GENERATOR DRYOUT EVENT**
- **LOW NUMBER OF REACTOR TRIPS AND DECREASING**
- **IMPROVING OPERATOR PROFESSIONALISM**
- **IMPROVED OPERATIONS SUPPORT**
- **EFFECTIVE EMERGENCY OPERATING PROCEDURES**
- **EFFECTIVE OPERATOR QUALIFICATION AND REQUALIFICATION PROGRAMS**

MAINTENANCE EXPERIENCE

- **WEAKNESSES IDENTIFIED MAY 1989 BY
MAINTENANCE TEAM INSPECTION**

- POORLY DEFINED PROGRAM

- POOR MANAGEMENT SUPPORT

- POOR MATERIAL CONDITION

- GOOD IMPLEMENTATION BY MAINTENANCE STAFF

- **CORRECTIVE ACTION**

- PROGRAM AND PROCEDURE UPGRADES

- ADDED STAFFING

- IMPROVED FACILITIES

CONCLUSION

INDIAN POINT 2 OPERATING EXPERIENCE AND PERFORMANCE FROM 1988 TO 1990 HAS BEEN ADEQUATE TO SUPPORT SAFE POWER OPERATIONS AT THE HIGHER POWER LEVEL REQUESTED BY THE LICENSE AMENDMENT.

- **BACKGROUND**

- CONFIRMED PLANT WAS DESIGNED FOR A CORE POWER LEVEL OF 3071.4 MWT

- ORIGINAL OPERATING LICENSE WAS REQUESTED AT 2758 MWT

- NO TECHNICAL REASON FOR DERATE

- 1970 SER

- ENGINEERED SAFETY FEATURES (EXCEPT ECCS) AND ENVIRONMENTAL REVIEWS EVALUATED BY NRC STAFF AT 3216 MWT

- ECCS EVALUATED AT 2758 MWT

- **CURRENT SAFETY EVALUATION BY NRC STAFF
OF LICENSEE'S ANALYSIS OF OPERATION AT
3071.4 MWT**

- CORE DESIGN

- ANALYSES PERFORMED

- ECCS PERFORMANCE (LOCA)

- OVERPRESSURE PROTECTION

- ANTICIPATED OPERATIONAL OCCURRENCES

- NON-LOCA ACCIDENTS

- AUXILIARY FEEDWATER AND RESIDUAL HEAT
REMOVAL PERFORMANCE

- REACTOR COOLANT SYSTEM

- **CONTAINMENT INTEGRITY ANALYSIS**

- DESIGN PRESSURE = 47 PSIG

- LOCA

- 40.31 PSIG FOR 3083.4 MWT

- 41.12 PSIG FOR 3216 MWT

- MAIN STEAM LINE BREAK

- 39.99 PSIG FOR 3083.4 MWT

- **BALANCE OF PLANT SYSTEMS**

- STEAM TURBINE SYSTEM INCLUDING MAIN STEAM, FEEDWATER, CONDENSER, CONDENSATE AND CIRCULATING WATER SYSTEMS AND SUPPORT SYSTEMS
- ESSENTIAL AND NON-ESSENTIAL SERVICE WATER SYSTEMS
- EMERGENCY DIESEL GENERATORS
- BOP PIPING SYSTEMS
- STEAM GENERATORS

- **EQUIPMENT QUALIFICATION**

- **INSTRUMENTATION**

- NO CHANGES TO PLANT EQUIPMENT REQUIRED
- USE APPROVED METHODOLOGY FOR CALCULATING SETPOINT CHANGES
- REVIEWED SETPOINT CHANGES FOR OVERPOWER DELTA T AND OVERTEMPERATURE DELTA T CHANNELS, POTENTIAL UNCERTAINTIES PROPERLY CONSIDERED

- **ENVIRONMENTAL CONSEQUENCES**

- RADIOLOGICAL AND NON-RADIOLOGICAL ANALYSES WERE ORIGINALLY PERFORMED AT 3216 MWT WHICH BOUNDS PROPOSED LEVEL OF 3071.4 MWT
- OFFSITE DOSES ARE WELL WITHIN ACCEPTANCE CRITERIA OF SRP 15.6.3
- LICENSEE'S REASSESSMENT DOES NOT ALTER OUR CONCLUSIONS STATED IN SECTION 11.4 OF ORIGINAL SER

- **TECHNICAL SPECIFICATION CHANGES**

- CHANGE VALUE OF RATED POWER FROM 2758 MWT TO 3071.4 MWT
- CHANGE ALLOWABLE T_{AVG} LSSS AND LCO SETPOINTS
- INCREASE MINIMUM REQUIRED AUXILIARY FEEDWATER FLOWRATE TO 380 GPM
- INCREASE MINIMUM DECAY BEFORE FUEL MOVEMENT TO 174 HOURS

IP-2 ECCS EVALUATION

* SYSTEM OVERVIEW

- ORIGINAL DESIGN RATING
- SYSTEM COMPOSITION
- SIMILARITY TO OTHER PLANTS

* PERFORMANCE ANALYSIS

- METHODS
- SCOPE
- INPUT
- RESULTS

SYSTEM OVERVIEW

- * ORIGINAL DESIGN FOR 3216 MWt PLANT

- * SYSTEM CONFIGURATION
 - 4 COLD LEG ACCUMULATORS
 - 3 HIGH HEAD SAFETY INJECTION PUMPS
 - 2 RHR PUMPS & HX's
 - 2 RECIRCULATION PUMPS

- * SIMILARITY TO OTHER PLANTS
 - TYPICAL MIX OF SUBSYSTEMS
 - TYPICAL SUBSYSTEM CAPACITIES

ECCS PERFORMANCE ANALYSIS

* METHODS

- APPROVED BASH CODE FOR LARGE BREAKS
- APPROVED NOTRUMP CODE FOR SMALL BREAKS

* SCOPE

- FULL SPECTRUM OF BREAK SIZES EXAMINED

* INPUT

- 102% OF 3071.4 MWt
- 102% OF PEAK LINEAR POWER
- 25% SG TUBE PLUGGING
- APPENDIX K INPUTS

* RESULTS

- LARGE BREAK PCT: 2039 F
- SMALL BREAK PCT: 1218 F
- PCT CRITERION: 2200 F


ECCS REVIEW CONCLUSIONS

- * ORIGINAL DESIGN RATING UNCHANGED
- * APPROVED ANALYSIS METHODS USED
- * SCOPE OF ANALYSIS ADEQUATE
- * INPUTS/RESULTS SATISY REGULATIONS
- * ECCS ACCEPTABLE FOR 3071.4 MWt OPERATION

CRACKING OF THE UPPER SHELL-TO-TRANSITION CONE
GIRTH WELD IN STEAM GENERATORS

INFORMATION NOTICES AND PLANTS

- 90-04 INDIAN POINT 2 AND ZION 1
- 85-65 INDIAN POINT 3 AND SURRY 2
- 82-37 INDIAN POINT 3



GENERAL OUTLINE OF
WESTINGHOUSE MODEL 44
STEAM GENERATOR

Figure 2.3-1


OVERVIEW OF INDUSTRY EXPERIENCE

FOUR DOMESTIC PLANTS - 18 SGs
WESTINGHOUSE MODEL 44 AND MODEL 51
WITH FEEDWATER RING DESIGN
ONE FOREIGN PLANT

CRACKS VARY FROM SEVERE TO ISOLATED
AND DISPERSED AT DIFFERENT PLANTS
IP-3 HAD THROUGH-WALL LEAK

SUMMARY OF EXPERIENCE AT IP-2

COMPREHENSIVE NDE AFTER IP-3 CRACKING
CRACKS DETECTED AND REPAIRED IN FALL 1987
ADDITIONAL CRACKS DETECTED IN SPRING 1989
MID-CYCLE EXAMINATION IN FEBRUARY 1990



GENERAL OUTLINE OF GIRTH WELD REGION

Figure 2.1-2

INDIAN POINT UNIT 2
FINAL MAX. DEPTH OF GRIND
(COMBINATION OF 1987 AND 1989 DATA)

| <u>ZONE</u> | <u>S/G 21</u> | | <u>S/G 22</u> | | <u>S/G 23</u> | | <u>S/G 24</u> | |
|-------------|---------------|-------------|---------------|-------------|---------------|-------------|---------------|-------------|
| | <u>1989</u> | <u>1987</u> | <u>1989</u> | <u>1987</u> | <u>1989</u> | <u>1987</u> | <u>1989</u> | <u>1987</u> |
| 1 | .57 | .56 | .63 | .49 | .76 | 1.01 | .48 | .48 |
| 2 | .40 | .40 | .54 | .68 | .33 | .33 | .27 | .27 |
| 3 | .37 | .37 | .56 | .56 | .20 | .65 | .28 | .13 |
| 4 | N/A | | .51 | .88 | .49 | .49 | .28 | .00 |
| 5 | N/A | | .73 | 1.00 | .09 | .38 | .42 | .42 |
| 6 | N/A | | .58 | .76 | .34 | .34 | .33 | .57 |
| 7 | .28 | .28 | 1.42 | 1.07 | .11 | .42 | .26 | .36 |
| 8 | .36 | .36 | 1.38 | .89 | .36 | .16 | .51 | .51 |
| 9 | .32 | .32 | .58 | 1.01 | .79 | .65 | .16 | .00 |
| 10 | .36 | .36 | .71 | .51 | .58 | .58 | .33 | .33 |
| 11 | N/A | | 1.24 | .65 | .29 | .29 | .07 | .07 |
| 12 | .54 | .50 | .49 | .49 | .57 | .57 | .40 | .40 |

Table 2.3-6

PROBABLE FAILURE MECHANISM:
CORROSION-ASSISTED THERMAL FATIGUE

COMMON FACTOR: GENERAL CORROSION PITS
WERE CRACK INITIATION SITES

POSSIBLE CONTRIBUTING FACTORS:

THERMAL CYCLING DURING TRIPS AND TRANSIENTS
COPPER ALLOYS IN FEEDWATER SYSTEM AND CONDENSER
LOW TEMPERATURE FABRICATION HEAT TREATMENT
OXYGEN IN AUXILIARY FEEDWATER
LOCATION OF THE DOWNCOMER FLOW RESISTANCE PLATE

CORRECTIVE ACTIONS TO DATE

REPAIR BY GRINDING TO ESTABLISHED PROFILES

WELD BUILDUP AND PWHT OF DEEP FLAWS

FINAL MT AND MAPPING OF EXCAVATIONS

REMOVE DOWNCOMER FLOW RESISTANCE PLATES

CHANGE PLANT OPERATING CONDITIONS

(FLOW AND WATER CHEMISTRY)

REPLACE COPPER ALLOY HEAT EXCHANGERS

REPLACE STEAM GENERATORS

POSSIBLE FUTURE ACTIONS

NONDESTRUCTIVE EXAMINATIONS

ENHANCED UT BY EXPERIENCED PERSONNEL CAPABLE
OF DETECTING SURFACE-CONNECTED CRACKS

OLDER ASME SECTION XI SAMPLING COULD MISS CRACKS

NEWER ASME SECTION XI RULES INCREASE DETECTION

INTERNAL MT ONLY CONCLUSIVE NDE

ASSESS NEED FOR ADDITIONAL GENERIC COMMUNICATIONS

ZION METALLURGICAL RESULTS

ADDITIONAL VOLUNTARY EXAMINATION RESULTS

CONCLUSION

**PROPOSED INCREASE IN LICENSED THERMAL
POWER IS ACCEPTABLE**