

# LICENSEE EVENT REPORT

U.S. NUCLEAR REGULATORY COMMISSION

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5				
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	37	58	9

0	1	L	6	0	5	0	0	0	3	6	6	7	0	4	0	8	8	1	8	0	5	0	5	8	1	9
7	8	REPORT SOURCE		60	61	DOCKET NUMBER						60	62	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | With Hatch 2 at steady state, 100% power the RCIC steam line dP instr. |  
 03 | FT and C was being performed. The RCIC inboard steam supply isol. valve |  
 04 | could not be reopened after being closed on an isolation signal. This |  
 05 | is reportable under Tech Specs 6.9.1.9.B. As per Tech Specs 3/4.7.3.2 |  
 06 | HPCI system was operable, and no significant event occurred. This is a |  
 07 | nonrepetitive event, and there were no effects upon public health and |  
 08 | safety due to this event. |

0	9	C	E	A	A	V	A	L	V	I	O	P	B	Z
7	8	9	10	11	12	13	COMPONENT CODE					18	19	20
SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE	VALVE SUBCODE

17	8	1	—	0	2	9	0	3	L	—	0
21	22	23	24	25	26	27	28	29	30	31	32
LER/RO REPORT NUMBER	EVENT YEAR	SHUTDOWN METHOD	SEQUENTIAL REPORT NO.	HOURS	OCCURRENCE CODE	REPORT TYPE	REVISION NO.	ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	ATTACHMENT SUBMITTED

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The event was due to the control switch to the valve being activated |  
 11 | too frequently during valve opening. This jogging caused an excessive |  
 12 | motor amperage which tripped the breaker. The breaker was then reset |  
 13 | and the valve worked properly. The unit is now in full compliance with |  
 14 | the requirements, and no further reporting is required. |

1	5	E	J	0	0	LA	B	Functional test and calibration	
7	8	9	FACILITY STATUS				OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION

1	6	Z	Z	NA	NA
7	8	9	10	11	12
ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE		

1	7	0	0	Z	NA
7	8	9	10	11	12
PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION			

1	8	0	0	0	NA
7	8	9	10	11	12
PERSONNEL INJURIES NUMBER	DESCRIPTION				

1	9	Z	NA
7	8	9	10
LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION		

2	10	N	NA
7	8	9	10
PUBLICITY ISSUED	DESCRIPTION		

810512 412 NAME OF PREPARER: C. L. Coggin, Supt. Plt. Eng. Serv. PHONE: 912-367-7851

NRC USE ONLY

LER #: 50-366/1981-029  
Licensee: Georgia Power Company  
Facility Name: Edwin I. Hatch  
Docket #: 50-366

Narrative Report  
for LER 50-366/1981-029

On 4-8-81, at 13:00 and with Unit 2 at 100% thermal power the monthly test (functional test part) of HNP-2-3410, RCIC Steam Line Delta Pressure Instrument FT&C, was being performed. As per the procedure the RCIC inboard steam supply valve, 2E51-F007, was closed on an isolation trip signal. The isolation trip signal was reset, and the valve control switch was actuated a number of times in rapid succession to open the valve. This resulted in an apparent overcurrent situation for the MOV, and this tripped the breaker and overload blocks for the MOV. The breaker and overload blocks were reset, and the valve was successfully tested for operability. RCIC was declared operable upon completion of the test. Operating personnel have been reminded that valves of this type are subject to failure if excessive duty cycles are imposed.

As per Tech Specs 3/4.7.3.2 HPCI was operable with current surveillance requirements complete and satisfactory during this period of RCIC inoperability. No significant event occurred.

The unit is now in full compliance with the requirements of Tech Specs, and no further reporting is required.