

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MI PAL 12 00 - 000000 - 000 3 41111 4 _____ 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CON'T
01 REPORT SOURCE L 5 015 000 0125 15 7 0 53 11 8 1 8 0 6 2 9 8 1 1 9
7 8 9 DOCKET NUMBER 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 During operator rounds, Snubber No 43 (ESF pump suction) was observed
03 to be leaking oil. Further investigation revealed the snubber to be
04 inoperable. Condition reportable per TS 3.20 and 6.9.2.B.2. Operabil-
05 ity restored within time requirements of TS 3.20. Refer to LER 81-18
06 for similar occurrence. No threat to public health or safety.
07 _____
08 _____

09 SYSTEM CODE S F 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE S U P O I R T 14 COMP SUBCODE D 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 LER NO REPORT NUMBER 8 7 21 22 EVENT YEAR 8 7 23 24 SEQUENTIAL REPORT NO. 0 1 2 2 26 27 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32
18 ACTION TAKEN C 18 X 19 33 34 FUTURE ACTION X 19 35 EFFECT ON PLANT Z 20 36 SHUTDOWN METHOD Z 21 37 HOURS 0 0 0 0 40 ATTACHMENT SUBMITTED N 23 41 NPRD-4 FORM SUB Y 24 42 PRIME COMP SUPPLIER A 25 43 COMPONENT MANUFACTURER B 2 0 9 26 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 Oil leakage caused by apparent O-ring failure. Snubber will be
11 disassembled to verify cause.
12 _____
13 _____
14 _____

15 FACILITY STATUS B 28 29 % POWER 0 0 2 29 30 OTHER STATUS NA 31 METHOD OF DISCOVERY A 31 32 DISCOVERY DESCRIPTION Operator Rounds 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
15 ACTIVITY CONTENT Z 33 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38 TYPE Z 38 39 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
18 PERSONNEL INJURIES NUMBER 0 0 0 40 41 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 43 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
20 PUBLICITY ISSUED N 44 45 DESCRIPTION NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8107140529 810629
PDR ADOCK 05000255
PDR

17

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M I P A L | 1 | 2 | 0 0 | - | 0 | 0 0 | 0 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CON'T
01 | L | 6 | 0 1 5 | 1 0 0 | 0 | 2 5 | 5 | 7 | 0 | 5 3 | 1 | 8 1 | 8 | 0 | 6 | 2 1 9 | 8 | 1 | 9 |
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | During operator rounds, Snubber No 43 (ESF pump suction) was observed
03 | to be leaking oil. Further investigation revealed the snubber to be
04 | inoperable. Condition reportable per TS 3.20 and 6.9.2.B.2. Operabil-
05 | ity restored within time requirements of TS 3.20. Refer to LER 81-18
06 | for similar occurrence. No threat to public health or safety.
07 |
08 |

09 | S | F | 11 | E | 12 | B | 13 | S U P P O R T | 14 | D | 15 | Z | 16 |
7 8 SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP SUBCODE 14 VALVE SUBCODE 15
17 | 8 1 | 0 1 2 2 | 0 3 | L | 10 |
7 8 LER NO REPORT NUMBER 21 22 EVENT YEAR 23 SEQUENTIAL REPORT NO. 24 OCCURRENCE CODE 25 REPORT TYPE 26 REVISION NO. 27
18 | C | X | 19 | Z | 20 | Z | 21 | 0 0 0 0 | N | 23 | Y | 24 | A | 25 | B | 2 0 1 9 | 26 |
33 34 ACTION TAKEN 35 FUTURE ACTION 36 EFFECT ON PLANT 37 SHUTDOWN METHOD 38 HOURS 39 ATTACHMENT SUBMITTED 40 NRC-4 FORM SUB. 41 PRIME COMP. SUPPLIER 42 COMPONENT MANUFACTURER 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | Oil leakage caused by apparent O-ring failure. Snubber will be
11 | disassembled to verify cause.
12 |
13 |
14 |

15 | E | 28 | 0 0 2 | 29 | NA | 30 | A | 31 | Operator Rounds | 32 |
7 8 FACILITY STATUS 9 10 % POWER 11 OTHER STATUS 12 13 METHOD OF DISCOVERY 14 DISCOVERY DESCRIPTION 15
16 | Z | 33 | Z | 34 | NA | 35 | NA | 36 |
7 8 ACTIVITY CONTENT RELEASED OF RELEASE 9 10 AMOUNT OF ACTIVITY 11 12 LOCATION OF RELEASE 13 14
17 | 0 0 0 | 37 | Z | 38 | NA | 39 |
7 8 PERSONNEL EXPOSURES NUMBER 9 10 TYPE 11 DESCRIPTION 12 13
18 | 0 0 0 | 40 | NA | 41 |
7 8 PERSONNEL INJURIES NUMBER 9 10 DESCRIPTION 11 12
19 | Z | 42 | NA | 43 |
7 8 LOSS OF OR DAMAGE TO FACILITY TYPE 9 10 DESCRIPTION 11 12
20 | N | 44 | NA | 45 |
7 8 PUBLICITY ISSUED DESCRIPTION 9 10 NRC USE ONLY 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

17