17	* LICENSEE EVENT REPORT
•	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	1 LZ IS 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	SOURCE LL 6 0 5 0 0 0 2 9 5 7 0 6 1 5 8 1 8 0 7 0 6 8 1 9 OCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	During normal operation the stack gas rad monitor ORE-0014 began spik-
0 3	ing erratically. Isotopic samples immediately pulled indicated no ab-
0 4	normal activity. The monitor was taken OOS and shiftly gas samples
0 5	were taken as required by TS 3.14.1.C. There were no safety implica-
0 6	tions and the healt: and safety of the general public were not affec-
0 7	ted.
0 8 7 8	9 80
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) COURT COUR
1 0	The cause of the erratic spiking is unknown. The GM tubes (Amperex
11	Model 12NB3) were replaced. The monitor was functionally tested and
1 2	returned to service. This is the first incidence of this occurrence to
1 3	this rad monitor. No further action is necessary.
14	9 80
15	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 NA NA
	9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8	9 PERSONNEL INJURIES 13 80
1 8	NUMBER DESCRIPTION (41) NA NA
	LOSS OF OR DAMAGE TO FACILITY 43
7 8	Z (42) 9 10 PUBLICITY NRC USE ONLY
2 0	NRC USE ONLY