LICENSFE EVENT REPORT

	EIGENGEE EVENT HETON
	CONTROL BLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	I L D R S 3 2 0 0 - 0 0 0 0 - 0 0
O 1	REPORT L 6 0 5 0 10 10 12 14 19 7 0 6 1 1 9 8 1 8 0 7 1 0 8 1 9 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During RPS MG Set relay calibration, the 3B MG Set undervoltage relay failed to trip
0 3	on an undervoltage signal. This was of minimal safety significance, since the pro-
0 4	tective function of the RPS system was not inhibited. There was no effect on public
0 5	health or safety. This is the first occurrence of this type at Dresden.
0 6	
0 7	
08	90
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
	TO LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE COMPONENT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER X 18 X 19 Z 20 Z 21 0 0 0 0 0 0 0 0 0
10	The cause will not be resolved until the relay can be broken down and examined
11	during the next scheduled unit outage of sufficient length. Upon discovery of the
1 2	nature of the problem, the relay will be repaired or replaced, and a supplemental LER
1 3	will be submitted. The 3A Reactor Protection Bus will remain on the backup power
14	supply until the relay is repaired.
	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
	OCTIVITY CONTENT 12 13 44 45 46 LOCATION OF RELEASE 36
7 8	2 (33) Z (34) N/A N/A 9 10 11 44 45 80 PERSONNEL EXPOSURES
1 7	NUMBER TYPE DESCRIPTION (39) N/A
	PERSONNEL INJURIES NUMBER DESCRIPTION 41 N/A
7 8	9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	Z 42 N/A
20	PUBLICITY ISSUED DESCRIPTION 45 PDR ADOCK 05000249 N/A S PDR
7 8	9 10 68 6 80.5



DEVIATION REPORT

DVR NO.

STA UNIT YEAR NO.

D - 12 - 3 - 81- 36

PART I TITLE OF DEVIATION			OCCURRED
3B RPS MG Set Failure to Tri			6/19/81 10:25 DATE TIME
SYSTEM AFFECTED 500	PLANT CONDITIONS		TESTING
Rx Protection	MODERun	PWR (MWT) , LOAD (MWE) 715 X D
DESCRIPTION OF EVENT			TAX DE CONTROL DA PROPERTO DE CONTROL AUTORIA
During RPS MG Set undervolta	ge relay calibration	the 3B RPS MG set failed	to trip on an
undervoltage signal.			
DESCRIPTION OF CAUSE			
Unknown at this time.			
	Tre-built the		
OTHER APPLICABLE INFOR	MATION		
None	NA CON		
EQUIPMENT X YES DR NO.		Michael Wright	6/19/81
FAILURE NO N	/A ' 14290	RESPONSIBLE SUPERV	
PART 2 OPERATING ENGINEERS	COMMENTS		
The 3A RPS Bus will remain o	n backup feed until	the tripping problem is res	solved.
TYPE OF DEVIATION EVE	ENT OF POTENTIAL TE	CH SPEC NON-REPORTABLE	ANNUAL RELATED
REPORTABLE OCCURRETICE P		OLATION OCCURRENCE	REPORTING WE ISSUED
14 DAY 10CFR21			YES X YES X
X 30 DAY NOTIFICATION			NO NO NO
REPORTABLE OCCURRENCE	ACTION (TEN NO	T 555005 50 50 50 50 50 50 50 50 50 50 50	
NUMBER	ACTION ITEM NO.	PROMPT ON-SITE NOTIFICAT	6/19/81 11:30
		TITLE	DATE TIME
XXXX 81=17/03L-0			1196
		TITLE	DATE TIME
24-HOUR NEC NOTIF	CATION	PROMPT OFF-SITE NOTIFICA	TION
X TPH M. Jordan	6/19/81 1100	F. Palmer	6/19/81 12:42
REGION III	DATE TIME	TITLE	DATE TIME
TGM			
RESPONSIBLE COMPANY OFFICE	DATE TIME	TITLE	DATE TIME
CONDITIONS AND THEIR REPOR		TITLE	DATE TIME
	REVIEW AND COMPLETED	Michael Wright	6/19/81
		OPERATING ENGINEER	DATE
ACCEPTANCE BY STA	TION REVIEW 1	e e Villialiant Illi	146
AS REQUIRED		2. and Millian 1	77
DATE	7-1	0-31 7-10-81	
RESOLUTION APPROV	ED AND	mustes 1 hot	7/10/81
AUTHORIZED FOR DI		STATION SUPERINTENDENT	# DATE
86-517: (C-77 (FORM (5-52-1)			