

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

# SAFETY EVALUATION BY THE OFFICE OF NUCLEAR REACTOR REGULATION

### FOR THE

## PRAIRIE ISLAND NUCLEAR GENERATING PLANT UNIT NOS. 1 AND 2

DOCKET NOS. 50-282 AND 50-306

#### INTRODUCTION

10 N N N

On March 28, 1979 the Three Mile Island Nuclear Power Plant, Unit 2 (TMI-2) experienced core damage which resulted from a series of events which were initiated by a loss of feedwater transient. Several aspects of the accident have generic applicability at operating Westinghouse reactors. On April 11, 1979, IE Bulletin 79-06 was sent to all Combustion Engineering and Westinghouse operating plant licensees. The purpose of the Bulletin was to provide information concerning the accident at TMI-2 and to request certain actions be taken by licensees to preclude a similar occurrence at their facilities. This bulletin was superseded and expanded by IE Bulletin 79-06A dated April 14, 1979, and by IE Bulletin 79-06A Revision 1 dated April 18, 1979. By letters dated April 30, May 18, and June 22, 1979 the Northern States Power Company provided responses to the Bulletins.

#### EVALUATION

In the two-year period since the Bulletins have been implemented we have observed, in addition to our review of the responses enumerated above, that the licensee has complied with all the following provisions of the Bulletins:

- Understanding of the TMI-2 sequence of events.
- Review Plant Procedures for coping with accidents and transients.
- By review of procedures and training instructions:
  - (1) to avoid overriding automatic action of ESF,
  - (2) to keep high pressure injection (HPI) system in operation for ac least 20 minutes and to maintain 50 F subcooling margin,
  - (3) to correlate HPI initiation with reactor coolant pump (RCP) operation, and
  - (4) to train operators not to rely on pressurizer level only, to determine primary coolant invectory.
- Verification of emergency feedwater (EFW) valve positions and all safetyrelated valve positions to ensure proper operation of EFW and ESF.

07220376 810708 ADDCK 05000282

- By review of containment isolation initiation and design for avoidance of isolating lines that are needed to avoid degraded core cooling capability.
- By preparing and implementing procedures for all valves which could defeat or compromise flow of EFW.
- By reviewing operating modes and procedures to prevent inadvertent pumping of radioactive gasses and liquids out of the primary containment.
- By reviewing procedures related to maintenance and test of safety-related systems to:
  - verify operability of redundant system prio to removal of any system from service,
  - (2) verify operability of all systems following maintenance or testing, and,
  - (3) verification to operating personnel whenever a system is removed from or returned to service.
- By developing procedures and training operators to establish and maintain natural circulation.
- By training operators to take into account reactor vessel integrity considerations during any accident or transient.
- By performing analyses and design modifications to reduce the likelihood of automatic PORV actuation during anticipated transients.
- By providing procedures and training operators for a prompt manual reactor trip for transients that result in a pressure increase in the reactor coolant system.
- By providing for prompt reporting within one hour of the time the reactor is not in a controlled or expected condition of operation.
- By proposing any needed Technical Specification changes to implement any of the above parts of the Bulletins.

#### CONCLUSIONS

.

Eased on our review of the information provided by the licensee in response to these IE Bulletins, we conclude that the licensee has acceptably responded to these Bulletins. The actions taken by the licensee demonstrate its understanding of the concerns and implications of the TMI-2 accident as they relate to the Prairie Island Nuclear Generating Plant. These actions have resulted in added assurance for the continued protection of the public health and safety during plant operation.

Dated: CIL CO toet

.