

LEB SUPPLEMENTAL INFORMATION

RRRO-50- 260 / 81030 Technical Specification Involved 3.5.B.7

Reported Under Technical Specification 6.7.2.b(2) *Date due NRC: 7/29/81

Date of Occurrence 6/29/81 Time of Occurrence 2030 Unit 2

Identification and Description of Occurrence:

While performing SI 4.5.B.1.d., valve 2-FCV-2-74-57, became inoperable, making RHR loop I inoperable.

Conditions Prior to Occurrence:
Unit 1 in refueling outage.

Unit 2 at 99%.

Unit 3 at 95%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Met requirements of T.S. 4.5.B.7.

Apparent Cause of Occurrence:

Geared limit switch "red" switch finger base broke off of the operator, making the valve inoperable.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Replaced the "red" finger base of the limitorque type SMB size 2 valve on the motor operator. The vibration problem with this valve is being investigated.

Failure Data: None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: 