

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | E | C | P | R | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 9 | 8 | 7 | 0 | 5 | 2 | 2 | 8 | 1 | 8 | 0 | 6 | 1 | 6 | 8 | 1 | 9
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | As part of a follow-up inspection of an unexpected alarm, it was discovered that the
0 3 | CS header break detection instrument switches were piped to the incorrect CS lines,
0 4 | i.e., CS-DPIS-43A was connected to the B loop header and CS-DPIS-43B to the A loop
0 5 | header. At the time of the discovery of the occurrence the CS systems were not re-
0 6 | quired to be operable. This occurrence had no adverse affect on the public health
0 7 | and safety. This event is not repetitive.

0 8 | _____ 80

0 9 | S | F | 11 | B | 12 | C | 13 | I | N | S | T | R | U | 14 | I | 15 | Z | 16
7 8 SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 14 VALVE SUBCODE 15
17 | 8 | 1 | 21 | 22 | 0 | 1 | 1 | 24 | 26 | 0 | 3 | 28 | 29 | I | 30 | 0 | 32
LE/RD REPORT NUMBER 21 22 EVENT YEAR 23 SHUTDOWN METHOD 24 SEQUENTIAL REPORT NO. 25 OCCURRENCE CODE 26 REPORT TYPE 27 REVISION NO. 28
F | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | 24 | Z | 25 | Z | 9 | 9 | 9 | 26
33 ACTION TAKEN 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUTDOWN METHOD 37 HOURS 38 ATTACHMENT SUBMITTED 39 NPRD-4 FORM SUB. 40 PRIME COMP. SUPPLIER 41 COMPONENT MANUFACTURER 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this occurrence is that the instrument lines were connected to the
1 1 | wrong line at the drywell penetration. To correct the problem, the instruments
1 2 | were connected to the proper lines. No further action is planned.

1 3 | _____
1 4 | _____ 80

1 5 | H | 28 | 0 | 0 | 0 | 29 | NA | 30 | C | 31 | Operator Inspection | 32
7 8 FACILITY STATUS 9 10 % POWER 11 OTHER STATUS 12 METHOD OF DISCOVERY 13 DISCOVERY DESCRIPTION 14

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 ACTIVITY CONTENT 9 10 RELEASED OF RELEASE 11 AMOUNT OF ACTIVITY 12 LOCATION OF RELEASE 13

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 PERSONNEL EXPOSURES 9 10 NUMBER 11 TYPE 12 DESCRIPTION 13

1 8 | 0 | 0 | 0 | 40 | NA | 41
7 8 PERSONNEL INJURIES 9 10 NUMBER 11 DESCRIPTION 12

1 9 | Z | 42 | NA | 43
7 8 LOSS OF OR DAMAGE TO FACILITY 9 10 TYPE 11 DESCRIPTION 12

2 0 | N | 44 | NA | 45
7 8 PUBLICITY 9 10 NUMBER 11 DESCRIPTION 12

NRC USE ONLY

R. D. Flannigan

PHONE 402-825-3811