50.55(e) 50-498 50-499

The Light company

Company Houston Lighting & Power P.O. Box 1700 Houston, Texas 77001 (713) 228-9211

June 22, 1981 ST-HL-AE-684 SFN: V-0530

Mr. Karl Seyfrit Director, Region IV Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

Dear Mr. Seyfrit:



South Texas Project
Units 1 & 2
Docket Nos. STN 50-498, 50-499
Supplemental Information Regarding the Concrete Repair Program of the Reactor Containment Buildings

On May 20, 1981, during an inspection of Houston Lighting & Power's documentation for 10CFR50.55(e) items, Mr. J. Tapia of your office requested supplemental information concerning the concrete repair program utilized in the repair of the Reactor Containment Building (RCB) shell walls. The request for additional information was limited to those concrete repairs required as a result of the Lift No. 8 Concrete Void Investigation. Therefore the following information is provided in response to Mr. Tapia's request.

The method for repair of the concrete voids in the Reactor Containment Building shell walls basically comprised the following steps:

- (1) The containment liner was "sounded" in order to map potential void areas.
- (2) Exploratory holes were drilled to determine the actual void area.
- (3) All voids were hydrostatically pressure tested using the holes to determine which voids were interconnected behind the liner plate.
- (4) Pumping of the grout was then initiated. Grout injection was made at the lowest open insert for an individual repair area as determined by the hydrostatic pressure test. As the grout filled the void successively higher insert holes were shut off (closed) as full consistency grout flowed through the hole (i.e. water-dilluted grout and/or air bubbles were allowed to escape).

1/01

Houston Lighting & Power Company June 22, 1981 ST-HL-AE-684 SFN: V-0530 Page 2 (5) The holes drilled into the liner plate were repaired using couplings and plugs. These couplings were machined to fit the holes and welded to the liner to meet ASME requirements. Plugs were inserted into the couplings and seal welded. (6) Iraining was required of all personnel involved in the repair program. (7) Repairs were witnessed by a Brown & Root QA/QC inspector and performed under the direction of, and evaluated by, Design Engineering or a professional consultant. The adequacy of this repair method was verified following the repair of Lift 15 in RCB 1. Holes were drilled through the liner into the grouted area to determine whether there were any ungrouted voids, and to inspect the quality of the grout in place and the grout-concrete interface. Examination of each of these holes revealed solid grout, concrete, or both. No voids were found, and the interfaces between the grout and concrete were tight. Additionally, a polar crane girder bracket was successfully load tested, also demonstrating that this repair method was adequate. If there are any questions regarding this item, please contact Mr. R. R. Hernandez at (713) 676-8211. Very truly yours, J. H. Goldberg Vice President Nuclear Engineering and Construction RRH/SSR/amj

Houston Lighting & Power Company

cc: J. H. Goldberg D. G. Barker

C. G. Robertson Howard Pyle

R. L. Waldrop

H. R. Dean

D. R. Beeth

J. D. Parsons

J. W. Williams J. W. Briskin

R. A. Frazar

STP RMS

H. S. Phillips

J. O. Read M. D. Schwarz

R. Gordon Gooch

d. R. Newman

(Lowenstein, Newman, Reis, & Axelrad)

Director, Office of Inspection & Enforcement

Nuclear Regulatory Commission

Washington, D. C. 20555

M. L. Borchelt President

Central Power & Light Compan

P. O. Box 2121

Corpus Christi, Texas 78403

R. L. Range

Central Power & Light

P. O. Box 2121

Corpus Christi, Texas 78403

R. L. Hancock

Director of Flectrical Utilit.

City of Austin

P. O. Box 1088 Austin, Texas 78767

T. H. Huehlenbeck

City of Austi-

P. O. Box 1088

Austin, Texas 78767

J. B. Poston

Assistant General Manager of Operations

City Public Service Board

P. O. Box 1771

San Antonio, Texas 78296

A. vonRosenberg

City Public Service Board

P. O. Box 1771

San Antonio, Texas 78296

Brian E. Berwick, Esquire Assistant Attorney for the State of Texas

P. O. Box 12548

Capitol Station

Austin, Texas 78711

June 22, 1981 ST-HL-AE-684

SFN: V-0530

Page 3

(NRC)

(Read-Poland, Inc.)

(Baker & Botts)

(Baker & Botts)

Charles Bechhoefer. Esquire Chairman, Atomic Safety & Licensing Board U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dr. James C. Lamb, III 313 Woodhaven Road

Chapel Hill, North Carolina 27514

Mr. Ernest E. Hill

Lawrence Livermore Laboratory

University of California

P. O. Box 808, 1-123

Livermore, California 94550

William S. Jordan, III

Harmon & Weiss 1725 I Street, N. W.

Suite 506

Washington, D. C. 20006

Lanny Sinkin Citizens Concerned About Nuclear Power

5106 Casa Oro

San Antonio, Texas 78233

Citizens for Equitable Utilities, Inc.

c/o Ms. Peggy Buchorn

Route 1, Box 1684

Brazoria, Texas 77422

Jay Gutierrez, Esquire

Hearing Attorney

Office of the Executive Legal Director U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

6-9-81