

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | C | M | G | S | | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | | 5
7 8 LICENSEE CODE 14 15 LICENSE NUMBER 15 28 LICENSE TYPE 30 37 47 58

0 1 | | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 9 | 7 | 0 | 4 | 2 | 7 | 8 | 1 | 8 | 0 | 5 | 2 | 7 | 8 | 1 | 9
7 8 REPORT SOURCE 50 61 DOCKET NUMBER 58 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While in Mode 5, initial fuel loading, the RHR system was inadvertently
 0 3 | isolated from the RCS. While performing a modification, the fuses from the
 0 4 | solid state protection system output cabinet were removed and an isolation
 0 5 | valve closed. This is in violation of Technical Specification 3:4.1.4 and
 0 6 | is reportable per Technical Specification 6.9.1.13(b). Since there is only
 0 7 | new fuel and no decay heat, the health and safety of the public were not
 0 8 | affected.

0 9 | | 9 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33
7 8 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 17 LER/RD REPORT NUMBER 21 EVENT YEAR 22 SEQUENTIAL REPORT NO. 23 OCCURRENCE CODE 24 REPORT TYPE 25 REVISION NO.
 ACTION TAKEN 22 FUTURE ACTION 23 EFFECT ON PLANT 24 SHUTDOWN METHOD 25 HOURS 26 ATTACHMENT SUBMITTED 27 NPROA FORM SUB. 28 PRIME COMP. SUPPLIER 29 COMPONENT MANUFACTURER
 0 | X | 18 | H | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 22 | N | 23 | Z | 24 | Z | 25 | 9 | 9 | 9 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 1 0 | A normally energized relay in the Solid State Protection System logic was
 1 1 | inadvertently de-energized closing an isolation valve and isolating the RCS
 1 2 | from the RHR system. The valve was manually opened and the responsible
 1 3 | personnel were cautioned to thoroughly investigate their work.

1 4 | | 20 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60
7 8 9 FACILITY STATUS 9 % POWER 10 OTHER STATUS 20 METHOD OF DISCOVERY 22 DISCOVERY DESCRIPTION 23
 1 5 | X | 28 | 0 | 0 | 0 | 29 | Mode 5 44 | A | 31 | Operator Observation 45
 ACTIVITY CONTENT 10 RELEASED OF RELEASE 11 AMOUNT OF ACTIVITY 25 LOCATION OF RELEASE 26
 1 6 | Z | 32 | Z | 34 | NA 44 | NA 45
 PERSONNEL EXPOSURES NUMBER 11 TYPE 12 DESCRIPTION 39
 1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA 39
 PERSONNEL INJURIES NUMBER 11 DESCRIPTION 41
 1 8 | 0 | 0 | 0 | 40 | NA 41
 LOSS OF OR DAMAGE TO FACILITY TYPE 11 DESCRIPTION 43
 1 9 | Z | 47 | NA 43
 PUBLICATION ISSUED DESCRIPTION 45
 2 0 | N | 44 | NA 45

NAME OF PREPARER R. W. Ouellette PHONE: (704) 373-75