DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242 1 7111 1 7 3 . .

WILLIAM O. PARKER, JR. VICE PRESIDENT STEAM PRODUCTION

Jane 5, 1981

TELEPHONE: AREA 704 373-4083

Mr. James P. O'Reilly, Director U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1 Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-81. This report concerns high groundwater level. This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

O. Parker Th. lyso William O. Parker, Jr.

RWO:pw Attachment

cc: Director

Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Ms. M. J. Graham NRC - Resident Inspector McGuire Nuclear Station

Mr. Bill Lavallee Nuclear Safety Analysis Center P. O. Box 10412 Palo Alto, CA 94303

DUKE POWER COMPANY McGUIRE NUCLEAR STATION INCIDENT REPORT

Report Number: RO-369/81-81

Report Date: June 4, 1981

Occurrence Date: May 8, 1981

Facility: McGuire Unit, Cornelius, N. C.

Identification of Occurrence: High groundwater alarm was received in the Control

Room (WZ System)

Condition Prior to Occurrence: Mode 5, Cold Shutdown

Description of Occurrence: A ground water level transmitter activated a high level alarm at 1615 hours on May 8, 1981. Level was 0.25 feet above slab elevation. This high level required increased surveillance per Technical Specification 4.7.13(b). Level was monitored at the accessible interior groundwater level monitoring stations. The alarm cleared at 1720 hours on May 8, 1981.

Apparent Cause of Occurrence: The apparent cause of the alarm was localized temporary high groundwater level.

Analysis of Occurrence: When the high level alarm was received, the proper surveillance was conducted, and within one hour the alarm cleared.

Corrective Action: No corrective action is required.

<u>Safety Analysis</u>: This event did not endanger the health or safety of the public. If it had occurred while the plant was at power and remained in the alarmed condition for seven days, plant shutdown would have been required.