



LER SUPPLEMENTAL INFORMATION

BFRO-50-259 / 81039 Technical Specification Involved 3.11.C.1

Reported Under Technical Specification 6.7.2.b(2) \*Date due NRC: 8/2/81

Date of Occurrence 7/3/81 Time of Occurrence: 0905 Unit 1

Identification and Description of Occurrence: While performing SI 4.11.C 3 & 4, the inverter control card for alarm panel XA-55-8E failed. It was tightened in its slot and began to operate. The next day while again performing SI 4.11.C 3 & 4, it became inoperable and power could not be restored.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 99%.

Unit 3 at 99%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe:

Met surveillance requirements of T.S. 3.11.C.2.

Apparent Cause of Occurrence:

Loss of power to panel XA-55-8E. Cause is unknown.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action: When power to panel first failed, the inverter card for panel XA-55-8E was tightened in its slot and the annunciator operated. The next day while again performing SI 4.11.C 3 & 4, the inverter again failed and power could not be restored. The inverter control card was replaced, successfully tested, and returned to service. This is considered a random failure and no further recurrence control is required.

Failure Data: BFRO-50-296/79015.

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: *ALL*