

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

ALBRF 2 000-00000-000 41111

REPORT SOURCE L 05000260 070881 072881

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During a maintenance outage, while performing level switch testing SI 4.1.A-8, prior to startup, the scram discharge instrument volume tank level switch 2-LS-85-45F (SDV 3-gallon alarm switch) failed to operate (NRC IE Bulletin 80-14.) The 25-gallon rod block and all 50-gallon scram switches were available and operable. There was no danger to the health or safety of the public. Previous similar events: BFR0-50-260/80052, 80758.

SYSTEM CODE I B 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE INSTRU 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 16

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The Robertshaw level switch model SL-305-EI-X was inoperable. The switch was back flushed and failed to operate. This is a newly installed switch, replaced 6/2/81 and will be repaired or replaced during a future outage.

FACILITY STATUS C 33 POWER 000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance testing.

ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 37 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 000 17 TYPE Z 35 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY ISSUED N 44 DESCRIPTION NA 45

NAME OF PREPARER Gene Holder PHONE (205) 729-6134

8108100252 810728 PDR ADOCK 05000260

GPO 817-926

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81035 Technical Specification Involved NRC LE Bulletin 80-14

Reported Under Technical Specification NRCB 80-14 *Date due NRC: 8/6/81

Date of Occurrence 7/8/81 Time of Occurrence 0245 Unit 2

Identification and Description of Occurrence:

During the performance of SI 4.1.A-8, level switch testing, prior to startup, the scram discharge volume tank level switch 2-LS-85-45F failed to operate.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 in maintenance outage.

Unit 3 at 98%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Inoperable switch.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Switch will be repaired or replaced during a future outage.

Failure Data: BFR. D-260/80058, 80052.

Retention: Period Lifetime; Responsibility - Document Control Supervisor

Revision: *AM*