


OFFICIAL COPY  
DCS  
(no externals)  
Return to Baer, JE



H. B. ROBINSON STEAM ELECTRIC PLANT  
Post Office Box 790  
Hartsville, South Carolina 29550

JUL 22 1981

Robinson File No: 2-0-4-a-9

Serial:RSEP/81-1151

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303



H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23

THIRTY DAY SPECIAL REPORT - FIRE BARRIER PENETRATION FIRE SEALS

Dear Mr. O'Reilly:

Carolina Power and Light Company (CP&L) submits the following thirty day special report as required by Technical Specifications (TS) 3.14.7.2.c. This specification requires that a special report be prepared if an inoperable fire barrier penetration seal is not restored to an operable condition within seven days. As of June 18, 1981, H. B. Robinson Unit No. 2 (HBR2) has had five fire barrier penetration seals in a degraded state, and therefore inoperable, for more than seven days. The required backup fire detectors have been verified operable which satisfies the compensatory action required by TS 3.14.7.2. The following is a description of the status of these five penetration seals.

Background

On May 15, 1981, NRC issued Amendment No. 57 to License No. DPR-23. This amendment updated the fire protection Technical Specifications to include operability and testing requirements for new fire protection systems and included a 7 day inoperability requirement for fire barrier penetration seals which was not in the previous Technical Specifications. At this time HBR2 was shutdown for a steam generator inspection outage.

On June 11, 1981, the unit went critical, and the seven day inoperability period described in TS 3.14.7.2 for the above seals began. On June 18, 1981, CP&L was required to submit this report pursuant to TS 6.9.3.g within the next 30 days. This report is being submitted beyond this 30 day period due to an administrative delay. This delay was discussed with Mr. C. Julian of Region II on July 20, 1981.

8108100263 810722  
PDR ADOCK 05000261  
S PDR

IE22  
5/10

Event

During a Control Room habitability inspection on June 8, 1981, while the plant was shutdown, five of eighteen fire barrier penetration seals in the Control Room floor were identified as not satisfying the approved configuration requirements of Maintenance Instruction 12, "Repair of Cable Penetrations". Specifically two problems were noted: 1) In two penetrations, FP-30 and FP-31, the open ends of conduits penetrating the seals were filled with Kao-wool mineral wool fiber material instead of the required BISCO Silicon RTV foam, and 2) In three cable tray penetrations, FP-33, 37 and 38, only one  $\frac{1}{2}$ -inch Marinite-I board was bolted to the bottom of these floor penetrations as a backing to the Kao-wool seal instead of the required two  $\frac{1}{2}$ -inch Marinite-I boards. These deficiencies apparently occurred during Modification 445-N implementation and were not identified during the post modification inspections.

The small open end conduit penetrations through cable tray penetration seals are unique to the Control Room. Modification 445-N did not address filling these conduits with BISCO Silicon RTV foam because the modification did not treat these conduit penetrations within the cable tray penetrations separately from the cable tray penetrations themselves.

Following the completion of Modification 445-N, CP&L initiated an inspection of conduit penetrations throughout the plant for review of the proper sealing configuration. The two Control Room conduit penetrations in question were inadvertently omitted from this list as they were considered part of the cable tray penetrations. All conduit penetration seals other than the two omitted from the list did meet the configuration requirements of MI-12.

The small clearances between the cable trays and the Control Room cable tray penetrations prevented the installation of the additional  $\frac{1}{2}$ -inch Marinite-I boards to FP-33, 37 and 38. A preliminary review of plant cable trays indicates that this situation does not exist elsewhere in the plant.

Because the five fire barrier penetration seals are located in Control Room cabinets it would be difficult to effect repairs without possibly compromising the control circuits for safe shutdown equipment. As a result, the earliest possible date for repairs is during the next scheduled refueling outage in late 1981. Operation in the interim with the five fire barrier penetration seals inoperable will not constitute a safety hazard for the following reasons:

1. The seals in their current configuration are nearly degraded and do provide a fire barrier.

Letter to Mr. James P. O'Reilly  
Serial:RSEP/81-1151  
Page 3

2. Penetration Seals FP-30 and FP-31 are small conduits between the Control Room and the old Unit No. 1 Cable Spread Room. Fire detection in both rooms is operable and should provide early warning of fires in these zones.
3. Penetration Seals FP-33, FP-37 and FP-38 are located between the Unit No. 2 Cable Spread Room and the NIS cabinets and RTGB in the Control Room. Fire detection in these areas is operable and should provide early warning of a fire. In addition, the Cable Spread Room contains a HALON 1301 Suppression System. All cables in the Cable Spread Room are coated with Intumastic 285 flame retardant material which would prevent the spread of any fire along cables in this zone. These factors, combined with the fact that there are almost no fixed or transient combustibles in the Cable Spread Room make it highly unlikely that a fire could occur of sufficient magnitude to reach the existing seals and create a significant hazard to safe shutdown capabilities.

HBR2 will repair the five fire barrier penetration seals during the next refueling outage, and will thereby be in full compliance with TS 3.14.7.2 before achieving criticality at the end of the 1981 refueling outage.

If you have any questions, please contact me or my staff.

Very truly yours,

*R. B. Starkey, Jr.*

R. B. Starkey, Jr.  
General Manager  
H. B. Robinson S.E. Plant

FMG/tm

cc: V. Stello