NRC FOF (7-77)	U.S. NUCLEAR REGULATORY COMMISSION
	CONTROL BLOCK:
0 1 7 8	$ \underbrace{ \begin{array}{c c c c c c c c c c c c c c c c c c c $
CON'T	REPORT L 6 0 5 0 - 0 3 2 5 0 0 7 0 6 8 1 8 0 7 2 8 8 1 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	During routine shutdown operations while running 1A RHRSW pump for shutdown cooling
03	it was discovered the pump was experiencing vibration in excess of normal. The pump
0 4	[was therefore declared inoperable. This event did not affect the health or safety of]
05	the public.
06	
0 7	
0 8 7 8	Technical Specifications 3.7.1.1a, 6.9.1.9b B0 9 SYSTEM CAUSE COMP. VALVE
09	$\begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \end{array} \\ \end{array} \\ \end{array} \end{array} \end{array} \end{array} \end{array} \xrightarrow{\begin{array}{c} \begin{array}{c} \end{array} } \\ \begin{array}{c} \end{array} \end{array} \end{array} \xrightarrow{\begin{array}{c} \end{array} } \\ \end{array} \end{array} \xrightarrow{\begin{array}{c} \end{array} } \\ \begin{array}{c} \end{array} \end{array} \xrightarrow{\begin{array}{c} \end{array} } \\ \end{array} \end{array} \xrightarrow{\begin{array}{c} \end{array} } \xrightarrow{\begin{array}{c} \end{array} } \\ \begin{array}{c} \end{array} \end{array} \xrightarrow{\begin{array}{c} \end{array} } \end{array} } \xrightarrow{\begin{array}{c} \end{array} } \xrightarrow{\begin{array}{c} \end{array} } \xrightarrow{\begin{array} } \end{array} } \xrightarrow{\begin{array}{c} \end{array} } \end{array} \end{array} \xrightarrow{\begin{array}{c} \end{array} } \xrightarrow{\begin{array} } \end{array} } \xrightarrow{\begin{array}{c} \end{array} } \end{array} \end{array} \xrightarrow{\begin{array}{c} \end{array} } \xrightarrow{\begin{array} } \end{array} } \xrightarrow{\begin{array} } \end{array} } \xrightarrow{\begin{array} } \end{array} \end{array} \end{array} \xrightarrow{\begin{array} } \end{array} \end{array} \xrightarrow{\begin{array} } \end{array} } \xrightarrow{\begin{array} } \end{array} } \xrightarrow{\begin{array} } \end{array} } \xrightarrow{\begin{array} } \end{array} } \end{array} \end{array} \xrightarrow{\begin{array} } \end{array} } \end{array} \xrightarrow{\begin{array} } \end{array} } \end{array} \end{array} \end{array} \end{array} \xrightarrow{\begin{array} } \end{array} } \end{array} \end{array} \end{array} $ } \end{array} } \end{array} } \end{array} } \end{array} } \end{array} } \end{array}
	Image: Description for the second
	TAKEN ACTION ON PLANT METHOD HOURS (22) CUBMITTED FORM SUB. SUPPLIER MANUFACTURER A 18 Z 19 Z 20 Z 20 Z 20 0 0 0 0 0 0 0 0 0 0 0 0
10	An inspection of the pump revealed that water in the pump bearings had caused abnormal
111	bearing wear which led to the elevated vibration. The pump bearings were replaced
12	and the pump was returned to operability. The RHRSW pumps of both units are checked
13	for vibration every 92 days by an operability PT. A review of plant documentation
14	SACILITY (30) METHOD OF DISCOVERY DESCRIPTION (32)
15	D 28 0 0 0 29 NA A 31 Operational Event
	0 10 12 13 44 45 46 80 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 <
17	PERSONNEL EXPOSURES NUMBER 0 0 0 0 37 Z 38 NA
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION (41)
7 8	
19	LOSS OF OR DAMAGE TO FACILITY (3) TYPE DESCRIPTION (3)
7 8	9 10 PUBLICITY ISSUED DESCRIPTION (45)
20	N (44) NA 68 69 80.5
B108 PDR	M. J. Pastva, Jr. 919-457-9521