

LER #: 50-366/1981-059, Rev. 1
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1981-059, Rev. 1

On 6-22-81, while operating at 86% power HNP-2-1050, Daily Channel Surveillance Checks, was performed. This procedure revealed that the postaccident torus water level indicator 2T48-R622A was reading approximately 25 inches higher than the redundant indicator 2T48-R622B. The indicator was declared inoperative per Tech Specs section 3.3.6.4.a. This is a nonrepetitive event. The cause of this event has been attributed to personnel error. A deviation from procedure HNP-2-3880M, Suppression Chamber Level Instruments, left a low fluid level in the reference log sensing line. MR 2-81-2723 was written to backfil the low sensing line on transmitter 2T48-N010A. The indicator was declared operative and returned to service.

Plant operation was not affected as a result of this event. The health and safety of the public were not affected. A generic review revealed that Unit 1 uses a different type of indicator.