LICENSEE EVENT REPORT

EIGENSEL EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
7 1 M D C C N 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
CON'T 0 1 REPORT L 6 0 5 0 0 0 3 1 7 7 0 7 0 1 8 1 8 0 7 3 1 8 1 9
[0] At 0215 during normal operation, containment Radiation Monitoring System
[0]3 [(RMS) pump tripped resulting in a loss of the gaseous and particulate
radiation monitors (T.S. 3.4.6.1). The gaseous and particulate moni-
tors were returned to service at 1500. The containment sump level
alarm system remained operable during the event. This is not a re-
o 7 petitive occurrence.
081
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
17 RL ORT 8 1
A lead normally energizing the High Flow Trip/Alarm time delay relay
broke at its relay termination lug. The break is due to fatigue caused
by wire flexure during operation and maintenance of the skid. No pre-
ventive action is currently deemed necessary as this is the first such
event and wiring is arranged properly in the allowed space. 80
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 8 8 29 NA A 4 45 46 46 46 46 46 46 46 46 46 46 46 46 46
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA NA LOCATION OF RELEASE (36) NA NA NA NA NA NA NA NA NA N
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA 1 7 0 0 0 0 37 Z 38 NA NA 80
Fahsonnel Induries NUMBER DESURIPTION (41) 1 8 0 0 0 0 40 NA NA NA NA
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA
PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA NA
8108110203 810731 PDR ADDCK 05000317 ER G. S. Pavis/P. G. Rizzo PHONE: (301) 269-4742/4786