## LICENSEE EVENT REPORT

Eldensee Event Heron 1
CONTROL BLOCK: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
7 8 9 LICENSEE CODE 14 18 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
REPORT LO 5 0 0 0 3 1 1 7 0 2 8 1 8 0 7 3 1 8 1 9  SOURCE LO 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80  EVENT DESCRIFTION AND PROBABLE CONSEQUENCES 10  O 2 0 July 2, 1981, the control operator placed No. 21 containment fan coil unit (CFCU)
in service. He noticed the service water flow rate was approximately 2100 gallons
per minute, which is less than the required flow rate of 2500 gallons per minute.
No. 21 CFCU was declared inoperable, and action statement 3.6.2.3.a was entered at
0 6   1710 hours on July 2, 1981.
7 8 9  SYSTEM CAUSE CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
SBU E 2 A 3 INSTRUM C 5 Z 6
SEQUENTIAL OCCUPRENCE REPORT REVISION NO CODE TYPE NO
NUMBER 21 22 23 24 26 27 28 29 30 31 32
TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURES (23) SUBMITTED FORM SUB. SUPPLIER MANUFACTURES (24) L 25 F 1 2 0
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  [1 [0]   The setpoint on No. 21 CFCU setpoint generator was incorrectly adjusted. It was
readjusted to an 85% setting. No 21 CFCU was tested satisfactorily and returned to
service. Action statement 3.6.2.3.a was terminated at 2010 hours on July 2, 1981.
113
TIE L
POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 5 B 28 0 3 0 29 N/A A 31 Operator Observation
ACTIVITY CONTENT 12 13 44 45 46 10 12 13 12 13 14 45 46 15 16 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18
7 8 9 10 11 44 45  PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 d ol ol 32 Z 38 NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION (43)
PUBLICITY ISSUED DESCRIPTION 45
2 10 NA 10 NA 68 69 80
8108110395 810731 PREPARER Frank Dickey PHONE 609-935-5100
PDR ADDCK 05000311 S PDR