

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSE CODE: A L J M F 1 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 4 5

REPORT SOURCE: L 6 0 5 0 0 0 3 4 8 7 0 7 1 2 1 1 8 1 1 2 0 1 8 0 5 1 8 1 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

As a result of an inadvertent actuation of the fire protection deluge system on cooling tower 2B, the levels in fire protection tanks A and B fell to approximately 230,700 gallons each at 1140 on 7-21-81. Unit 1 and 2 Technical Specifications require a minimum tank level of 250,000 gallons. Tech. Spec. 3.7.11.1 action statement requirements were met. Health/safety of the public was not affected. (NOTE: This LER is applicable to both Units 1 and 2 at FNP.)

SYSTEM CODE: A B 11 CAUSE CODE: A 12 CAUSE SUBCODE: X 13 COMPONENT CODE: Z Z Z Z Z Z 14 COMP. SUBCODE: Z 15 VALVE SUBCODE: Z 16

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The inadvertent actuation resulted during testing of the Unit 2 cooling tower fire protection air supervision pressure system. A test regulator should have been placed in a secured position; however, this was not done. Therefore, the regulator allowed the air supervision pressure to slowly decrease to the point where the clapper valve opened and the deluge system actuated. The tank levels were returned to minimum acceptable Technical Specification levels at 1218 on 7-21-81. A similar occurrence was reported in LER 81-038/OIT-0. Personnel involved in this incident have been instructed to verify that test equipment is properly isolated from affected systems during a break in test activities.

FACILITY STATUS: E 28 % POWER: 1 1 0 0 29 OTHER STATUS: NA 30 METHOD OF DISCOVERY: A 31 DISCOVERY DESCRIPTION: Operator Observation 32

ACTIVITY CONTENT: Z 33 RELEASED OF RELEASE: Z 34 AMOUNT OF ACTIVITY: NA 35 LOCATION OF RELEASE: NA 36

PERSONNEL EXPOSURES: 0 0 0 37 Z 38 DESCRIPTION: NA 39

PERSONNEL INJURIES: 0 0 0 40 DESCRIPTION: NA 41

LOSS OF OR DAMAGE TO FACILITY: Z 42 DESCRIPTION: NA 43