(7-77)	LICENSEE EVENT REPORT
	CON PLEASE PRINT OR TY ALL REQUIRED INFORMATION
0 1	N   15   G   S   1   2   0   0   0   0   0   0   0   0   0
ON'T	SOURCE LE DOCKET NUMBER 66 69 EVENT DATE 74 75 REPORT DATE 80  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During a routine containment inspection, service water leaks were discovered in No. 12
0 3	and 14 containment fan coil units (CFCU) cooling coils. The leaks were approximately
0 4	1.75 and 1.0 gallons per minute respectively. The leakage stopped by isolating the
0 5	service water to the CFCUs. Action statements 3.6.2.3.a and 3.6.2.3.b were entered
0 6	when the CFCU was isolated and declared inoperable on August 13, 1981.
0 7	
0 8	COMP VALVE
7 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE SHUTDOWN METHOD HOURS 22 ATTACHMENT FORM SUBMITTED F
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	The leakage was due to cooling coil failure. The leaking cooling coils were blank
111	flarged off and the CFCUs were tested satisfactory and returned to service. Action
1 2	statements 3.6.2.3.a and 3.6.2.3.b were terminated. (81-10, 81-11, 81-31, 81-39, 81-64)
1 3	
1 4	80
1 5	FACILITY STATUS  POWER  OTHER STATUS  OTHER
1 6	ACTIVITY CONTENT RELEASED OF RELEASE N/A  AMOUNT OF ACTIVITY 35 N/A  80
,	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  1 0 1 0 1 0 (37) Z (33) N/A
7	PERSONNEL INJURIES
1 8	0 0 0 0 0 0 N/A 80
1119	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION N/A
7	NRC USE ONLY
2 0	60 67
810 PDR S	7040207 810827 J. Varga PHONE: 609-935-5100 PHONE: PDR