

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | J | S | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T  
 0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 2 | 7 | 0 | 8 | 0 | 9 | 8 | 1 | 8 | 0 | 8 | 2 | 8 | 8 | 1 | 9 | \_\_\_\_\_ | 9  
60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90  
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On August 9, 1981, the control room operator noticed that there was no service water  
 0 3 | flow indication on No. 13 containment fan coil unit (CFCU). The CFCU was declared  
 0 4 | inoperable and action statement 3.6.2.3.a was entered at 0530 hours, August 9, 1981.  
 0 5 | \_\_\_\_\_  
 0 6 | \_\_\_\_\_  
 0 7 | \_\_\_\_\_  
 0 8 | \_\_\_\_\_

0 9 | SYSTEM CODE | S | B | 11 | CAUSE CODE | C | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP SUBCODE | T | 15 | VALVE SUBCODE | Z | 16 |  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
LER RC REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

17 | LER RC REPORT NUMBER | 8 | 1 | 21 | ACTION TAKEN | X | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NPSR-4 FORM SUB | N | 24 | PRIME COMP. SUPPLIER | N | 25 | COMPONENT MANUFACTURER | F | 1 | 2 | U | 26 |  
21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPSR-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Equipment failure. The low pressure side of flow transmitter FA-3543Z-1 was plugged  
 1 1 | with silt. Flow transmitter FA-3543Z-1 sensing line was blown clear and the trans-  
 1 2 | mitter was recalibrated satisfactorily. The No. 13 CFCU was tested satisfactorily  
 1 3 | and returned to service. Action statement 3.6.2.3.a was terminated at 1137 hours  
 1 4 | on August 9, 1981. (81-65, 81-66, 81-71)

1 5 | FACILITY STATUS | E | 28 | % POWER | 0 | 7 | 1 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | \_\_\_\_\_ | 31 | DISCOVERY DESCRIPTION | No service water flow indication. | 32 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | N/A | 43 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | N/A | 45 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60  
PUBLICITY ISSUED DESCRIPTION

8109090441 810828  
 PDR ADDCK 05000272  
 S PDR

NRC USE ONLY  
 \_\_\_\_\_  
68 69 80

NAME OF PREPARER: Frank Dickey PHONE: 609-935-5100