

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P | L | S | I | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

7 8 9 3 14 15 25 26 37 38

LICENSEE CODE LICENSE NUMBER LICENSE TYPE J0 JAT 58

CON'T

0 1 | R | E | P | O | R | T | S | O | U | R | C | E | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 5 | 7 | 0 | 8 | 0 | 2 | 8 | 1 | 3 | 0 | 8 | 3 | 1 | 8 | 1 | 9

7 8 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | DURING POWER OPERATION, A ROUTINE SURVEILLANCE SHOWED THAT PORV BLOCK

0 3 | VALVE MV1403 WOULD NOT CLOSE. MV1403 WAS MANUALLY CLOSED AND DEENERGIZED

0 4 | PER T.S.3.4.12. EXCESSIVE LEAKAGE THROUGH THE PACKING OF THE MV1403 RE

0 5 | SULTED IN A T.S. CHANGE REQUEST ALLOWING DE-ENERGIZING THE PORV AND BACK-

0 6 | SEATING MV1403. THIS REQUEST WAS APPROVED AND IMPLEMENTED ON AUG. 4.

0 7 | (THE HEALTH AND SAFETY OF THE PUBLIC WAS NOT AFFECTED. A PREVIOUS

0 8 | SIMILAR FAILURE OF A PORV BLOCK VALVE IS DESCRIBED IN LER 335-81-18.

7 8 9 30

0 9 | C | J | 11 | E | 12 | X | 13 | V | A | L | V | E | X | 14 | E | 15 | D | 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

17 | L | E | R | R | E | P | O | R | T | N | U | M | B | E | R | 8 | 1 | 21 | 22

18 | X | 19 | X | 20 | Z | 21 | Z | 22 | 0 | 3 | 9 | 23 | 0 | 3 | 24 | L | 25 | - | 26

18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

LETRID REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

18 | X | 19 | X | 20 | Z | 21 | Z | 22 | 0 | 3 | 9 | 23 | 0 | 3 | 24 | L | 25 | - | 26

18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM 50B PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | THE CAUSE OF THE FAILURE IS NOT KNOWN AT THIS TIME. THE CAUSE WILL BE

1 1 | DETERMINED AT THE TIME OF REPAIR (PRESENTLY SCHEDULED FOR THE REFUELING

1 2 | IN OCTOBER 1981.). POSSIBLE CAUSES INCLUDE PACKING BEING TOO TIGHT,

1 3 | BINDING IN THE VALVE, OR PROBLEMS WITH THE LIMITORQUE VALVE OPERATOR.

1 4 | A REVISION TO THIS LER WILL BE ISSUED WHEN THE CAUSE IS DETERMINED.

7 8 9 30

1 5 | E | 33 | 0 | 9 | 7 | 34 | NA | 30 | B | 31 | Operator Observation | 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 5 | Z | 33 | Z | 34 | NA | 35 | NA | 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

ACTIVITY CONTENT RELEASED OR RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | NA | 38

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 39 | NA | 40

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | NA | 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | NA | 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PUBLICITY DESCRIPTION NRC USE ONLY

NAME OF PREPARER P. L. Pace PHONE (305) 552-3654