LER

COOPER NUCLEAR STATION

Nebraska Public Power District

CNSS817125

August 25, 1981

Mr. K. V. Seyfrit U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region IV 611 Ryan Plaza Suite 1000 Arlington, Texas 76011

Dear Sir:

.

.

This report is submitted in accordance with Section 6.7.2.B.2 of the Technical Specifications for Cooper Nuclear Station and discusses a reportable occurrence that was discovered on July 28, 1981. A licensee event report form is also enclosed.

Report No.:	50-298-81-19
Report Date:	August 25, 1981
Occurrence Date:	July 28, 1981
Facility:	Cooper Nuclear Station
	Brownville, Nebraska 68321

Identification of Occurrence:

A condition occurred which resulted in operation in a degraded mode permitted by a limiting condition for operation established in Section 3.5.F.2 of the Technical Specifications.

Conditions Prior to Occurrence: The reactor was at 96% of rated thermal power.

Description of Occurrence:

During performance of Surveillance Procedure 6.'.12.1, to prove operability of #' Diesel Generator (DG) prior to making the 'B' loop of the containment cooling subsystem inoperable for maintenance, a fuel supply hose developed a leak. The DG was shut down and declared inoperable.

Designation of Apparent Cause of Occurrence: The fuel supply hose leak was caused by a combination of excessive localized flexure of the hose and vibration.



8109150172 810825 PDR ADDCK 05000298 S PDR Mr. K. V. Sovfrit August 25, 1981 Page 2.

Analysis of Occurrence:

The station's emergency power system consists of two emergency diesel generators, each capable of supplying power for post accident safety system operation and safe reactor cooldown.

The flexible fuel supply hose provides the connection between rigid fuel supply piping and engine mounted equipment. During the event in question, the hose started leaking. Had the DG been required under accident conditions, it would have continued to run with the leak; however, the engine was shut down during the test due to equipment safety considerations. Repair procedures were immedistely initiated and the hose was replaced within one hour.

2

63

During this event the normal, startup and emergency transformers were available to supply power as the station required. This event presented no adverse consequences to the public health and safety.

Corrective Action:

The fuel line was replaced immediately. The DG was tested and returned to service. During an outage scheduled to start in September 1981, the fuel line will be repiped to alleviate che sharp bend in the tubing and provide for better alignment.

Sincerely,

ł,

E Lesso

L. C. Lessor Station Superintendent Cooper Nuclear Station

LCL:cg Attach.