## LICENSEE EVENT REPORT

	LICENSEE EVENT HERONT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	M I D' C C 1 2 0 U 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5 CAT 58 5
CON'T	SOURCE L 6 0 5 0 0 0 8 0 4 8 1 8 0 9 0 3 8 1 9
0 2	WHILE REDUCING REACTOR POWER FROM 35% TO 8% IN PREPARATION FOR TURBINE OVERSPEED
0 3	TESTING, PRESSURIZER PRESSURE TWICE WITHIN A TEN-MINUTE PERIOD DROPPED BELOW THE MINI-
0 4	MUM PRESSURE LIMIT OF 2220 PSIA REQUIRED BY TECHNICAL SPECIFICATION 3.2.5. DURING THE
0 5	FIRST INSTANCE THE PRESSURE DROPPED TO 2210 PSIA FOR APPROXIMATELY TWO-MINUTES AND
0 6	DURING THE SECOND INSTANCE THE PRESSURE DROPPED TO 2198 PSIA FOR APPROXIMATELY THREE-
0 7	MINUTES. THERE WAS NO THREAT TO THE PUBLIC HEALTH AND SAFETY. PREVIOUS SIMILAR
0 8	EVENTS INCLUDE: DOCKET NUMBER 050316 - 81-23, 81-24, 80-1, 80-11, 78-43, 78-97,
0 9 7 8	SYSTEM CAUSE CAUSE SUBCODE SUB
	LER/RO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME GOMP SUPPLIER SUPPLIER SUPPLIER TO SUPPLIER SUPPL
10	BOTH TRANSIENTS WERE RESULTS OF TURBINE LOAD REDUCTION RATE BEING GREATER THAN REACTOR
	POWER REDUCTION RATE. BOTH THE TURBINE AND THE REACTOR WERE BEING CONTROLLED MANU-
1 2	ALLY. DURING THE FIRST INSTANCE AN OVERCORRECTION OF REACTOR POWER OCCURRED CAUSING
13	A DROP IN TAVE AND THE RESULTING DROP IN PRESSURIZER PRESSURE. DURING THE SECOND
1 4	INSTANCE THE HIGH TAVE CAUSED A MOMENTARY OPENING OF THE NO. 1 STEAM GENERATOR POWER
7 g	FACILITY STATUS  D 28 0 3 5 29 NA  OTHER STATUS  OPERATOR OBSERVATION  B0  OPERATOR OBSERVATION
	2 10 12 13 44 45 46 ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) AMOUNT OF ACTIVIT
1 7	PERSONNEL EXPOSURES NUMBER 0 0 0 37 Z 38 NA
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION (4)
7 8	0 0 0 40 NA 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	TYPE DESCRIPTION (43)  NA
2 0	PUBLICITY PDR ADDCK 05000315 NA S PDR ADDCK 05000315 PDR ADDCK 05000315
7 8	9 10 80 68 69 80 7

SUPPLEMENT TO LER NO. 81-034/03L-0

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

78-99, 78-73, 78-72. DOCKET NUMBER 050315 - NO PREVIOUS SIMILAR EVENTS ON UNIT ONE.

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

OPERATED RELIEF VALVE WHICH RESULTED IN A DROP IN TAVE AND PRESSURIZER PRESSURE.

TO PREVENT RECURRENCE, THIS EVENT WILL BE REVIEWED BY ALL LICENSED OPERATORS.