

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: ALBRF1; LICENSE NUMBER: 00-000000-000; LICENSE TYPE: 41111; CAT: 5

REPORT SOURCE: L; DOCKET NUMBER: 05000259; EVENT DATE: 081981; REPORT DATE: 091081

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: On 8/15/81, U-1 was in cold shutdown and U-2 and U-3 were in the run mode with start bus undervoltage relays out of service for the 1A and 1B start buses. (Ref. T.S. 3.9.B.10.) This event was also reported in BFRO-50-260/81043. There was no danger to the health or safety of the public. Redundant systems were available and operable. There were no previous similar events.

SYSTEM CODE: EE; CAUSE CODE: A; CAUSE SUBCODE: E; COMPONENT CODE: ZZZZZZ; COMP. SUBCODE: Z; VALVE SUBCODE: Z; LER/RO REPORT NUMBER: 81; EVENT YEAR: 81; SEQUENTIAL REPORT NO.: J45; OCCURRENCE CODE: 03; REPORT TYPE: L; REVISION NO.: 0; ACTION TAKEN: X; FUTURE ACTION: Z; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: Y; NPRD-4 FORM SUB.: N; PRIME COMP. SUPPLIER: L; COMPONENT MANUFACTURER: Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS: Personnel error. A modification activity removed the 1A and 1B start bus relays. During preliminary review of the modification workplan, it was not recognized that T.S. 3.9.B.10 did not permit this activity with the units in run mode. The relays were reconnected immediately on discovery of error. This is a random event, no further recurrence control required.

FACILITY STATUS: H; % POWER: 000; OTHER STATUS: NA; METHOD OF DISCOVERY: A; DISCOVERY DESCRIPTION: Operator observed

ACTIVITY CONTENT: Z; AMOUNT OF ACTIVITY: NA; LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES: 000; TYPE: Z; DESCRIPTION: NA

PERSONNEL INJURIES: 000; DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY: Z; DESCRIPTION: NA

PUBLICITY ISSUED: N; DESCRIPTION: NA