

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I	L	D	R	S	3	(2)	0	0	-	0	0	0	0	0	-	0	0	(3)	4	1	1	1	1	(4)			(5)	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER									25	26	LICENSE TYPE					30	31	CAT		33

REPORT SOURCE L 5 0 5 0 0 0 2 3 7 7 0 9 0 2 8 1 8 0 9 1 8 8 1 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

02 While performing routine surveillance DIS 500-2, vessel low low water level isolation

03 switch LIS 3-263-57B found to have a setpoint of 116.8 inches of water which exceeds

0	4	Tech. Spec. limit (Table 3.2.1) of 114.5 inches of water. Safety implications minimal.
---	---	----------------------------------------------------------------------------------------

05 because redundant level switches were operable to provide the necessary isolation

06 function. There was no effect on public health or safety. Previous occurrence:

67 Docket 50-249/80-16, 80-023/03L-0, 80-024/03L-0.

08

09		SYSTEM CODE I A 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14						COMP. SUBCODE S 15		VALVE SUBCODE Z 16	
7		9 10		11 12		12 13		13 18						19 20			
17		EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 2 2		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0							
LER/RO REPORT NUMBER		21 22		23 24		25 26		27 28		29 30		31 32					
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPR-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
E 18		Z 19		Z 20		Z 21		0 0 0 22		N 23		N 24		N 25		Y 0 1 0 26	
33 34		35 36		37 38		39 40		41 42		43 44		45 46		47 48		49 50	

1	0	Cause of event was attributable to instrument setpoint drift.
---	---	---------------------------------------------------------------

1	1	Instrument inspected and nothing abnormal found. Setpoint was immediately
---	---	---------------------------------------------------------------------------

1	2	adjusted to 112 inches water column and repeatability verified. Reactor level
---	---	-------------------------------------------------------------------------------

1	3	switches will continue to be tested monthly.
---	---	----------------------------------------------

1	4	
---	---	--

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	
1	5	G	0	0	0	NA	B	Surveillance Test	
7	8	9	10	11	12				

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 2 34 N/A

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES									
NUMBER				TYPE		DESCRIPTION			
1	7	0	0	(37)	Z	(38)	(39) N/A		

PERSONNEL INJURIES										
NUMBER				DESCRIPTION						
1	3	0	0	0	40	N/A				

1		9		3		10		80	
LOSS OF OR DAMAGE TO FACILITY (43)									
TYPE		DESCRIPTION							
Z (42)		N/A							

PUBLICATION		ISSUED		DESCRIPTION		NAC USE ONLY	
2	0	N	44	N/A			

NRC USE ONLY

PHONE: 815-942-2920 Ext. 548



Commonwealth Edison

DEVIATION REPORT

DVR NO.
STA UNIT YEAR NO.
D - 12 - 3 - 81 - 48

PART 1 TITLE OF DEVIATION
Rx Vessel Low Low Water Level Isolation LIS 3-263-57B Tripped Above
Tech. Spec. Limits

OCCURRED
9/2/81 1100
DATE TIMESYSTEM AFFECTED 260
Vessel Instrumentation

PLANT CONDITION:

MODE Refuel

PWR(MWT) 0

LOAD(MWE) 0

TESTING
☒ YES ☐ NO

DESCRIPTION OF EVENT
Found Rx vessel low low water level isolation switch to trip at 116.8" W.C. dp increasing, which
is 2.3 inches greater than Tech. Spec. Limit of 114.5 inches of water maximum.

DESCRIPTION OF CAUSE
F ind no problem with instrument during investigation via DIP 010-9.

OTHER APPLICABLE INFORMATION
Readjusted switch to trip at 112.4" W.C. dp increasing and verified repeatability. Other switch
in yarway unit for Rx scram operated satisfactorily.

EQUIPMENT ☐ YES
FAILURE ☒ NO

DR NO.

N/A

WR NO.

N/A

Alan R. Zapatocky

RESPONSIBLE SUPERVISOR

9/2/81

DATE

PART 2 OPERATING ENGINEERS COMMENTS

The switch was immediately reset, per Tech. Spec setpoints and repeatability verified.

TYPE OF DEVIATION
REPORTABLE OCCURRENCE☐ 14 DAY ☐ 10CFR21☒ 30 DAY NOTIFICATION
6.6.B.2.aEVENT OF POTENTIAL
PUBLIC INTERESTTECH SPEC
VIOLATIONNON-REPORTABLE
OCCURRENCEANNUAL
REPORTINGYES ☒NO ☐SAFETY-
RELATED
WR ISSUEDYES ☐NO ☒REPORTABLE OCCURRENCE
NUMBER

81-22/03L-0

ACTION ITEM NO.

PROMPT ON-SITE NOTIFICATION

R. M. Ragan

9/4/81

1030

TITLE

DATE

TIME

TITLE

DATE

TIME

24-HOUR NRC NOTIFICATION
N/A☐ TPH

REGION III

DATE

TIME

☐ TGM

N/A

REGION III & DOL

DATE

TIME

PROMPT OFF-SITE NOTIFICATION

F. A. Palmer

9/8/81

0836

TITLE

DATE

TIME

TITLE

DATE

TIME

RESPONSIBLE COMPANY OFFICER INFORMED OF 10CFR21
CONDITIONS AND THEIR REPORT TO NRC

TITLE

DATE

TIME

REVIEW AND COMPLETED

Michael Wright

9/4/81

OPERATING ENGINEER

DATE

ACCEPTANCE BY STATION REVIEW
AS REQUIRED

DATE

RESOLUTION APPROVED AND
AUTHORIZED FOR DISTRIBUTION

J. Brunner *Michael Wright*
9/21/81 9-21-81
Douglas J. Hunt
STATION SUPERINTENDENT

9/21/81
DATE