Bechtel Power Corporation

IE NOS

Engineers - Constructors

12400 East Imperial Highway Norwalk, California 90650 Mail Adoress P O. BOX 60660 - TERMINAL ANNEX, LOS ANGELES, CALIFORNIA 9006 TELEPHONE (213) 864-6011

September 21, 1981

Mr. Karl Seyfrit Director, Region IV Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

Subject: General Electric 4.16 KV Switchgear Containing Internal Wiring Which Violates Class 1E/Non-Class 1E Separation Requirements

Reference: Arizona Public Service 10 CFR 50.55(e) Report dated September 18, 1981. Palo Verde Nuclear Generation Station, Units 1, 2 and 3

Dear Mr. Seyfrit:

On September 18, 1981, Arizona Public Service, PVNGS 1, 2 and 3, informed Mr. B. H. Faulkenberry, Chief Reactor Construction and Engineering Support Branch, of the subject deficiency.

Subsequent evaluation by the Bechtel Review Committee concludes that the condition is also reportable under 10 CFR Part 21. The Arizona Public Service report contains all the information required by Part 21 with the exception of the information required by 21.21(b)(3) VI as it is unknown to Bechtel.

General Electric will be advised by letter that the component as applied by Bechtel contains a substantial safety hazard defect and will be requested to review the information supplied by Bechtel and determine its responsibility for compliance to Part 21, Section 21.21(b)(3) VI.

Other Bechtel Divisions were advised of the defect by copies of appropriate reports and correspondence. Should it be determined that basic components with this defect are in use, have been supplied to or are being supplied for one or more other Bechtel projects, the affected Division will report the condition according to the Regulation.

Sincerely,

BECHTEL POWER CORPORATION

R. L. Patterson 69 toutourent Manager of Division Quality Assurance

TE31

5

RLP: JHS: db

