

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | J | M | F | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
3 9 14 15 25 26 30 37 38
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

REPORT SOURCE | L | 5 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 4 | 7 | 0 | 9 | 2 | 3 | 8 | 1 | 3 | 1 | 0 | 1 | 6 | 8 | 1 | 9
60 61 66 69 74 75 80
 SOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1940 on 9/23/81, the plant stack effluent monitor (R29B) was declared inoperable due
 0 3 | to a data transmit error. At 2235 on 9/23/81, the 120 VAC vital bus 2A was deenergized
 0 4 | when inverter 2A tripped. Tech. Spec. 3.3.3.1, in part, requires R29B to be operable.
 0 5 | Tech. Spec. 3.8.2.1 requires the 2A inverter to be operable. Tech. Spec. action statement
 0 6 | requirements were met. Health/safety of the public was not affected.
 0 7 |
 0 8 |

0 9 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE
9 10 11 12 13 14 15 16 17 18 19 20
 M C (11) E (12) G (13) I N S T R U (14) P (15) Z (16)

17 | LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.
21 22 23 24 25 26 27 28 29 30 31 32
 8 1 | — | 0 4 0 | / | 0 3 | L | — | 0

ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRO-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
 X (18) Z (19) Z (20) Z (21) 0 0 0 0 | N (22) | N (23) | N (24) | N (25) | W 1 2 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause for the transmit error on R29B was being investigated at the time the 2A
 1 1 | inverter tripped. As a result of loss of power to the consoles the cause for the trans-
 1 2 | mit error could not be determined. The inverter tripped due to a transient voltage spike
 1 3 | and was reset and returned to service at 0010 on 9/24/81. Because of the loss of power to
 1 4 | the R29B consoles, the unit required complete reprogramming following restoration of power,
 R29B was subsequently returned to service at 0900 on 9/24/81.

1 5 | FACILITY STATUS | % POWER | OTHER STATUS (30) | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION (32)
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 E (28) 1 0 0 (29) NA | A (31) Operator observation

1 6 | ACTIVITY CONTENT | RELEASED OF RELEASE | AMOUNT OF ACTIVITY (35) | LOCATION OF RELEASE (36)
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 Z (33) Z (34) NA | NA

1 7 | PERSONNEL EXPOSURES | NUMBER | TYPE | DESCRIPTION (39)
11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 0 0 0 (37) Z (38) NA

1 8 | PERSONNEL INJURIES | NUMBER | DESCRIPTION (41)
11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 0 0 0 (40) NA

1 9 | LOSS OF OR DAMAGE TO FACILITY | TYPE | DESCRIPTION (43)
11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 Z (42) NA

2 0 | PUBLICITY | ISSUED | DESCRIPTION (45)
11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 N (44) NA

8110290367 811016
 PDR ADOCK 05000364

NAME OF PREPARER: W. G. Hairston, PDR

PHONE: (205)899-5156

NRC USE ONLY