

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | C | B | E | P | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 C.A.I. 58

CON'T
0 1 | L | 0 | 5 | 0 | - | 0 | 3 | 2 | 4 | 1 | 1 | 0 | 4 | 8 | 1 | 1 | 0 | 2 | 2 | 8 | 1 | 1
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | During routine surveillance it was discovered that suppression chamber water level
0 3 | recorder, 2-CAC-LR-2602, model No. BQH, was showing a downscale indication of level
0 4 | while the other Control Room suppression chamber water level indicators showed a
0 5 | normal level. This event did not affect the health and safety of the public.
0 6 |
0 7 |

0 8 | Technical Specifications 3.3.5.3, 6.9.1.9b
7 8 9 80

0 9 | SYSTEM CODE: I | E | 11 | CAUSE CODE: A | 12 | CAUSE SUBCODE: C | 13 | COMPONENT CODE: I | N | S | T | R | U | 14 | COMP. SUBCODE: R | 15 | VALVE SUBCODE: Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 | LER/RO REPORT NUMBER: 8 | 1 | 22 | EVENT YEAR: 8 | 1 | 21 | 22 | SEQUENTIAL REPORT NO.: - | 23 | 24 | OCCURRENCE CODE: / | 27 | 28 | REPORT TYPE: 0 | 3 | 29 | 30 | REVISION NO.: - | 31 | 32
18 | ACTION TAKEN: B | 18 | 33 | FUTURE ACTION: - | 19 | 34 | EFFECT ON PLANT: Z | 20 | 35 | SHUTDOWN METHOD: Z | 21 | 36 | HOURS: 0 | 0 | 0 | 0 | 22 | 37 | 40 | ATTACHMENT SUBMITTED: N | 23 | 41 | 42 | NPRD-4 FORM SUB.: Y | 24 | 42 | PRIME COMP. SUPPLIER: N | 25 | 43 | COMPONENT MANUFACTURER: B | 1 | 3 | 5 | 26 | 44 | 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | The recorder input signal cable had been pulled from the recorder input
1 1 | terminal causing the downscale indication. It is believed technicians working in the
1 2 | vicinity of the cable accidentally pulled it from the terminal. The cable was properly
1 3 | terminated and the recorder was returned to service showing expected indication of
1 4 | level. All I&C technicians will review this report to ensure their awareness of this
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 event.

1 5 | FACILITY STATUS: E | 28 | 7 8 9 | % POWER: 0 | 5 | 3 | 29 | 10 11 12 13 | OTHER STATUS: NA | 30 | 44 | METHOD OF DISCOVERY: A | 31 | 45 | 46 | DISCOVERY DESCRIPTION: Routine Surveillance | 32 | 40

1 6 | ACTIVITY CONTENT: Z | 33 | 7 8 9 | RELEASED OF RELEASE: Z | 34 | 10 11 | AMOJNT OF ACTIVITY: NA | 35 | 44 | LOCATION OF RELEASE: NA | 36 | 45 46 47 48 49 50

1 7 | PERSONNEL EXPOSURES NUMBER: 0 | 0 | 0 | 37 | 7 8 9 | TYPE: Z | 38 | 10 11 | DESCRIPTION: NA | 39 | 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 | PERSONNEL INJURIES NUMBER: 0 | 0 | 0 | 40 | 7 8 9 | DESCRIPTION: NA | 41 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z | 42 | 7 8 9 | DESCRIPTION: NA | 43 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 | PUBLICITY ISSUED DESCRIPTION: N | 44 | 7 8 9 | 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
8111030294 811022
PDR ADCK 0500024
S PDR