

LICENSEE EVENT REPORT

CONTROL BLOCK: [][][][][][][][] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [G][A][E][I][H][L] (2) [0][0]-[0][0][0][0][0]-[0][0] (3) [4][1][1][1][1] (4) [][][] (5)
7 8 9 14 15 25 26 30 57 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T [0][1] REPORT SOURCE [L] (6) [0][5][0][0][0][3][2][1] (7) [1][0][0][9][8][1] (8) [1][0][2][0][8][1] (9)
7 8 60 61 68 69 74 75 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[0][2] [0][3] [0][4] [0][5] [0][6] [0][7] [0][8] [0][9]
During steady state power operation the site discovered the HNP-1 & 2 torus-to-rx. bldg. d.p. sw., 1T48-N210, N211, 2T48-N210 and N211 respectively, had proof press. of 10 & 20 PSIG respectively. This results in inoperability of the sw. (T.S. 3.7.A.3 (HNP-1) and 3.6.4.2 (HNP-2)) and a potential loss of prim. cont. integrity (3.7.8.2 (HNP-1) and 3.6.1.1 (HNP-2)). Neither plant operation nor the health or safety of the public was affected. This is a non-repetitive event.

[0][9] SYSTEM CODE [S][H] (11) CAUSE CODE [B] (12) CAUSE SUBCODE [A] (13) COMPONENT CODE [I][N][S][T][R][U] (14) COMP. SUBCODE [S] (15) VALVE SUBCODE [Z] (16)
7 8 9 10 11 12 13 18 19 20
LER/RO REPORT NUMBER [8][1] (17) EVENT YEAR [8][1] SEQUENTIAL REPORT NO. [1][1][2] OCCURRENCE CODE [0][1] REPORT TYPE [T] REVISION NO. [0]
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN [F] (18) FUTURE ACTION [F] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS [0][0][0] (22) ATTACHMENT SUBMITTED [Y] (23) NPRD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [A] (25) COMPONENT MANUFACTURER [B][0][6][9] (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[1][0] [1][1] [1][2] [1][3] [1][4]
The cause of this event has been attributed to mis-application of sw. during initial design. The HNP-2 DP sw. were replaced with Barton sw. which have acceptable proof press. The HNP-1 DP sw. were replaced with a single Barton sw. The unit was S/D prior to expiration of the 7 day LCO for the fuel recon. outage. Both HNP-1 DP sw. will be replaced.

[1][5] FACILITY STATUS [E] (28) % POWER [0][4][5] (29) OTHER STATUS NA (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION Engineering Evaluation (32)
7 8 9 10 12 13 44 45 46 80
ACTIVITY RELEASED [Z] (33) CONTENT [Z] (34) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)
7 8 9 10 11 44 45 80
PERSONNEL EXPOSURES NUMBER [0][0][0] (37) TYPE [Z] (38) DESCRIPTION NA (39)
7 8 9 11 12 13 80
PERSONNEL INJURIES NUMBER [0][0][0] (40) DESCRIPTION NA (41)
7 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION NA (43)
7 8 9 10 80
PUBLICITY ISSUED [N] (44) DESCRIPTION NA (45)
7 8 9 10 80

8111030536 811020
PDR ADDCK 05000321
S PDR

NRC USE ONLY

NAME OF PREPARER: C. L. Coggin - Supt. Plt. Eng. Serv. PHONE: 912-367-7851

3 P O 51 7-925

LER #: 50-321/1981-112
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-321

Narrative Report
for LER 50-321/1981-112

On October 9, 1981, while the plant was in steady state operation, the site discovered the HNP-1 and 2 Torus-to-Rx. Bldg. diff. press. switches 1T48-N210 and N211 made by Barksdale and 2T48-N210 and N211 made by static o-ring had proof pressures of 10 psig and 20 psig respectively. This results in technical inoperability of the switches which is required per Tech Specs (HNP-1) 3.7.A.3 and (HNP-2) 3.6.4.2 and a potential loss of primary containment integrity which is required per Tech Specs (HNP-1) 3.7.8.2 and (HNP-2) 3.6.1.1. Neither plant operation nor the health or safety of the public was affected. This is a non-repetitive event.

The cause of this event has been attributed to mis-application of switches due to oversight in initial design. The HNP-2 diff. press. switches were replaced with Barton switches that have an acceptable proof pressure. The HNP-1 diff. press. switches were removed and replaced with a single Barton switch. The unit was shutdown prior to expiration of the 7 day LCO, for the scheduled fuel reconstitution outage. Both HNP-1 diff. press. switches will be replaced prior to startup.