

November 30, 1981

In reply, please
refer to LAC-7933

DOCKET NO. 50-409

Director of Nuclear Reactor Regulation
ATTN: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
INFORMATION REQUEST REGARDING STATION BLACKOUT,
UNRESOLVED SAFETY ISSUE A-44

REFERENCE: (1) NRC Letter, Crutchfield to Linder,
dated July 20, 1981.

Gentlemen:

Enclosed is the information requested by Reference 1, containing data for the years 1976 through 1980, inclusive. The information is provided on the four attached tables: (1) Diesel Generator Operations Data; (2) Diesel Generator Down Time Record; (3) Diesel Generator Unscheduled Down Time Record; and (4) Onsite Emergency Diesel Generator and Auxiliary Equipment Modification Record.

Also, enclosed are copies of Licensee Event Report (LER) documentation. The items listed as numbers 4 and 7 are not indicated on Enclosure 2 of Reference 1.

If there are any questions regarding this letter, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE


Frank Linder
Frank Linder, General Manager

FL:GSB:af

Enclosure

cc: J. G. Keppler, Regional Director, NRC-DRO, Region III
NRC Resident Inspector

8112080257 811130
PDR ADDCK 05000409
F PDR



A050
s
1/1

TABLE 1 Diesel Generator Operations Data
Calendar Year 1976-80

Reason for DG Operation, & Scheduled Duration of Run Tech, Spec Req'd Test	DG No.	Number of Starts	Number of Failures	Percent Loading of DG (KW)	Duration of Run Before Stop For Each DG Failure	Identification of Failure (Refer to attached LERs or Table 1)
Bi-weekly	1A	19	0	40%	0 Hrs.	
	1B	6	1	75%	12 Hrs.	LER #1
Monthly	1A	55	1	40%	12 Hrs.	LER #3
	1B	56	1	75%		LER #6
Daily	1A	5	0	40%	0 Hrs.	
	1B	8	0	75%	0 Hrs.	
Annual + 18 Mo.	1A	6	0	40%	0 Hrs.	
	1B	7	0	75%	0 Hrs.	
Annual + 18 Mo.		162	3			
DG Actual Demand Starts not for Testing	1A	14	0	59%	0 Hrs.	
	1B	8	0	55%	0 Hrs.	
		22	0			
Miscellaneous Tests (Specify Type)	1A	31	0	40%	0 Hrs.	
	1B	14	1	75%	1 Hr.	LER #6
After Maintenance Has Been Performed	1A	6	0	40%	0 Hrs.	
	1A	24	3	40%	24½ Hrs., 14½ Hrs.	LER #4
Severe Weather Operational Checks	1B	12	1	75%	10 Min SD	LER #1
	1A	5	0	40%	0 Hrs.	
Special Test	1B	4	0	75%	0 Hrs.	

Diesel Generator Scheduled Downtime Record
Calendar Year 1976-80

Plant Name LACBWR

Unit No. #1

[illegible]

Diesel Generator Scheduled Downtime Record
Calendar Year 19 76-80

Unit No. #1

[illegible]

TABLE 3

Diesel Generator Unscheduled Downtime Record
Calendar Year 19 76-80

Enclosure 1 - Page 3
Plant Name TACBWR
Unit No. #1

LER Abstract No. (Refer to attached LER Abstracts)	Downtime Hours				Comments - If any of the reported failures would not have been a failure under emergency conditions, please explain here. Refer to attached LERs or the failures listed in Table 1.
	Total Hours	Trouble-shooting	Parts, Delivery, etc.	Repair/replace	
1.	12 Hrs	12 Hrs.	-	-	1. Diesel unavailable.
2.	7 Hrs	-	-	2 Hrs.	2. Except for 2 hrs (1 Hr per tank) the diesels were available.
3.	7 Hrs	7 Hrs	-	2 Hrs.	3. The test load closed-in in excess of 10 secs (13 secs) Electrical Maintenance troubleshoot problem. The diesel was available all this time.
4.	24½ Hrs.	24½ Hrs.	-	24½ Hrs	4. Diesel unavailable.
5.	1 Hr. 12Min.	- 12Min.	-	1 Hr.	5. Diesel unavailable.
6.	82½ Hrs	82 Hrs	-	½ Hr.	6. Diesel Unavailable.
7.	-	-	-	-	7. Available throughout the whole sequence.

TABLE 4

Onsite Emergency Diesel Generator and
Auxiliary Equipment Modification Record

Enclosure 1 - Page 4
Plant Name LACBWR
Unit No. #1

Equipment or procedure modified	Date of Mod.	Reason for Modification and Desired Improvement	Description of Modification
1A Diesel Generator	10/75	Improve Reliability and Availability of ECCS	FC#74-27 - Emergency Diesel Generator Low Water Level Start.
1A Diesel Generator	9/74	Eliminate overheating after diesel has shutdown.	FC#74-29 - Emergency Diesel Generator Hi Temperature Lockout.
1B Diesel Generator	8/76	To add a redundant emergency power system for LACBWR requirements.	FC#75-12 - Addition of 1B Diesel Generator Building.
1B Diesel Generator	8/76	To meet ECCS Requirements.	FC#75-26 - Add HPSW Well H ₂ O Service air to diesel building.
1B Diesel Generator	2/76	To permit filling oil storage tank with transfer pump from 20,000 gal. tank.	FC#75-33 - Fuel oil fill line to new diesel.
Diesel Generators	8/76	To maintain adequate fuel levels and to provide sampling capabilities.	FC#76-27 - Fuel oil tanks level transmitters relocation and recalibration.
1A Diesel Generator	6/77	Additional information to operators	FC#77-08 - Add low H ₂ O temperature and low voltage alarm to diesel generator.
1B Diesel Generator	8/77	NRC Requirement Operator information	FC#77-15 - Add Power "ON" lite in control room from D.G. 1B.
1A Diesel Generator	1/78	To prevent high D/P across solenoid valve which prevented valve from opening.	FC#78-01 - Diesel generator 1A fuel solenoid valve.
1B Diesel Generator	3/78	NRC Requirement - Change actuation signal to building Hi-Pressure switch.	FC#78-02 - Containment pressure switch for 1B HPCS pump and 1B diesel.
1B Diesel Generator	5/78	To allow flushing the header every 6 months as per Tech. Spec. Req.	FC#78-08 - Flush valve in 1B diesel generator building at fire hose 5F.

TABLE 4

Onsite Emergency Diesel Generator and
Auxiliary Equipment Modification Record

Enclosure 1 - Page 4

Plant Name LACBWRUnit No. #1

Equipment or procedure modified	Date of Mod.	Reason for Modification and Desired Improvement	Description of Modification
1A Diesel Generator	10/78	NRC Requirements - Operator Information	FC#78-10 - Install separate alarm in control room for 1A diesel out of "auto".
Diesel Generators	4/80	Isolates identified fire zones.	FC#79-10 - Fire Penetration Barriers
1B Diesel Generators	4/80	Rewire Power from the Diesel Building MCC to the TB MCC 1A Aux. Dist. Panel	FC#79-19 - Change 1B Diesel Fire Protection Power from 1B diesel to TB MCC 1A Aux. Panel
Diesel Generator	N/A	Cancelled by ORC 4/3/80 78-80-2 has replaced this Facility Change.	FC#79-23 Install fuel oil shutdown valve in 1A diesel generator supply.
Inverter 1-C	4/80	Information to operators	FC#78-80-1 Install loss of voltage alarm from inverter 1-C.
1A Diesel Generator	4/80	Switch to be located outside 1A Diesel Room to prevent inadvertent operation.	FC#78-80-2 Install electrical shutoff switch in fuel oil PM of 1A Diesel Generator.
1A Diesel Generator	2/81	Seismic Upgrade Program	FC#78-81-3 Anchor 1A Diesel Generator
Battery Rooms	8/77	NUREG 75/987 Section 9.5.1 Local and remote indications of H ₂ Concentrations.	FC#77-16 Install H ₂ Alarms in Battery Room.
1A Diesel Generator	4/81	Upgrade Fire Protection System	FC#06-80-1 Install sprinklers in 1A Diesel Generator Room
Diesel Generators	12/80	Upgrade Fire Protection System	FC#06-80-2 Install curbs in 1A and 1B Diesel Rooms
1B Diesel Generator	4/81	Upgrade Fire Protection System	FC#06-80-5 - Modify 1B Diesel Generator CO ₂ System to remote manual actuators.

LA CROSSE BWR 050-0409
EMERG GENERATOR SYS + CONTROLS 015984
ENGINES, INTERNAL COMBUSTION
DESIGN/FABRICATION ERROR

091576
101476
30-DAY

(76-9) DURING A SURVEILLANCE TEST THE 1B EMERGENCY DIESEL GENERATOR FAILED TO CARRY THE FULL TEST LOAD. THE 1A DIESEL GENERATOR WAS TESTED TO VERIFY OPERABILITY. THE CAUSE WAS DETERMINED AND CORRECTED AND A SATISFACTORY TEST PERFORMED.

LA CROSSE BWR 050-0409
EMERG GENERATOR SYS + CONTROLS 016302
ENGINES, INTERNAL COMBUSTION
EXTERNAL CAUSE

111776
111676
24-HOUR

(76-15) EMERGENCY DIESEL GENERATOR FUEL OIL SAMPLES DID NOT MEET THE TECH SPEC REQUIREMENTS FOR WATER AND SEDIMENT CONTENT. SAMPLE FROM BOTTOM OF TANK INDICATED 3.1% BY VOLUME. LIMIT IS 0.05%.

THE OIL WILL BE REPLACED AND TESTED PRIOR TO STARTUP.

LA CROSSE BWR 050-0409
EMERG GENERATOR SYS + CONTROLS 017027
HEATERS, ELECTRIC
COMPONENT FAILURE

120376
010377
30-DAY

(76-16) DURING ROUTINE SURVEILLANCE TEST, STARTING TIME OF EMERG. DIESEL -GEN. 1A EXCEEDED TECH. SPEC. LIMIT DUE TO LOW COOLANT TEMPERATURE. ELECTRIC COOLANT HEATER WAS INOPERATIVE DUE TO LOOSE WIRE. FOLLOWING REPAIRS THE UNIT RETESTED SATISFACTORILY. THE REDUNDANT DIESEL GENERATOR WAS NOT AFFECTED BY THIS EVENT. COMBINATION OF VIBRATION AND INCOMPLETE TERMINAL LUG CRIMP ON POWER LEAD TO HEATER ELECTRODE.

LA CROSSE BWR 05000409
AC ONSITE POWER SYS + CONTROLS 77-007/03L-0
COMPONENT CODE NOT APPLICABLE 020180
SUBCOMPONENT NOT APPLICABLE
DESIGN/FABRICATION ERROR
DESIGN
ITEM NOT APPLICABLE

122077
010578
30-DAY

EMERGENCY DIESEL GENERATOR 1A DID NOT OPERATE CONTINUOUSLY UPON PROMPT AUTOMATIC RESTART FOLLOWING SATISFACTORY MANUAL OPERATION. PLANT WAS IN SHUTDOWN STATUS DURING CONDUCT OF EMERGENCY DIESEL GENERATOR TESTS.

DESIGN DEFICIENCY IN LOCATION OF FUEL CUTOFF SOLENOID VALVE INTRODUCED PRESSURE DIFFERENTIAL PREVENTING VALVE OPENING. VALVE WAS RELOCATED AND SYSTEMS AND EQUIPMENT TESTED SATISFACTORILY.

LA CROSSE BWR 05000409
EMERG GENERATOR SYS + CONTROLS 78-010/03L-0
COMPONENT CODE NOT APPLICABLE 023247
SUBCOMPONENT NOT APPLICABLE
OTHER
NOT APPLICABLE
ITEM NOT APPLICABLE

081178
091578
30-DAY

1A DIESEL GENERATOR WAS TAKEN OUT OF SERVICE FOR ONE HOUR AND TWELVE MINUTES DURING REACTOR OPERATION TO CHANGE ENGINE SUMP LUBE OIL. LUBE OIL WAS DILUTED WITH DIESEL FUEL OIL. 1B DIESEL GENERATOR AND OTHER A.C. SOURCES REMAINED OPERABLE TO PROVIDE REQUIRED BACKUP A.C. ELECTRICAL POWER.

PARTIAL DILUTION OF LUBE OIL ATTRIBUTED TO RESIDUAL FUEL OIL IN INJECTOR S. FOLLOWING OIL CHANGE, TECHNICAL SPECIFICATION SURVEILLANCE TESTING WAS AS PERFORMED ON BOTH DIESEL GENERATORS TO VERIFY OPERABILITY. ADDITIONAL SAMPLING BY IMPROVED PROCEDURES WILL BE PERFORMED TO PROVIDE FURTHER BASIS FOR ACCEPTANCE CRITERIA AND DETERMINATION OF RATE OF DILUTION. DURING CONDUCT OF PRIMARY REACTOR CONTAINMENT TYPE A LEAKAGE TEST, THE M

LA CROSSE BWR 05000409
AC ONSITE POWER SYS + CONTROLS 78-014/03L-0
INSTRUMENTATION + CONTROLS 023505
SENSOR/DETECTOR/ELEMENT
COMPONENT FAILURE
ELECTRICAL
SYNCHRO START PRODUCTS

121578
011879
30-DAY

DURING A ROUTINE SURVEILLANCE TEST ON THE 1B EMERGENCY DIESEL GENERATOR, THE UNIT TRIPPED ON INDICATED OVERSPEED. SUBSEQUENT RESTARTS WERE SATISFACTORY AND THE SURVEILLANCE FREQUENCY WAS INCREASED. THE PROBLEM WAS DUPLICATED ON DECEMBER 18, 1978. THE UNIT WAS DECLARED INOPERABLE TO PERMIT REPAIRS (TECH. SPEC. 5.2.10.1.1.2.A). THE REDUNDANT DIESEL GENERATOR WAS OPERATED AT INCREASED SURVEILLANCE FREQUENCY PER TECH. SPEC. 4.2.3.1.1. ACTION A. THE ELECTRIC OVERSPEED SWITCH REQUIRED READJUSTMENT AS IT WAS SET AT 1980 RPM INSTEAD OF 2010-2015 RPM. THE LOWER SETPOINT CAUSED OVERSPEED TRIPS ON THE INITIAL COLD START ONLY. THE SWITCH SETPOINT WAS READJUSTED BY A REPRESENTATIVE OF THE MANUFACTURER. A SCHEDULE OF INCREASED SURVEILLANCE WAS IMPLEMENTED. PERIODIC LEAKAGE RATE TESTING REVEALED ELECTRICAL PENETRATION UNIT NO.

REPORT SOURCE 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

THE RESULTS OF A ROUTINE SURVEILLANCE TEST ON FUEL OIL SAMPLES FROM THE
TANKS SUPPLYING THE 1A HPSW PUMP, 1B HPSW PUMP AND THE 1B EMERGENCY DIES
EL GENERATOR INDICATED WATER AND SEDIMENT CONCENTRATIONS OF 0.1% COMPARE
D TO A TECHNICAL SPECIFICATION LIMIT OF 0.05% (SECTIONS 5.2.18.1.2.c AND
5.2.10.1.1.2.b). SIMILAR OCCURRENCE RO-76-15. THE ELECTRIC DRIVEN HIGH
PRESSURE SERVICE WATER PUMP AND THE 1A EMERGENCY DIESEL GENERATOR WERE
AVAILABLE AND OPERABLE.

SYSTEM CODE 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

EACH OF THE FUEL OIL TANKS WERE RESAMPLED AT THREE ELEVATIONS PRIOR TO PARTIAL PURGING. THE TANK TRUCK WAS ALSO SAMPLED AS WELL AS EACH TANK FOLLOWING REPLENISHMENT. ALL SAMPLES INDICATED WATER AND SEDIMENT LEVELS BELOW 0.02%. THE SAMPLING TECHNIQUE AND PROCESSING METHODS ARE BEING EXAMINED TO DETERMINE IF CHANGES ARE WARRANTED TO REDUCE THE POTENTIAL FOR SAMPLE CONTAMINATION.

FACILITY STATUS 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

Dupe 7901290261