Georgia Power Company * 333 Piedmont Avenue Atlanta. Ceorgia 30308 Teleptic ne 404 526 3195

• •

Mailing Address: 40 Inverness Center Parkway Post Office Box 1295 Birmingham, Alabama 35201 Telephone 205 868 5581

December 19, 1989

the southern electric system

W. G. Hairston, III Senior Vice President Nuclear Operations

> ELV-01147 0160

Docket No. 50-425

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555

Gentiemen:

VOGTLE ELECTRIC GENERATING PLANT LICENSEE EVENT REPORT PERSONNEL ERROR LEADS TO CONTAINMENT VENTILATION ISOLATION

In accordance with 10 CFR 50.73, Georgia Power Company hereby submits the enclosed report relating to an event which occurred on November 26, 1989.

Sincerely,

W.S. Mant The

W. G. Hairston, II)

WGH, III/NJS/gm

Enclosure: LER 50-425/1989-030

xc: Georgia Power Company Mr. C. K. McCoy Mr. G. Bockhold, Jr. Mr. P. D. Rushton Mr. R. M. Odom NORMS

8912270162 891219 PDR ADDCK 05000425

<u>U. S. Nuclear Regulatory Commission</u> Mr. S. D. Ebneter, Regional Administrator Mr. J. B. Hopkins, Licensing Project Manager, NRR Mr. J. F. Rogge, Senior Resident Inspector, Vogtle

TERN

NRC*5orm 366 (9-62)		uc	ENSEE EVI	NT RE	PORT	(LER)	U.\$. NU	CLEAR REGUL APPROVED ON EXPIRES 8/31/	270RY COM 28 NO 3150-0 86	MISSION
FACILITY NAME (1)						1	DOCKET NUMBER	(2)	PAT	GE (3)
VOGTLE ELECTRIC	GENERATI	NG PLANT	- UNIT 2	?			0 6 0 0	1014121	5 1 07	0 4
PERSONNEL ERROR	LEADS TO	CONTAIN	MENT VENT	ILATIC	N ISO	LATION				
EVENT DATE (5)	LER NUMBER	(6)	REPORT DA	TE (7)		OTHER	FACILITIES INVOI	VED (8)		
MONTH DAY YEAR YEAR	BEQUENTIAL UMBER	REVIBION NUMBER	MONTH DAY	YEAR		FACILITY NAS	DOCKET NUMBERIS			
								0 15 10 1	0101	11
11268989	- 0310	d o - o	12 19	8 9				0 15101	0 1 0 1	1.1
OPERATING THIS REP	PORT IS BURMITTI	ED PURSUANT 1	TO THE REQUIREN	NENTS OF 10	CFR \$ 10	theck one or more i	of the following) (11			4
MODE (0) 1 20	6D2(b)		20.405(6)		X	\$0.73(e)(2)(iv)		73.75(b)		
LEVEL 1,0,0 - 20	405(6)(1)(i)		50.36(c)(1)			50.73(s)(2)(v)		73.71(e)		
20	406 (#1(*) (mi)		60.73(e)(2)(i)			60.73(a)(2)(viii)(A)	below et 366A)	d in Text NA	C Form
20	406 (e)(1) (iv)		50.73(e)(2)(ii)		50.73(6)(2)(em)(B)		8)			
20.	406 (#)15 (v)		50,73(s1(2)(iii)			50.73(e)(2)(x)				
NAME	interfete and interfete distance of	L	ICENSEE CONTAC	T FOR THIS	LER (12)			TELEPHONE N	UMBER	
5 H 050H 100		TV AND					AREA CODE			
R. M. ODOM, NUC	LEAK SAFE	ITY AND O	LUMPLIANCE				404	8 2 6	- 3 12	1011
	COMPLETE	ONE LINE FOR	EACH COMPONE	TFAILURE	DESCRIBE	D IN THIS REPOR	1 (13)		1	
CAUSE SYSTEM COMPONENT	MANUFAC TURER	TO NPRDS		CAUSE	SVSTEM	COMPONENT	MANUFAC TURER	TO NPRDS	E	
	111					111	111			
			1		1					
	SUPPLEM	ENTAL REPORT	EXPECTED .				EXPECT	D MON	TH DAY	VEAR
YES III ves complete EXPECTED	SUBMISSION DAT	Ð	X NO				DATE (15)		1.	
ABSTRACT (Limit to 1400 used) (* * On 11-26-89, 18-month Ana radiation mo "Bypass" pos radiation re minutes to p delay and pr correct. At position whi Isolation (C The root cau technician. address moved moved it to the importan test results	, an Instr alog Cham bnitor 2R sition as eading. broceeded t 1510 CS ich allow CVI). use of the The proc ement of t the Remon ce of con s are not	rument & nel Oper E-0003. the tec The mon he signa to check T, he mo ed the t is event cedure w the Remo te posit mpliance achieve	Controls ational T The moni hnician i itor's pr 1. Howev the gain ved the R est signa was cogn hich was te/Bypass ion. The with pro d.	(I&C) est (A tor's ntrodu ocessi er, th and b emote/ 1 to i itive being switc techn cedure	techn COT) (Remote ced a ng un e tech ackgro Bypas: nitiat persor employ h at t ician s and	nician wa on Contai e/Bypass test sig it took a hnician d bund sign s switch te a Cont nnel erro yed to co the time has been seeking	s perform nment low switch wa nal to si pproximat id not un al to ens to the "R ainment V r on the nduct the when the counsele guidance	ing the range s in the mulate ely fou derstand ure the emote" entilat part of test d technic d regard when ex	area a high d the y were ion the id not ian ding bected	

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION							
FACILITY NAME (1)		DOCKET NUMBER (2)	1	LER NUMBER (6)	PAGE (3)		
			YEAR	SEQUENT AL REVISION NUMBER NUMBER			
VEGP	- UNIT 2	0 15 10 10 10 14 1 215	819	- 0131 0 - 010	01200014		

A. REQUIREMENT FOR REPORT

.

This report is required per 10 CFR 50.73 (a)(2)(iv) because an unplanned Engineered Safety Feature (ESF) actuation occurred.

B. UNIT STATUS AT TIME OF EVENT

At the time of the event on 11-26-89, Unit 2 was operating in Mode 1 (Power Operation) at 100% rated thermal power (RTP). Other than that described herein, there was no inoperable equipment which contributed to the occurrence of this event.

C. DESCRIPTION OF EVENT

On 11-26-89, an Instrument & Controls (I&C) technician was performing the 18-month Analog Channel Operational Test (ACOT) on Containment low range area radiation monitor 2RE-0003. The monitor's Remote/Bypass switch was in the "Bypass" position as the technician introduced a test signal to simulate a high radiation reading. The monitor's processing unit took approximately 4 minutes to process the signal. However, the technician did not understand the delay and proceeded to check the gain and background signal to ensure they were correct. At 1510 CST, he moved the Remote/Bypass switch to the "Remote" position which allowed the test signal to initiate a Containment Ventilation Isolation (CVI). The appropriate valves and dampers actuated and control room operators verified that no abnormal radiation condition existed. The CVI signal was reset at 1547 CST.

D. CAUSE OF EVENT

The root cause of this event was personnel error on the part of the Georgia Power Company technician. Procedure 24623-2, "Containment Low Range Area Radiation Monitor Analog Channel Operational Test", which was being employed to conduct the test, did not address movement of the Remote/Bypass switch at the time when the technician moved it out of bypass.

The following are contributing causes of this event:

 The test procedure indicates that testing should cease if expected results are not being obtained. When the technician did not understand the lengthy processing time, he failed to stop and notify his foreman as indicated by the procedure.

LICENSEE EVENT REP	U.S. NUCLEAR RE JATION APPROVED I EXPIR 16: 8/3	U.S. NUCLEAR REGULATORY COMMISSION APPROVED ONE NO. 3150-0104 EXPIF 26: 8/31/88				
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)			
		YEAR SEQUENTIAL REVISION				
VEGP - UNIT 2	0 15 10 10 10 1 41 2 15	819 - 01 30 - 010	013 01 014			

- The test procedure did not indicate that a lengthy processing time may be required (depending on the test signal frequency used). This lack of information misled the technician into believing that the signal was not being processed.
- Although the technician performing the ACOT testing was trained and qualified to do surveillance testing, this was only the second time he had performed testing on 2RE-0003. This lack of specific experience contributed to his personnel error.
- Operational needs for blocking the ESF actuation signal during maintenance and testing were not addressed in the original design.

The above cognitive personnel errors were not the result of any unusual characteristics of the work location.

E. ANALYSIS OF EVENTS

During this event, the CVI signal actuated the proper valves and dampers and control room operators responded correctly in verifying that no abnormal radiation condition existed. Therefore, plant safety would have been maintained if an abnormal radiation condition had, in fact, existed. Based on these considerations, there was no adverse effect on plant safety or public health and safety as a result of this event.

- F. CORRECTIVE ACTIONS
 - The technician involved has been counseled regarding the importance of compliance with procedure and seeking guidance when expected test results are not achieved. Personnel responsible for performing maintenance or surveillance activities on Process Effluent Radiation Monitoring System (PERMS) monitors have been reminded of the necessity to stop testing and seek guidance whenever expected test results are not being achieved.
 - Procedures 24623-1 and 2 have been changed to advise personnel of the potential for a lengthy test signal processing time.
 - An additional instructional unit will be developed for this specific ACOT testing by 2-1-90. Additional PERMS hands-on training will be instituted upon receipt and installation of the PERMS training simulator.

.

Beal . LICENSEE EVE	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88					
FACILITY NAME (1)	DOCKET NUMBER (2)	LE S NUMBER (6)			PAGE (3)			5)		
		YEAR		SEQUENTIAL NUMBER	REVISION NUMBER		TT			
VEGP - UNIT 2	0 15 10 10 10 14 12 15	8 19	-	0 1310	- 010	01	4 OF	014		
YEAT III man share is required use additional MDC form Strate 115	and a second and the second second by the second	Accession and and	-	above description of	Annaharah	A				

- A blocking capability is being designed with installation currently planned for 1990.
- G. ADDITIONAL INFORMATION
 - 1. Failed Components

None

. .

2. Previous Similar Events

LER 50-424/1989-001, dated 02-01-89. Corrective action addressed means to prevent inadvertent actuation of IRE-0003's reset button. However, it did not address movement of the Remote/Bypass switch.

LER 50-424/1988-027, dated 10-26-88. Corrective action addressed lack of a switch to block the CVI actuation signal. Installation of these switches is scheduled to occur during 1990.

3. Energy Industry Identification System Code

Containment Isolation Control System - JM

Radiation Monitoring System - IL