

The Light company

Houston Lighting & Power

P.O. Box 1700 Houston, Texas 77001 (713) 228-9211


March 1, 1990
ST-HL-AE-3389
File No.: G26
10CFR50.73

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 2
Docket No. STN 50-499
Licensee Event Report 90-002 Regarding
A Reactor Trip Due to Spurious
Actuation of a Reactor Trip Breaker

Pursuant to 10CFR50.73, Houston Lighting & Power Company (HL&P) submits the attached Licensee Event Report (LER 90-002) regarding a reactor trip due to spurious actuation of a reactor trip breaker. This event did not have any adverse impact on the health and safety of the public.

If you should have any questions on this matter, please contact Mr. C. A. Ayala at (512) 972-8628 or myself at (512) 972-7921.


G. E. Vaughn
Vice President
Nuclear Operations

GEV/BEM/n1

Attachment: LER 90-002 (South Texas, Unit 2)

9003140403 900301
PDR ADDCK 05000499
S PNU

NL.LER90002.U2

A Subsidiary of Houston Industries Incorporated

IF22
||

Houston Lighting & Power Company
South Texas Project Electric Generating Station

ST-HL-AE-3389
File No.: G26
Page 2

cc:

Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

George Dick, Project Manager
U.S. Nuclear Regulatory Commission
Washington, DC 20555

J. I. Tapia
Senior Resident Inspector
c/o U. S. Nuclear Regulatory
Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire
Newman & Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

D. E. Ward/R. P. Verret
Central Power & Light Company
P. O. Box 2121
Corpus Christi, TX 78403

J. C. Lanier
Director of Generation
City of Austin Electric Utility
721 Barton Springs Road
Austin, TX 78704

R. J. Costello/M. T. Hardt
City Public Service Board
P. O. Box 1771
San Antonio, TX 78296

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 61867
Houston, TX 77208

INPO
Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

Dr. Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

D. K. Lacker
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78704

Revised 12/15/89

L4/NRC/

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) South Texas, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 4 9 9	PAGE (3) 1 OF 0 3
--	--------------------------------------	----------------------

TITLE (4) A Reactor Trip Due to Spurious Actuation of Reactor Trip Breaker

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)
0	2	0	2	9	0	9	0	0				0 5 0 0 0
												0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)

OPERATING MODE (9) 1	20.402(b)	20.406(c)	<input checked="" type="checkbox"/>	60.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 11010	20.406(a)(1)(i)	60.36(c)(1)		60.73(a)(2)(v)	73.71(c)
	20.406(a)(1)(ii)	60.36(c)(2)		60.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 556A)
	20.406(a)(1)(iii)	60.73(a)(2)(i)		60.73(a)(2)(viii)(A)	
	20.406(a)(1)(iv)	60.73(a)(2)(ii)		60.73(a)(2)(viii)(B)	
	20.406(a)(1)(v)	60.73(a)(2)(iii)		60.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME Charles Ayala - Supervising Licensing Engineer	TELEPHONE NUMBER
	AREA CODE: 5 1 2 9 7 2 - 8 6 2 8

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)
		MONTH: DAY: YEAR:

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

ABSTRACT

On February 2, 1990, Unit 2 was in Mode 1 at 100 percent power. At 0259 hours the Train S Reactor Trip Breaker spuriously opened. This initiated a turbine trip and subsequent reactor trip. Feedwater isolation occurred on low average Reactor Coolant System Temperature and an Auxiliary Feedwater System actuation occurred on low steam generator level as expected. The plant was stabilized in Mode 3. No unexpected post trip transients occurred. Extensive troubleshooting of the Solid State Protection System and the Reactor Trip Breaker was performed; however, the cause of the spurious breaker opening is unknown. As a conservative measure, the fifteen Universal Logic Cards associated with the reactor trip function in Train S of the Solid State Protection System have been replaced. Instrumentation has been installed on the reactor trip breaker in an attempt to isolate the source of the spurious trip signal should it recur.

NL.LER90002.U2

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) South Texas, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 4 9 9 9 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 0	— 0 0 2	— 0 0	0 2	OF	0 3

TEXT (if more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT:

On February 2, 1990, Unit 2 was in Mode 1 at 100 percent power. At 0259 hours, the Train S Reactor Trip Breaker opened. Opening of the breaker initiated a turbine trip and subsequent reactor trip. A feedwater isolation occurred on low average Reactor Coolant System temperature and an Auxiliary Feedwater System actuation occurred on low steam generator level as expected. The Main Steam Isolation Valves were closed to limit the cooldown and the plant was stabilized in Mode 3. No unexpected post trip transients were observed. The NRC was notified of this event at 0352 hours.

Troubleshooting was performed to determine the cause of the event. Plant computer logs were reviewed for the source of the trip. No actuation of the Solid State Protection System was identified which would account for the opening of the Train S breaker. The Train S Reactor Trip Breaker was subjected to thermographic examination and inspection. Westinghouse Universal Logic Cards and their power supplies in the Solid State Protection System were inspected and tested. The SSPS circuits and Train S Reactor Trip Breaker were inspected for loose connections and for conformance with schematic diagrams. No conditions were found which would result in a spurious trip.

In an attempt to identify external conditions which could initiate spurious operation of the trip circuits, additional troubleshooting was performed. SSPS Universal Logic Cards were subjected to heat and vibration. A radio frequency test was performed in the area of the SSPS equipment. No problems were noted with the equipment during these tests.

As a conservative measure, the fifteen Train S Universal Logic Cards associated with the reactor trip function were replaced prior to restart of the unit.

CAUSE OF EVENT:

The cause of the Train S Reactor Trip Breaker to open spuriously is unknown at this time. Instrumentation has been installed to monitor the breaker undervoltage trip device and shunt trip coils in an attempt to identify the source of the spurious signal should another trip occur.

ANALYSIS OF EVENT:

Unplanned reactor trips are reportable pursuant to 10CFR50.73(a)(2)(iv). the plant tripped from 100 percent power and was brought to a stable condition in Mode 3 with no unexpected post trip transients.

NL.LER90002.U2

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) South Texas, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 4 9 9 9 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0 0 2	0 0 0	0 0 0	3	OF	0 3

TEXT (if more space is required, use additional NRC Form 305A's) (17)

CORRECTIVE ACTION:

The following corrective actions are being taken as a result of this event:

1. As a conservative measure, the fifteen Universal Logic Cards associated with the reactor trip function in SSPS Train S have been replaced.
2. Instrumentation has been installed to monitor the Reactor Trip Breaker undervoltage trip device and shunt trip coil in an attempt to identify the source of the spurious signal should another trip occur.

ADDITIONAL INFORMATION:

A previous similar spurious actuation of the Train S Reactor Trip Breaker was reported under LER 89-013.

NL.LER90002.U2