Attachment to AECM-83/0275

	Page 1 of 1
	CONTROL BLOCK:
0 1 7 8	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 0 5 57 CAT 58
0 1 0 2	SOURCE LIG O SO O O 4 1 60 0 4 1 1 8 3 8 0 5 1 1 8 3 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  On April 11, 1983, while reviewing the vessel head installation work
0 3	package the I&C Superintendent discovered that the head flange/vessel
0 4	[flange thermocouples had not been physically reinstalled during the
0 5	[insulation installation. Consequently, for approximately a 30 day
0 6	period the operators were monitoring ambient air temperatures. The
0 7	surveillance requires verification that these temperatures are greater
0 8	than or equal to 70 degrees F in mode 4.
7 8	SYSTEM CAUSE SUBCODE COMPONENT CODE SUBCODE SU
10	The cause is still under evaluation. The flange thermocouples have been
111	reinstalled. A follow-up report is expected to be submitted by May 30.
1 2	[1983. This is considered an interim report submitted pursuant to T.S.
1 3	6.9.1.13.b as the surveillance requirements of Technical Specification
14	[4.4.6.1.4 were not actually met.
1 5	9 FACILITY STATUS  B POWER  OTHER STATUS  OT
	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  10 11 11 44 45 LOCATION OF RELEASE (36)  PERSONNEL EXPOSURES 80
7 8	NUMBER TYPE DESCRIPTION (39)  9 11 12 13 80  PERSONNEL INJURIES 13 80  NUMBER DESCRIPTION (41)
1 8	9 11 12 8305200532 830511 80 Coss of OR DAMAGE TO FACILITY 43 PDR ADDCK 05000416 PDR ADDCK 05000416 S PDR
2 0	9 10 PUBLICITY SSUED DESCRIPTION 45 NRC USE ONLY
	NAME OF PREPARER M. V. Robrer