

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T

0	1	L	6	0	5	0	0	0	3	1	7	7	0	5	1	9	8	3	8	0	6	1	6	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1220 during normal operations the Plant Computer was taken out of  
0 3 | service to replace a fan that was found during a routine inspection to  
0 4 | be defective. Securing the computer rendered Incore Monitoring inoper-  
0 5 | able (T.S. 3.3.3.2). The fan was replaced and the computer returned to  
0 6 | service at 1310. Excore Monitoring remained operable during this event.  
0 7 | Similar events: none.

0 8 | \_\_\_\_\_

0	9	I	E	11	E	12	B	13	X	X	X	X	X	X	14	Z	15	Z	16	17	8	3	—	0	3	0	—	0	3	L	—	0	18	Z	19	Z	20	Z	21	0	0	0	0	—	N	23	N	24	A	25	X	9	9	9	9	26
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	----	---	---	---	---	---	---	---	---	---	---	---	---	----	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	---	---	---	---	---	----

  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause for this event was a bearing failure of the fan (IMC Magnetic  
1 1 | Corp., Model#WS2107FL). This fan provides cooling to the logic power sup-  
1 2 | ply. The fan was replaced with a spare. Since the fan is checked monthly  
1 3 | under the preventive maintenance program, no further corrective or  
1 4 | preventive actions are deemed necessary.

1	5	E	28	1	0	0	29	N/A	30	B	31	Preventive Maintenance Inspection	32
---	---	---	----	---	---	---	----	-----	----	---	----	-----------------------------------	----

  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1	6	Z	33	Z	34	N/A	35	N/A	36
---	---	---	----	---	----	-----	----	-----	----

  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1	7	0	0	0	37	Z	38	N/A	39
---	---	---	---	---	----	---	----	-----	----

  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1	8	0	0	0	40	N/A	41
---	---	---	---	---	----	-----	----

  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1	9	Z	42	N/A	43
---	---	---	----	-----	----

  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

2	0	N	44	N/A	45
---	---	---	----	-----	----

  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER R. J. Porter/J. W. Raynor

PHONE 301-269-4747/4713

# BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT  
CALVERT CLIFFS NUCLEAR POWER PLANT  
LUSBY, MARYLAND 20657

June 16, 1983

Mr. James M. Allan  
Acting Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region 1  
631 Park Avenue  
King of Prussia, PA 19406


Docket No. 50-317  
License No. DPR 53

Dear Mr. Allan:

In accordance with Technical Specification 6.9 please find the attached thirty day report for LER 83-30/3L.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,

  
L. B. Russell  
Plant Superintendent

LBR:JWR:bsb

cc: Director, Office of Management Information  
and Program Control  
Messrs: A. E. Lundvall, Jr.  
J. A. Tiernan

IE22  
11