

CONTROL BLOCK: [] [] [] [] [] [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[01] [A][L][J][M][F][1] [2] [0][0] - [0][0] [0][0][0] - [0][0] [3] [4][1][1][1][1] [4] [] [5]
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 50

CON'T
[01] REPORT SOURCE [L] [6] [0][5] [0][0][0][3] [4] [8] [7] [0][6][0][7][8][3] [8] [0][6][3][0][8][3] [9]
7 8 40 DOCKET NUMBER 48 49 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[02] At 1320 on 6/7/83 during performance of FNP-1-STP-43.0 (Spent Fuel Pool Ventila-
[03] tion Isolation Test), the "A" train penetration room filtration system was
[04] declared inoperable when exhaust fan damper 3357A would not open. Tech. Spec.
[05] 3.7.8 requires two independent penetration room filtration systems to be oper-
[06] able. Tech. Spec. 3.7.8 action statement requirements were met. Health/Safety
[07] of the public was not affected.

[09] SYSTEM CODE [A][A] [11] CAUSE CODE [E] [12] CAUSE SUBCODE [G] [13] COMPONENT CODE [I][N][S][T][R][U] [14] COMP. SUBCODE [Y] [15] VALVE SUBCODE [Z] [16]
7 8 9 10 11 12 13 18 19 20
[17] LER/RO REPORT NUMBER [8][3] [] [] [0][2][7] [] [] [0][3] [] [] [0]
21 22 23 24 26 27 29 30 31 32
ACTION TAKEN [A] [18] FUTURE ACTION [Z] [19] EFFECT ON PLANT [Z] [20] SHUTDOWN METHOD [Z] [21] HOURS [0][0][0][0] [22] ATTACHMENT SUBMITTED [N] [23] NPRD-4 FORM SUB. [N] [24] PRIME COMP. SUPPLIER [N] [25] COMPONENT MANUFACTURER [W][1][2][0] [26]
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[10] This event was due to the failure of a comparator card. Following replacement of
[11] the card and satisfactory performance of FNP-1-STP-43.0, the "A" train penetra-
[12] tion room filtration system was declared operable at 0530 on 6/8/83.

[15] FACILITY STATUS [E] [28] % POWER [1][0][0] [29] OTHER STATUS [NA] [30] METHOD OF DISCOVERY [B] [31] DISCOVERY DESCRIPTION [Surveillance Test] [32]
7 8 9 10 12 13 44 45 46 80

[16] ACTIVITY CONTENT RELEASED OF RELEASE [Z] [33] AMOUNT OF ACTIVITY [NA] [35] LOCATION OF RELEASE [NA] [36]
7 8 9 10 11 44 45 80

[17] PERSONNEL EXPOSURES NUMBER [0][0][0] [37] TYPE [Z] [38] DESCRIPTION [NA] [39]
7 8 9 11 12 13 80

[18] PERSONNEL INJURIES NUMBER [0][0][0] [40] DESCRIPTION [NA] [41]
7 8 9 11 12 80

[19] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] [42] DESCRIPTION [NA] [43]
7 8 9 10 80

[20] PUBLICITY ISSUED [N] [44] DESCRIPTION [] [45] 8307120286 830630 PDR ADOCK 05000348 S PDR
7 8 9 10 88 89 90 NRC USE ONLY

Mailing Address
Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6081

F. L. Clayton, Jr.
Senior Vice President
Flintridge Building

USNRC REGION II
ATLANTA, GEORGIA

July 5
83 JUN 4 A 9:47



Alabama Power

the southern electric system

June 30, 1983

Docket No. 348
Docket No. 364

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, N.W.
Suite 3100
Atlanta, Georgia 30303

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Reports Nos. LER 83-027/03L-0, LER 83-028/03L-0 and LER 83-029/03L-0 and Unit 2, Licensee Event Report No. LER 83-026/03L-0 are forwarded with three (3) copies of each in accordance with FNP Technical Specification 6.9.1.13 to provide thirty (30) days written notification of the occurrences.

If you have any questions, please advise.

Yours very truly,

F. L. Clayton, Jr.
F. L. Clayton, Jr.

FLCJr/KWM:nac/F-6

Enclosures

xc: Director, IE (30 copies)
Director, MIPC (3 copies)

IE22
11