

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(0) (1) P A S E S I (2) 0 0 - 0 0 0 0 0 - 0 0 (3) 4 1 1 F 1 (4) (5)
7 8 9 14 15 25 26 30 37 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CONT
(0) (1) REPORT SOURCE L (6) 0 5 0 0 0 3 8 7 (7) 0 5 2 4 8 3 (8) 0 6 2 3 8 3 (9)
7 8 80 81 88 89 74 75 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

(0) (2) The Control Room Emergency Outside Air Supply System (CREOASS) fan tripped during

(0) (3) surveillance testing. A time delay relay for heater differential temperature

(0) (4) initiated the trip. There were no occurrences requiring CREOASS to function and no

(0) (5) consequential effects to public health and safety.

(0) (6)

(0) (7)

(0) (8)

(0) (9) SYSTEM CODE S G (11) CAUSE CODE E (12) CAUSE SUBCODE E (13) COMPONENT CODE R E L A Y X (14) COMP. SUBCODE H (15) VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 14 15 16 19 20
EVENT YEAR 8 3 (21) SEQUENTIAL REPORT NO. 0 8 4 (24) OCCURRENCE CODE 0 3 (28) REPORT TYPE L (31) REVISION NO. 0 (32)

(17) LER/RO REPORT NUMBER 8 3 (21) (22) SHUTDOWN METHOD Z (21) HOURS 0 0 0 0 (22) ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. N (24) PRIME COMP. SUPPLIER A (25) COMPONENT MANUFACTURER A 1 1 0 9 (26)
ACTION TAKEN E (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0 0 0 0 (22) ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. N (24) PRIME COMP. SUPPLIER A (25) COMPONENT MANUFACTURER A 1 1 0 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

(1) (0) The time delay relay was found out of tolerance, six minutes, ten seconds instead

(1) (1) of seven minutes. The time delay was reset and the relay was subsequently

(1) (2) rechecked (two days later) to verify proper time setting did not drift.

(1) (3)

(1) (4)

(1) (5) FACILITY STATUS C (28) % POWER 0 0 8 (29) OTHER STATUS NA (30) METHOD OF DISCOVERY B (31) DISCOVERY DESCRIPTION Operator Observation (32)
7 8 9 10 11 12 13 44 45 M

(1) (6) ACTIVITY CONTENT RELEASED OF RELEASE Z (33) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)
7 8 9 10 11 44 45

(1) (7) PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION NA (39)
7 8 9 10 11 12 13

(1) (8) PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION NA (41)
7 8 9 10 11 12

(1) (9) LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION NA (43)
7 8 9 10

(2) (0) PUBLICITY ISSUED N (44) DESCRIPTION NA (45) 8307120443 830623 PDR ADOCK 05000387 S PDR
7 8 9 10 66 69 80 NRC USE ONLY



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215/770-5151

June 23, 1983

Mr. J.M. Allan
Acting Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 83-084/03L-0
ER 100450 FILE 841-23
PLA-1727

Docket No. 50-387
License No. NPF-14

Dear Mr. Allan:

Attached please find a copy of Licensee Event Report No. 83-084/03L-0. This event was determined to be reportable per Technical Specification 6.9.1.9.b, in that a Control Room Emergency Outside Air Supply (CREOASS) fan tripped during surveillance testing. A time delay relay was reset and the system is now operational.

H.W. Keiser
Superintendent of Plant-Susquehanna

APP/pjg

cc: G.G. Rhoads
Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

|| I E 22