

RECEIVED
NRC

PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372

JUN 28 AM 11:04
REGION V 182

J. O. SCHUYLER
VICE PRESIDENT
NUCLEAR POWER GENERATION

June 27, 1983

nm

Mr. John B. Martin, Regional Administrator
U.S Nuclear Regulatory Commission, Region V
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368

Re: Docket No. 50-323
Diablo Canyon Unit 2
10 CFR 50.55 (e) Report -
Malfunction of Limitorque Valve Operator

Dear Mr. Martin:

On May 26, 1983, Mr. Morrill of your office was notified by telephone of a problem concerning binding of a torque switch on an operator manufactured by Limitorque against the switch assembly mounting bolts.

When Region V was originally notified of this event, it appeared that the cause was manual overtorquing of the valve operator, resulting in the torque switch arm wedging against the mounting bolt. The proposed corrective action at that time was to replace the existing mounting bolts with round head bolts with a split lock washer. Subsequent investigation in conjunction with Limitorque, however, indicates that there is a need to evaluate the cause of the event in greater detail to prevent exacerbating the situation and to identify the specific valves susceptible to this phenomenon.

Investigations to date indicate that the problem has only occurred on one valve, and preliminary analysis showed that it occurred from overtorquing. However, PGandE has only been able to duplicate the problem on other valves by manually manipulating the torque switch, not by any actual operation. Limitorque does not believe that the torque switch can actually move far enough to bind during actual operation. PGandE is continuing the investigation in conjunction with Limitorque to confirm the extent of the problem and determine an appropriate corrective action.

In view of the above, please regard this as an interim report; a final report will be submitted once the investigation to establish the cause, corrective action, and generic implication is completed.


8307120582 830627
PDR ADOCK 05000323
S PDR

1E27/10

83-144

Corrective actions will be completed and a final 50.55(e) report submitted before Unit 2 fuel load.

Sincerely,

A handwritten signature in cursive script, appearing to read "J. O. Schunzler".

cc: Mr. G. W. Knighton, Chief
Licensing Branch No. 3
Division of Licensing
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Service List