NRC FORM 366 (12-81)\* 10 CFR 50 U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OMB 3150-0011 LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) PASESIO - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 6 57 CAT 0 1 0 CON'T REPORT L 6 0 5 0 0 3 8 7 7 0 6 2 5 8 3 6 0 7 2 5 8 3 9 0 1 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) 0 2 | During the performance of a routinely scheduled 31-day surveillance, a dual status 0 3 indication for one suppression pool-to-drywell vacuum breakers caused the position of the valve to be indeterminate. Since the remaining nine vacuum breakers tested 0 4 0 5 satisfactorily and were available for service, there was minimal impact to the health and safety of the general public. 0 6 0 7 0 8 8 ( CODE CAUSE CAUSE VALVE COMP COMPONENT CODE SUBCODE E 12 B 13 N S T R U 14 S 15 Z 10 0 9 I 18 19 12 SEQUENTIAL REPORT NO. OCCURRENCE REPORT REVISION CODE TYPE NO 17 REPORT 13 0 9 8 10 13 L 24 28 30 31 32 HOURS 22 ATTACHMENT NPR0-4 SUBMITTED FORM SUB. MANUFACTURER 26 ACTION FUTURE TAKEN ACTION EFFECT SHUTDOWN PRIME COMP. ON PLANT METHOD SUPPLIER Z 21 N 24 E 18 Z 19 Z 20 | N | 25 0 0 0 0 |A |4 |1 |5 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) 1 0 The causes of the dual indication were an insufficient limit switch plunger posit-1 1 ion and an out-of-adjustment rotary switch contact cam. Both it. switches were 2 adjusted to provide proper control room indication. The surveillance test was re-1 3 peated, and all valves tested satisfactorily. No further actions are planned. 1 4 80 FACILIT METHOD OF OTHER STATUS (30) S POWER (32) DISCOVERY DISCOVERY DESCRIPTION STATUS 5 G 28 0 0 0 29 NA B 3 Operator observation 8 9 10 ACTIVITY CONTENT RELEASED OF NELEASE 12 13 45 80 AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) Z 3 Z 3 NA 1 6 NA 10 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39 0 0 0 0 3 2 38 80 NA 80 PERSONNEL INJURIES NUMBER TEZZ 0 0 0 0 1 8 NA 8308070324 830725 PDR ADOCK 05000387 11 80 LOSS OF OR DAMAGE TO FACILITY Z (42) 1 9 NA PDR PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY 20 N 44 NA 11111 PHONE (717) 542-2181 Ex. 3759 NAME OF PREPARER L.A. Kuczynski



## Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

July 25, 1983

Dr. Thomas E. Murley Regional Administrator, Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 83-098/03L-0 ER 100450 FILE 841-23 PLA-1761

Dear Dr. Murley:

Attached is Licensee Event Report No. 83-098/03L-0. This event was determined to be reportable per Technical Specification 6.9.1.9.b, in that, with the unit in Operational Condition 3, one of the suppression pool-to-drywell vacuum breakers was considered inoperable based on dual status indication (simultaneous open and closed position indication) in the main control room.

eleci

H.W. Keiser Superintendent of Plant-Susquehanna

LAK/pjg

cc: G.G. Rhoads Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 52 Shickshinny, PA 18655

> Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

F622