NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 2900 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - RWCU Auto
Isolation Occurs
LER 83-097/03 X-1
AECM-83/0499

This letter submits an update to a previous report submitted on August 19, 1983. The event for which the report was submitted occurred on July 20, 1983, when a RWCU auto isolation occurred. At the time, RWCU was being used as an alternate method for reactor coolant circulation pursuant to Action (2) of Technical Specification 3.4.9.2 due to equipment failures in the RHR System. The RWCU system was returned to operation within thirty (30) minutes by placing the RWCU Isolation Logic "B" Bypass Switch in bypass. This was reported pursuant to Technical Specification 6.9.1.13.b.

In our original letter submitted August 19, 1983, we incorrectly stated on the LER form that Action (2) of Technical Specification 3.4.9.2 was entered due to equipment failures in the RWCU System. It should have said due to equipment failures in the RHR System. Attached is revised LER 83-097/03 X-1.

Yours truly,

8 H Hobbs

for L. F. Dale

Manager of Nuclear Services

EBS/SHH:sap Attachment

cc: (See Next Page)

TE 22

MISSISSIPPI POWER & LIGHT COMPANY

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555