

Attachment to AECM-83/0500

CONTROL BLOCK:

						(1)
--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58

LICENSER CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

REPORT SOURCE: 01 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
DOCKET NUMBER: 01 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
EVENT DATE: 01 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
REPORT DATE: 01 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During an inspection of completed work which corrected fire protection
0 3 | deficiencies on redundant raceways/cables, Maintenance Field Engineering
0 4 | noted similar deficiencies in the Auxiliary Building, Turbine Building,
0 5 | and Control Building. Fire watches were established in accordance with
0 6 | T.S.3.7.7.a. The condition had no affect on the health and safety of
0 7 | the public and did not constitute a threat to plant safety. This is
0 8 | submitted as a Special Report pursuant to T.S.6.9.2.

SYSTEM CODE A B (11)		CAUSE CODE B (12)		CAUSE SUBCODE C (13)		COMPONENT CODE Z Z Z Z Z Z (14)				COMP. SUBCODE Z (15)		VALVE SUBCODE Z (16)					
EVENT YEAR 8 3 (21) (22)		SEQUENTIAL REPORT NO. 0 1 0 (24) (25) (26)		OCCURRENCE CODE 9 9 (28) (29)		REPORT TYPE X (30)		REVISION NO. 2 (32)									
ACTION TAKEN X (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22) (23) (24) (25)		ATTACHMENT SUBMITTED Y (23)		NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER Z (25)		COMPONENT MANUFACTURER Z 9 9 9 (26) (27) (28) (29)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of the deficiencies was incomplete construction. Maintenance

1 1 work authorizations were initiated for correction. All work is complete

1 2 and all LCO's have been lifted. This is a final report.

1 3

1 4 1
7 8 9
FACILITY STATUS 8 (28) % POWER 0 0 0 (29) OTHER STATUS NA (30) METHOD OF DISCOVERY C (31) DISCOVERY DESCRIPTION Special Inspection (32)
7 8 9 10 11 12 13 14 15 16
ACTIVITY CONTENT RELEASED OF RELEASE 2 (33) Z (34) NA AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
7 8 9 10 11 12 13 14 15 16
PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION NA (39)
7 8 9 10 11 12 13 14 15 16
PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION NA (41)
7 8 9 10 11 12 13 14 15 16
LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION NA (43)
7 8 9 10 11 12 13 14 15 16
PUBLICITY ISSUED N (44) DESCRIPTION NA (45)
7 8 9 10 11 12 13 14 15 16
8309090521 830829
PDR ADOCK 05000416
S PDR
NRC USE ONLY
78 79 80

NAME OF PREPARER

M. V. Rohrer

PHONE

SUPPLEMENTARY INFORMATION TO
LER 83-010/99 X-2

Mississippi Power & Light Company
Grand Gulf Nuclear Station - Unit 1
Docket No. 50-416

Technical Specification Involved: 3.7.7
Reported Under Technical Specification: 6.9.2

Event Narrative:

This is an update to previous reports submitted on February 7, 1983, and June 2, 1983. The event for which the report was submitted is described in the following paragraphs.

During an inspection of completed work which corrected fire protection deficiencies on redundant raceways/cables (Reference LER 82-106/01 T-0), Field Engineering identified similar deficiencies which were not previously identified by the Architect Engineer but which were a result of incomplete construction. LCO's 83-0018, 83-0019, and 83-0020 were entered on January 5, 1983, to establish fire watches in the Auxiliary Building, Turbine Building, and Control Building areas which were not previously covered under LCO 83-0036 (Reference LER 82-106/01 T-0).

Maintenance work authorizations were issued to correct the deficiencies, and all work is complete. All LCO's were lifted by August 23, 1983. This is a final report.



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

August 29, 1983

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - Redundant
Division Raceway Fire
Protection Deficiencies
Discovered
LER 83-010/99 X-2
AECM-83/0500

This letter submits an update to previous reports submitted on February 7, 1983, and June 2, 1983. The event for which the reports were submitted occurred on January 5, 1983, when during an inspection of completed work which corrected fire protection deficiencies on redundant raceways/cables, it was noted that there were similar deficiencies in the Auxiliary Building, Turbine Building, and Control Building. Fire watches were established in accordance with Technical Specification 3.7.7.a. The event was reported pursuant to Technical Specification 6.9.2.

All work is complete and all LCO's associated with the task have been lifted. Attached is LER 83-010/99 X-2, which is a final report.

Yours truly,

L. F. Dale

for L. F. Dale
Manager of Nuclear Services

EBS/SHH:sap
Attachment

cc: (See Next Page)

OFFICIAL COPY
TE 22

USNRC REGION II
ATLANTA, GEORGIA
SEP 6 48:55

MISSISSIPPI POWER & LIGHT COMPANY

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555