

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I	L	D	R	S	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5		
8	9	LICENSEE CODE						14	15	LICENSE NUMBER								25	26	LICENSE TYPE					30	57	58	59

0	1	L	0	5	0	0	0	2	3	7	7	0	9	3	0	7	8	8	1	0	1	3	7	8	9
8	9	REPORT SOURCE		60	61	DOCKET NUMBER						68	69	EVENT DATE				74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing DOS 2300-3 (HPCI Turbine Quarterly Surv.) the HPCI turbine tripped

0 3 | on low pump suction pressure of 11.5 psig which exceeds the Dresden setpoint of 9.4

0 4 | in. Hg vacuum increasing. Safety significance was reduced since redundant Isolation

0 5 | Condenser and Auto Depressurization Systems were operable. No previous similar

0 6 | events at Dresden.

0 7 |

0 8 |

0 9 |

0	1	S	F	E	E	I	N	S	T	R	U	E	Z	7	8	0	5	5	0	1	T	0	M	2	3	5															
8	9	SYSTEM CODE		9	10	CAUSE CODE		11	12	CAUSE SUBCODE		13	COMPONENT CODE				15	VALVE SUBCODE		19	20	EVENT YEAR		21	22	SEQUENTIAL REPORT NO.		24	26	OCCURRENCE CODE		27	28	29	REPORT TYPE		30	31	REVISION NO.		32
33	34	ACTION TAKEN		33	34	EFFECT ON PLANT		35	36	SHUTDOWN METHOD		37	HOURS		37	40	ATTACHMENT SUBMITTED		41	42	NPRD-4 FORM SUB.		43	PRIME COMP. SUPPLIER		43	COMPONENT MANUFACTURER		44	47											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause was attributable to instrument drift of pressure switch PS 2-2360. The

1 1 | switch was recalibrated to trip at -9.4" Hg increasing. The switch will be checked

1 2 | in two months to ensure its continued acceptability.

1 3 |

1 4 |

1	5	E	0	9	2	NA	B	Surveillance Testing														
8	9	FACILITY STATUS		9	10	% POWER		10	11	OTHER STATUS		30	METHOD OF DISCOVERY		45	46	DISCOVERY DESCRIPTION					80

1	6	Z	Z	NA	NA	NA												
8	9	ACTIVITY CONTENT		9	10	RELEASED OF RELEASE		10	11	AMOUNT OF ACTIVITY		35	LOCATION OF RELEASE					80

1	7	0	0	0	NA													
8	9	PERSONNEL EXPOSURES		9	10	NUMBER		11	12	TYPE		13	DESCRIPTION					80

1	8	0	0	0	NA										
8	9	PERSONNEL INJURIES		9	10	NUMBER		11	12	DESCRIPTION					80

1	9	Z	NA												
8	9	LOSS OF OR DAMAGE TO FACILITY		9	10	TYPE		11	12	DESCRIPTION					80

2	0	N	NA											
8	9	PUBLICITY ISSUED		9	10	DESCRIPTION		45	NRC USE ONLY					80

78/0200097 S
NAME OF PREPARER Carl Lindberg

PHONE: X-289

ATTACHMENT TO LICENSEE EVENT REPORT 78-055/01T-0
COMMONWEALTH EDISON COMPANY (CWE)
DRESDEN UNIT-2 (ILDRS-2)
DOCKET #050-237

While conducting the HPCI Turbine Quarterly Surveillance DOS 2300-3, the HPCI Turbine tripped on low pump suction pressure sensed by pressure switch PS-2-2360. The switch tripped at 11.5 psig which is considerably above the Dresden setpoint of 9.4" Hg vacuum increasing. The safety significance of the event was reduced since the redundant Isolation Condenser and Automatic Depressurization Systems were operable.

In the surveillance procedure, normally closed MO valves 2-2301-14 (Flow to Torus), 2-2301-10 (Flow to 2/3B Contaminated Condensate Storage Tank), and 2-2301-49 (HPCI bypass line) are all opened and the HPCI turbine is started against little backpressure. Using a temporary procedure change, valve 2301-10 was closed to restrict the pumps discharge and HPCI started normally. Valve 2301-10 was subsequently throttled and proper flows and pressures were obtained to satisfactorily demonstrate operability in accordance with the surveillance requirements.

However, after subsequent management review on the next normal working day, it was concluded that HPCI might not have been operational under all accident conditions and should have been reported inoperable in accordance with Technical Specifications 6.6.B.1.e.

The cause of the trip was instrument drift of PS2-2360. The switch was recalibrated to trip at 9.4 inches Hg vacuum increasing. These switches have been calibrated each refueling outage in the past, and a review of records indicates no unusual tendency for excessive drifting of the switch setpoints. The switch will be checked in two months to ensure its continued acceptability.