

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [S] [C] [V] [C] [S] [1] [2] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [3] [4] [1] [0] [0] [0] [4] [ ] [ ] [5]

CONT

[0] [1] [L] [6] [0] [5] [0] [0] [0] [3] [9] [5] [7] [1] [0] [0] [3] [8] [2] [8] [1] [1] [0] [2] [8] [2] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0] [2] On October 3, 1982, with the Plant in Mode 3, one of four Main Control Board [0] [3] indicators of Reactor Building pressure was reading low. This pressure indicator [0] [4] (PI-0950) was declared inoperable. The PI subsequently tested satisfactory and [0] [5] was returned to service. On October 19, 1982, the PI again was reading low. The [0] [6] PI was declared inoperable and further investigation was initiated. In both cases [0] [7] three channels of pressure indication remained OPERABLE per the applicable [0] [8] Technical Specification Action Statement; therefore, no adverse consequences.

[0] [9] [I] [B] [11] [X] [12] [Z] [13] [I] [N] [S] [T] [R] [U] [14] [I] [15] [Z] [16] [17] [8] [2] [0] [1] [6] [0] [3] [L] [ ] [0] [18] [X] [19] [Z] [20] [Z] [21] [0] [0] [0] [0] [Y] [23] [N] [24] [N] [25] [I] [1] [3] [0]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1] [0] A Maintenance Work Request (MWR) has been initiated to determine the cause of [1] [1] this occurrence. The corrective actions will be dependent on the cause [1] [2] determination. [1] [3] [1] [4]

[1] [5] [B] [28] [0] [0] [0] [29] [N/A] [30] [A] [31] Operator Observation [32]

[1] [6] [Z] [33] [Z] [34] [N/A] [35] [N/A] [36]

[1] [7] [0] [0] [0] [37] [Z] [38] [N/A] [39]

[1] [8] [0] [0] [0] [40] [N/A] [41]

[1] [9] [Z] [42] [N/A] [43]

[2] [0] [N] [44] [N/A] [45]

NAME OF PREPARER: Curtis Fields PHONE: (803) 345-5209