(12-81)	CENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-82
CONTROL BLOCK: [] [1) (PLEASE PRINT OR TYPE ALL REQU	IRED INFORMATION)
0 1 p A S E S 1 2 0 0 - 0 7 6 9 LICENSEE CODE 14	0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 4 57 CAT 58 5
CON'T O 1 SOURCE L 6 0 5 0 0 0 3 TO SOURCE SO	8 7 0 1 0 1 1 8 2 8 1 1 8 2 8 1 1 1 8 1 2 8 1 1 1 1	1 0 3 8 2 9
EVENT DESCRIPTION AND PROBABLE CONSEQUE O 2 During startup testing the Cl	ences 🛈 REOASS "A" train outside air dam	per failed to
0 3 close, preventing proper oper	ration. The "A" train was decla	red inoperable
0 4 and the action statement was	entered. This is reportable pe	r 6.9.1.9.b.
0 5 No adverse consequences exist	ted in that the action statement	was met.
0 6		
0 7		
08		
SYSTEM CAUSE CAUSE CODE SUBCOD	E COMPONENT CODE SUBCODE	VALVE SUBCODE
S G (11) X (12) Z	(3) V A L V E X (4) X (15)	X (16)
17 REPORT 8 2 0 24	T NO. 3 4 27 20 3 L	REVISION NO.
ACTION FUTURE EFFECT SHUTDOWN METHOD X 18 G 19 Z 20 Z 21 33 34 35 36	HOURS (22) SUBMITTED FORM SUB. SUI	COMPONENT (26) A (25) I 2 0 7
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS The damper failed to function	s ② n due to inadequate lubrication	of the actuator
[1] stem. The stem was removed,	lubricated, and returned. The	damper then
1 2 functioned properly during to	esting. A maintenance procedure	was revised
1 3 to lubricate the stem on a re	egular basis.	
1 4		80
FACILITY STATUS OTHER STATUS	30 METHOD OF DISCOVERY DES	CRIPTION (32)
7 8 9 10 12 13 ACTIVITY CONTENT RELEASED OF TELEASE AMOUNT OF ACTIVITY	44 45 46 LOCATION OF RE	ELEASE 36
1 6 Z 33 Z 34 n/a	n/s	80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 0 0 0 37 Z 38 n,	/a	
7 8 9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION (41)		80
7 8 9 11 12	/a 8211180354 821103	80
1 9 Z 42	PDR ADOCK 05000387	
PUBLICITY ISSUED DESCRIPTION 45	/a	NRC USE ONLY
NAME OF PREPARER D.G. Mitcl	69	7) 542–2181 X524