* EIGENSEE EVENT HEFORT
* . CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M N P I N 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 ENCENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
REPORT L 6 0 5 0 0 0 2 8 2 7 1 0 2 7 8 2 8 1 1 1 7 8 2 9 7 8 OURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0 2 Following use in a routine sampling procedure, SV-33655, Hot Leg Loop B Sample Inside
O[3] Containment Isolation Valve, failed to remain closed. The valve will close on a
0 4 containment isolation signal, but would reopen on reset of containment isolation.
0 5 No effect on public health and safety since redundant valve was operable. Recent
0 6 similar event was RO 82-13.
07
7 8 9
SYSTEM CAUSE CAUSE SUBCODE SUB
LER/RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. O 2 1
ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER WANUFACTURER V 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1 0 Apparent malfunction of an internal limit switch in a Valcor 3/8" solenoid valve
[1] [Model No. V526-5295-5. Manual valve in series has been placed under administrative
[1] control. The faulty valve will be repaired at the refueling outage now in progress.
1 3
7 8 9
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 9 5 29 NA
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA NA NA NA NA NA NA NA N
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 0 0 0 37 Z 38 NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41) 1 0 0 0 (40) NA
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION Z 42 NA
7 8 9 10 10 PUBLICITY 15SUED DESCRIPTION 45 PDR ADDCK 05000282 PDR 10 10 10 10 10 10 10 10 10 10 10 10 10
NAME OF PREPARER A. A. Hunstad PHONE 612-388-1121