

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 30 57 58
[0][1] [N][J][S][G][S][1] [2][0][0]-[0][0][0][0][0]-[0][0] [3][4][1][1][1][1] [4] [5]
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
7 8 60 61 68 69 74 75 80
[0][1] REPORT SOURCE [L][6] [0][5][0][0][0][2][7][2] [7] [1][0][1][7][8][2] [8] [1][1][0][5][8][2] [9]
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[0][2] On October 17, 1982, during a routine containment purge, the Control Room Operator
[0][3] observed an abnormal decrease of radioactivity levels indicated by the Containment-
[0][4] Plant Vent Monitor. Investigation revealed that the Air Particulate Detector (APD)
[0][5] sample line to the plant vent had been erroneously capped during partial completion of
[0][6] Design Change Request (DCR) ED-0014. Subsequent investigation showed the vacuum relief
[0][7] device on the suction of the APD was lifting at normal operating pressure in the
[0][8] suction line, and the monitor had been inoperable since prior to the unit start-up in
9 April of this year. 80

7 8 9 10 11 12 13 18 19 20 21 22 23 24 26 27 28 29 30 31 32 33 34 35 36 37 40 41 42 43 44 47
[0][9] [B][B] (11) [A] (12) [F] (13) [P][I][P][E][X][X] (14) [A] (15) [Z] (16)
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
[17] LER NO REPORT NUMBER [8][2] [] [0][7][8] [] [0][1] [] [] [] []
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
[B] (18) [G] (19) [Z] (20) [Z] (21) [0][0][0][0] [Y] (23) [N] (24) [A] (25) [U][0][8][0] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[1][0] The sample line was capped due to personnel error. Operation with the APD aligned
[1][1] to the capped line resulted in damage to the vacuum relief device. The APD was
[1][2] repaired, and the monitor was returned to an operable status. A Supplemental Report
[1][3] will be submitted upon final resolution of the problems involved.
[1][4] _____ 80

7 8 9 10 11 12 13 14 44 45 46 47 80
[1][5] [D] (28) [0][0][0] (29) [N/A] (30) [A] (31) Operator Observation (32)
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

7 8 9 10 11 12 13 14 44 45 80
[1][6] [Z] (33) [Z] (34) [N/A] (35) [N/A] (36)
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

7 8 9 10 11 12 13 14 80
[1][7] [0][0][0] (37) [Z] (38) [N/A] (39)
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

7 8 9 10 11 12 13 14 80
[1][8] [0][0][0] (40) [N/A] (41)
PERSONNEL INJURIES NUMBER DESCRIPTION

7 8 9 10 11 12 13 14 80
[1][9] [Z] (42) [N/A] (43) 8211300300 821112 PDR ADOCK 05000272 S PDR
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

7 8 9 10 11 12 13 14 80
[2][0] [N] (44) [N/A] (45)
PUBLICITY ISSUED DESCRIPTION