

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 | N E C P R I | 2 | 0 0 0 - 0 0 0 0 0 0 - 0 0 | 3 | 4 1 1 1 1 1 | 4 | _____ | 5
 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

7 8 | 0 1 | REPORT SOURCE | L | 6 | 0 5 0 0 0 2 9 8 | 7 | 1 0 2 5 8 2 | 8 | 1 1 2 2 8 2 | 9
 DOCKET NUMBER 60 61 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During surveillance testing, RHR time delay relay designated 10A-K45A failed to oper-
 0 3 | ate within the required time limits. The redundant system was operable. This occur-
 0 4 | rence presented no adverse potential consequences from the standpoint of public
 0 5 | health and safety. Monthly tests performed on this relay during last two years re-
 0 6 | vealed no abnormal drift of the time delay relay.

7 8	SYSTEM CODE I B 11	CAUSE CODE X 12	CAUSE SUBCODE Z 13	COMPONENT CODE R E L A Y X 14	COMP. SUBCODE H 15	VALVE SUBCODE Z 16
-----	-------------------------	----------------------	-------------------------	------------------------------------	-------------------------	-------------------------

17 LER/RO REPORT NUMBER	EVENT YEAR 8 2 21 22	SEQUENTIAL REPORT NO. 0 2 2 23 24 26	OCCURRENCE CODE / 27	REPORT TYPE L 30	REVISION NO. 0 32
-------------------------	---------------------------	---	---------------------------	-----------------------	------------------------

ACTION TAKEN E 18	FUTURE ACTION E 19	EFFECT ON PLANT Z 20	SHUTDOWN METHOD Z 21	HOURS 0 0 0 0 22 37	ATTACHMENT SUBMITTED N 23	NPRD-4 FORM SUB N 24	PRIME COMP. SUPPLIER N 25	COMPONENT MANUFACTURER G O 8 0 26 44 47
------------------------	-------------------------	---------------------------	---------------------------	--------------------------	--------------------------------	---------------------------	--------------------------------	--

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Time delay relay, GE CR120K, failed to operate in the required time limits of 4.25 to
 1 1 | 5.75 minutes. The delay of the relay was 5.84 minutes. The relay was readjusted and
 1 2 | correct operation verified.

1 5 FACILITY STATUS	% POWER 1 0 0 28 29	OTHER STATUS NA 30	METHOD OF DISCOVERY B 31	DISCOVERY DESCRIPTION Surveillance Testing 32
---------------------	--------------------------	-------------------------	-------------------------------	--

1 6 RELEASER Z 33	CONTENT Z 34	AMOUNT OF ACTIVITY NA 35	LOCATION OF RELEASE NA 36
------------------------	-------------------	-------------------------------	--------------------------------

PERSONNEL EXPOSURES NUMBER 0 0 0 37	TYPE Z 38	DESCRIPTION NA 39
---	----------------	------------------------

PERSONNEL INJURIES NUMBER 0 0 0 40	DESCRIPTION NA 41
--	------------------------

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42	DESCRIPTION NA 43	8211300408 821122 PDR ADOCK 05000298 S PDR
---	------------------------	--

PUBLICITY DATE N 44	DESCRIPTION NA 45	NRC USE ONLY _____ 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
-----------------------------	------------------------	---