LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
	M I D C C 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 6 5 CAT 58
CON'T	SOURCE L 6 0 5 0 0 0 3 1 6 7 1 2 0 9 8 2 3 1 2 2 8 8 2 9
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 DURING A SURVEILLANCE TEST ON THE AUTOMATIC LOAD SEQUENCE TIMING RELAYS, TWO RELAY
031	TIMERS WERE FOUND TO HAVE EXCEEDED THE TOLERANCE ALLOWED BY TECHNICAL SPECIFICATION
0 4	4.8.1.1.2.c.2. THESE ARE ESF TIMERS: CCW PUMP 2E EXCEEDED THE MAXIMUM ALLOWABLE
0 5	TIME BY 0.09 SECONDS AND THE CCW PUMP 2W EXCEEDED THE MAXIMUM ALLOWABLE TIME BY 0.20
0 6	SECONDS. THE PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.
0 7	
7 8 9	
0 9	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
(SEQUENTIAL OCCURRENCE REPORT REVISION CODE TYPE NO.
A	CTION FUTURE EFFECT SHUTDOWN 26 27 28 29 30 31 32
ļ	E 18 X 19 Z 20 Z 21 O O O O N 23 Y 24 N 25 A 1 1 0 9 26
-	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	THE CCW PUMP 2E TIMER OUT OF SPECIFICATION VALUE IS ATTRIBUTED TO INSTRUMENT DRIFT.
1	THE TOGGLE SWITCH ASSEMBLY ON THE CCW PUMP 2W WAS FOUND TO NEED REALIGNMENT. THE
12 1	TIMERS WERE CALIBRATED AND VERIFIED TO OPERATE WITHIN THE ALLOWABLE LIMITS. PRESENTLY
13	AN ENGINEERING REVIEW IS BEING CONDUCTED ON A NEW TYPE OF SOLID STATE RELAY. DEPENDING
114	ON THE RESULTS OF THIS REVIEW, THE EXISITING RELAYS MAY BE REPLACED.
FAC	ATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 SURVEILLANCE TEST
RELE	AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA
1 7 0	PERSONNEL EXPOSURES NUMBER NUMBER 11 12 13 13 NA
1 10	PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA
8 9 LO TY	SS OF OR DAMAGE TO FACILITY 43 PDR ADOCK 05000316 PE DESCRIPTION S PDR ADOCK 05000316 S PDR
8 9	PUBLICITY 60
In N	DESCRIPTION (43) NA NAC USE ONLY
	NAME OF PREPARER R.A. PALMER PHONE 616/465/5901